



**GOVERNMENT OF ANDHRA PRADESH**

\* \* \* \* \*

**Web Site: [www.tender.approcurement.gov.in](http://www.tender.approcurement.gov.in)**

**TENDER DOCUMENT**

**FOR**

**Selection of service provider to execute the repairs for 336 old ambulances in Andhra Pradesh(108 & 104) (e- Procurement)**

**Tender Notice No. : 11.5/APMSIDC/2020-21, Dated:19.10.2020**

**Name of the Work : Selection of service provider to execute the repairs for 336 old ambulances in Andhra Pradesh (108 & 104)**

**Name of the Agency and Address :** .....  
.....  
.....

***Tender Inviting Agency/Implementing Agency:***

**ANDHRA PRADESH MEDICAL SERVICES & INFRASTRUCTURE DEVELOPMENT CORPORATION**

**(Formerly APHMHIDC)**

**(AN ENTERPRISE OF GOVT. OF A.P.)**

**Plot No:09, survey number: 49, IT Park, Mangalagiri, Guntur District- 522503.**

## INDEX

S. No.	DESCRIPTION	
	<b>Introduction</b>	
1	SECTION - I	INVITATION FOR BIDS (IFB)
2	SECTION - II	INSTRUCTIONS TO BIDDERS
3	SECTION - III	GENERAL CONDITIONS OF CONTRACT
4	SECTION - IV	SPECIAL CONDITIONS OF CONTRACT
5	SECTION - V	SCHEDULE OF REQUIREMENTS AND TECHNICAL SPECIFICATIONS
6	SECTION - VI	PRE - QUALIFICATION CRITERIA
7	SECTION - VII (A)	BID FORM
8	SECTION - VII (B)	Model PRICE Schedules (available on e-procurement Platform)
9	SECTION - VIII	BID SECURITY FORM
10	SECTION - IX	CONTRACT FORM
11	SECTION - X	PERFORMANCE SECURITY FORM
12	SECTION - XI	FORMAT B1: PROFORMA FOR PERFORMANCE (for a period of last three years)
		FORMAT B2: CA (STATUTORY AUDITOR) CERTIFICATE
		FORMAT B3: FINANCIAL CAPACITY OF THE BIDDER
14	SECTION - XII	DECLARATION FORM
15	SECTION - XIII	Check List: Documents to be Uploaded as part of the Bid and Notes to Bidders I. Documents with the Technical Bid
16	Annexure – I	WARRANTY CERTIFICATE
17	Annexure - II	GENERAL INFORMATION ABOUT THE TENDERER
18	Annexure – III	THREE MONTH PERFORMANCE CERTIFICATE

## INTRODUCTION

- 1.1. The Andhra Pradesh Medical Services & Infrastructure Development Corporation – APMSIDC (formerly APMHIDC) (Tender Inviting Authority) is a fully owned Government of Andhra Pradesh for providing services to the various health care institutions under the Department of Family Welfare and Health. One of the key objectives of the APMSIDC is to act as the central procurement agency for all essential drugs and equipments for all health care institutions (hereinafter referred to as user institutions) under the department. The corporation has also been entrusted with the setting up and running of all kinds of modern Medical and Paramedical or medical based ancillary facilities such as hospitals, pathological labs, diagnostic centres, x-ray/scanning facilities.
- 1.2. In this tender, the lowest price is not the sole criteria for selecting the supplier. The two-bid system, which is followed, has been designed to eliminate those bids which do not match the technical specifications, or not having the proven technology and to eliminate firms that do not have the financial or technical capability to fabricate vehicles.
- 1.3. It may be noted that the Corporation is not the agency finalizing the requirements of repairs and their specifications. These parameters are finalized by the committee formed by Government of Andhra Pradesh and forwarded to the corporation for procurement. On our side, we ensure that the technical specifications are not biased towards a particular firm, through consultations during the pre-tender meetings with the prospective tenderers. Amendments in the terms and conditions of the tender documents may be resorted to on the basis of expert advice to see that more than one firm qualifies for the final round. Since the repairs is done inside vehicles which mostly cater to the underprivileged of the society, it is our endeavor to ensure that most modern, but proven and durable equipments are procured and supplied. The tender documents are prepared after assessing the market to meet such objectives.
- 1.4. Every Rupee spend by the corporation is public money and hence accountable. Corporation will be dealing with defaulters with a firm hand, which may lead to black listing and recovery of damages. We request our valuable suppliers to avoid such unpleasant situations.
- 1.5. It is also essential while dealing with public money that utmost transparency has to be maintained in the procurements of the corporation. All decisions will be published from time to time on our website [www.msfdc.ap.nic.in](http://www.msfdc.ap.nic.in). The corporation will not wait for the mandatory 30 days period to provide any information under Right to Information Act and will provide the information within the minimum possible time. The Corporation will uphold the fundamental 'right to be heard' enshrined under the Constitution of India and will take harsh decisions only after providing opportunity for hearing/submission of facts.

Tenderers could prefer appeal to the government against all decisions of the corporation.

## SECTION - I: INVITATION FOR BIDS (IFB)

### GOVERNMENT OF ANDHRA PRADESH

#### ANDHRA PRADESH MEDICAL SERVICES & INFRASTRUCTURE DEVELOPMENT CORPORATION (APMSIDC)

\*\*\*\*

#### **Tender Notice No. 11.5/APMSIDC/2020-21, Dated: 19.10.2020**

1. APMSIDC is inviting tenders for selection of service provider to execute the repairs for 336 old ambulances in Andhra Pradesh(108 & 104). The successful bidder(s) would be required to collect these vehicles from the Client site, transfer them to their workshops for repairs and deliver the repairs vehicles to the locations identified by the Client.
2. Bids are invited on the e-procurement platform for Repairs as described in the Section V- Schedule of Requirements from the eligible fabricators. The details of bidding conditions and other terms can be downloaded from the electronic procurement platform of Government of Andhra Pradesh i.e. [www.tender.apecurement.gov.in](http://www.tender.apecurement.gov.in)
3. Bidders would be required to register on the e-Procurement market place “[www.tender.apecurement.gov.in](http://www.tender.apecurement.gov.in)” and submit their bids online. On registration with the e-Procurement market place they will be provided with a user id and password by the system through which they can submit their bids online.
4. The bidders need to scan and upload the required documents as per the Check list given in Section XIII. Such uploaded documents pertaining to technical bid need to be attached to the tender while submitting the bids on line. The attested copies of all these uploaded documents of technical bid, signed undertaking of tenderer should be submitted off line to Managing Director, APMSIDC, Mangalagiri on or before the next day of the last date of submission of bids. The Corporation will consider only the bids submitted through on-line over the copies of the paper-based bids.
5.
  - a) The participating bidder/s will have to pay tender processing fee (non-refundable) for the amounts specified in the Schedule of Requirements (Section –V), in the form of Demand Draft drawn in favour of Managing Director, APMSIDC, Mangalagiri.
  - b) Further the bidder/s shall furnish, as part of it bid, the Bid security for the amounts specified in the Schedule of Requirements (Section –V) to be paid in the form of an unconditional and irrevocable Bank Guarantee issued by any Scheduled Commercial bank in the standard format as shown in the Tender Schedule or a crossed Demand Draft drawn in favour of Managing Director, APMSIDC, Mangalagiri along with bids. The bidders should note that the local MSME units are exempted from payment of E.M.D, subject to the production of necessary documentation to that extent by them.

- c) Further all the participating bidders have to electronically pay a non-refundable transaction fee to M/s. APTS, the service provider through "Payment Gateway Service on E-Procurement platform", as per the Government Orders placed on the e-procurement website.
- d) APMSIDC will not accept the tenders from blacklisted companies or undependable Suppliers whose past performance with APMSIDC was found poor due to delayed and/or erratic supplies and those with frequent product failures, and also against whom there have been adverse reports of **Sub-Standard Quality / Poor Service of** repairs vehicles such as ambulances, Repairs or similar health service vehicles, as defined in the other parts of the Bidding document.

**6. Repairs of Vehicles: 60 days from the issuing of Purchase Order.**

***Time Limits prescribed***

<b>Sl. No</b>	<b>Activity</b>	<b>Time Limit</b>
1	Warranty period	1 Year
2	Frequency of visits to vehicles during Warranty	On call
3	Submission of Performance Security and entering into contract	15 days from the date of issuance of Supply Order
4	Payment Installments	Two Installments and in the ratio 90:10
5	Time for making payments by Purchaser	90% of the invoice amount within 60 days from the date of submission of proper documents
6	Maximum time to attend any Repair call	Within 24 hours

**7. Bidders eligibility and qualifications: Defined at Clause 13 of Instructions to Bidders (Section II) and Qualification Criteria (Section-VI)**

**8. Details of Tender Process:**

1	Downloading of documents	From 21-10-2020 to 28-10-2019 up to 11.00 A.M
2	Queries up to	23-10-2020 at 11.00 A.M
3	Due date for Receipt of tenders	28-10-2020 up to 03.00 P.M
4	Time and date of opening of technical bids	28-10-2020 @ 03.01 PM
5	Time and date of opening of financial bids	28-10-2020 @ 05.00 PM

**Note:** The dates stipulated above are firm and under no circumstances they will be relaxed unless otherwise extended by an official notification or happen to be Public Holidays. For the assistance in the online submission issues, the bidder may contact the help desk of M/s Vupadhi Techno Services Pvt. Ltd. (e-procurement) at their e-mail address: [eprocsupport@vupadhi.com](mailto:eprocsupport@vupadhi.com) or on the mobile nos.: 7337318402, 9959654764, 9347715628, 8919458857, 7416805449, 8919880420 (Due to COVID 19 Lock down support will be through mobile numbers from 9AM to 6:30 PM)

## **9. Procedure for Bid Submission**

- a. The Tenderers/Bidders who are desirous of participating in e-procurement shall submit their Technical bids, price bids etc., in the Standard formats prescribed in the Tender documents, displayed at e-procurement market place.
- b. The bidders shall sign on all the statements, documents, certificates, uploaded by them, owning responsibility for their correctness / authenticity.
- c. No hard copies of the bid are required to be submitted.
- d. The Corporation shall not hold any risk on account of postal delay. Similarly, if any of the certificates, documents, etc., furnished by the tenderer are found to be false / repairs / bogus, the bidder will be disqualified, blacklisted, action will be initiated as deemed fit and the EMD will be forfeited.
- e. The Corporation will not hold any risk and responsibility for the loss in transit during uploading of the scanned document, for the invisibility of the scanned document online, and any other problem(s) encountered by the Tenderers while submitting his bids online.

## **10. Important Instructions to the Bidders:**

- 10.1** Quality of repairs Repairs throughout its life cycle period, timely supplies and prompt maintenance support during the warranty without default are being given paramount importance by the Corporation. The Corporation will be dealing with the defaulters with firm hand, which may lead to blacklisting for a specified period in addition to levying penalties.
- 10.2** In case of complaints on the quality and poor maintenance support of the supplied repairs vehicles, the fabricator/supplier shall rectify the defect free of cost during the Contract Period.
- 10.3** The decision of the Managing Director, APMSIDC, or any officer authorized by him in respect of the quality of the supplied Repairs and other goods etc., shall be final and binding.
- 10.4** No claims shall be allowed against the APMSIDC in respect of interest on Earnest Money Deposit or on Security Deposit or late payments.

**10.5** Savings Clause: No suit, prosecution or any legal proceedings shall lie against APMSIDC or any person for anything, which is done in good faith or intended to be done in pursuance of bid.



## SECTION - II: INSTRUCTIONS TO BIDDERS

### TABLE OF CLAUSES

<b>Clause Number</b>	<b>Topic</b>	<b>Clause Number</b>	<b>Topic</b>
	<b>A. Introduction</b>		<b>D. Submission of Bids</b>
1	Source of funds	18	Sealing & Marking of Bids
2	Eligible Bidders	19	Dead line for submission of Bids
3	Eligible Goods & Services	20	Late Bids
4	Cost of Bidding	21	Modification & Withdrawal of Bids
	<b>B. Bidding Documents</b>		<b>E. Bid Opening &amp; Evaluation</b>
5.	Content of Bidding Document	22	Opening of Bids
6.	Clarification of Bidding Documents	23	Clarification of Bids.
7	Amendment of Bidding Documents	24	Preliminary Examination.
	<b>C. Preparation of Bids</b>	25	Conversion to single currency.
8	Language of Bid	26.	Evaluation & comparison of Bids
9	Documents comprising the Bid	27	Margin of Preference
10	Bid form	28	Contacting the purchaser.
11	Bid prices		
12	Bid currencies		<b>F. Award of contract</b>
13	Documents establishing, Bidders Eligibility & qualifications	29	Post qualification
14	Documents establishing goods, eligibility & conformity to bid documents.	30	Award criteria
15	Bid security	31	Purchasers right to vary quantities at time to award
16	Period of validity of Bids	32	Purchasers right to accept any bid or reject any or all bids.
17	Format & signing of Bid Bids.	33	Notification of award
		34	Signing of contract
		35	Performance security.
		36	Fraud and Corruption

## **A. Introduction**

### **1. Source of funds:**

The funds are made available by the State Government of Andhra Pradesh, towards the procurement processed under this tender notification.

### **2. Eligible Bidder**

This invitation for Bids is open to all Companies who fulfill the eligibility criteria mentioned in the Clause 13 and who meet qualification criteria mentioned in the Section VI.

### **3. Eligible Repairs Vehicles**

All repairs vehicles to be supplied under the contract shall meet the requirements as specified in the Technical Specifications and meet the eligibility criteria as given at Clause 14 of ITB.

### **4. Cost of bidding.**

The Bidder shall bear all costs associated with the preparation and submission of its bid, and the Managing Director, APMSIDC, Mangalagiri here in after referred to as "the purchaser", will in no case be responsible or liable for these costs, regardless of the conduct or outcome of the bidding process.

## **B. The Bidding Documents**

### **5. Content of Bidding Documents**

5.1 In addition to the Invitation for Bids, the bidding documents include:

- (a) Instruction to Bidders;
- (b) General conditions of contract;
- (c) Special conditions of contract;
- (d) Schedule of requirements;
- (e) Technical specifications;
- (f) Bid form and price schedules;
- (g) Bid security form;
- (h) Performance security form.
- (i) Firm Registration/manufacturer license
- (j) Performance statement form.
- (k) Declaration Form
- (l) Check List of the documents uploaded on e-platform as part of the bid

5.2 The bidder is expected to examine all instructions, forms, terms and specifications in the bidding documents. Failure to furnish all information required by the bidding documents or submission of a bid not substantially responsive to the bidding documents in every respect will be at the bidders risk and may result in rejection of its bid.

### **6. Clarification of bidding documents**

A prospective Bidder requiring any clarification of the bidding documents may notify the purchaser in writing at the purchasers mailing address indicated in the Invitation for Bids. The purchaser will respond in writing to any request for clarification of the Bidding documents if the same is received within 4 days of the tender notice prescribed by the purchaser.

## **7. Amendment of bidding documents**

7.1 At any time prior to the deadline for submission of bids, the purchaser may, for any reason, whether at its own initiative or in response to a clarification requested by prospective bidder, modify the bidding documents by amendment.

7.2 The amendment will be notified online.

7.3 In order to afford prospective Bidders reasonable time in which to take the amendment into account in preparing their bid, the purchaser may, at its discretion, extend the deadline for the submission of bids.

## **C. Preparation of Bids**

### **8. Language of Bid.**

The Bid prepared by the Bidder and all correspondence and documents relating to the bid exchanged by the bidder and the purchaser, shall be written in the English language, provided that any printed literature furnished by the Bidder may be written in another language so long as accompanied by an English translation of its pertinent passages in which case, for purposes of interpretation of the bid, the English translation shall govern.

### **9. Documents comprising the bid**

9.1 The bid prepared by the bidder shall comprise the following components:

#### **1. Technical Bid:**

- (a) A Bid form completed in accordance with clause 10
- (b) Documentary evidence established in accordance with clause 13 that the bidder is eligible to bid and is qualified to perform the contract if its bid is accepted.
- (c) Documentary evidence established in accordance with clause 14 that the goods and ancillary services to be supplied by the Bidder are eligible goods and services confirm to the Bidding Documents; and
- (d) Bid security furnished in accordance with clause 15.

#### **2. The Price Bid completed in accordance with clauses 11 and 12.**

## **10. Bid Form**

10.1 The Bidder shall complete the bid form provided in the Bidding documents, indicating the quantity and other declaration statements.

## **11. Bid prices.**

11.1 The Bidder shall indicate on the appropriate price schedule, made available in the e-procurement platform and a model format is also attached to these documents, the unit prices and total bid prices of the goods it proposes to supply under the contract, for each item separately. The unit prices shall be rounded off to nearest Indian rupee.

11.2. Prices indicated on the price schedule shall be entered separately in the following manner:

(i) The price quoted shall be inclusive of all duties and sales and taxes including transportation, installation, commissioning at site and all incidental charges associated with the contract.

11.3 The Bidder's separation of the price components in accordance with para 11.2 above will be solely for the purpose of facilitating the comparison of bids by the purchaser and will not in any way limit the purchaser's right to contract on any of the terms offered.

11.4 Fixed Price: Price quoted by the Bidder shall be fixed during the Bidder's performance of the contract and not subject to variation except for any changes made by the Statute in respect of local taxes. A bid submitted with an adjustable price quotation will be treated as non-responsive and rejected, pursuant to clause 24.

## **12. Bid currencies.**

12.1 Prices shall be quoted in Indian Rupees; Bids quoted other than Indian currency will be rejected.

## **13. Documents Establishing Bidder's Eligibility and Qualifications.**

13.1 Pursuant to clause 9, the bidder shall furnish, as part of its bid, documents establishing the bidder's eligibility to bid and its qualifications to perform the contract if its bid is accepted

13.2 The documentary evidence of the Bidder's eligibility to bid shall establish to the purchaser's satisfaction that the bidder, at the time of submission of the bid, is an eligible bidder as defined under clause 2.

13.3 The documentary evidence of the Bidders qualifications to perform the contract if its bid is accepted, shall establish to the purchaser satisfaction;

- (i) the legal status, place of registration and principle place of business of the company or firm or partnership etc.
- (ii) Details of experience and past performance of the bidder on specified item offered in the bid and on those of similar nature within the past three years

and details of current contracts in hand and other commitments (suggested proforma given in section XI);

- (iii) Copy of the GST Certificate and Details of IT- PAN / TIN copies
- (iv) The details in compliance to the Qualification Criteria (Section VI).

13.4 The check list for the details of documents to be submitted is given at Section XIII

#### **14. Documents Establishing Supplier/Fabricator's Eligibility and conformity to bidding documents.**

14.1 Pursuant to clause 9 the bidder shall furnish, as part of its bid, documents establishing the eligibility and conformity to the bidding document of all services which the bidder proposes to supply under the contract.

14.3 The documentary evidence of the repairs of vehicles conformity to the bidding documents may be in the form of literature, drawings and data, and shall furnish:

- (a) a detailed description of the repairs of essential technical and performance characteristics of the goods.
- (b) A clause by clause commentary on the purchaser technical specifications demonstrating the goods and services substantial responsiveness to those specifications or statement of deviations and exceptions of the Technical specifications.

14.4 For purpose of the commentary to be furnished pursuant to clause 14.3 above, the bidder shall note that standards for workmanship, material and goods, and references to brand names or catalogue numbers designated by the purchaser in its technical specifications are intended to be descriptive only and not restrictive. The bidder may substitute alternative standards, brand name and / or catalogue numbers in its bid, provided that it demonstrates to the purchaser's satisfaction that the substitutes are substantially equivalent or superior to those designated in the Technical specifications.

#### **15. Bid security**

15.1 Pursuant to Clause 9, the Bidder shall furnish, as part of it bid, the Bid security for the amounts specified in the Invitation for Bids (Section -1)

15.2 The bid security is required to protect the purchaser against risk of bidders conduct which would warrant the security forfeiture, pursuant to clause 15.7

15.3 The bid security shall be in Indian Rupees and shall be in one of the following forms:

- (a) A bank guarantee issued by scheduled commercial bank located in India acceptable to the purchaser, in the form provided in the bidding documents or another form acceptable to the purchaser and valid for 45 days beyond the validity of the bid; or
- (b) A Demand Draft/Pay Order in favour of Managing Director, APMSIDC, Mangalagiri payable at Guntur.

- 15.4 Any bid not secured in accordance with para 15.1 and 15.3 above will be rejected by the purchaser as non-responsive pursuant to clause 24.
- 15.5 Unsuccessful Bidder's bid security will be discharged/ returned as promptly as possible but not later than 30 days after the expiration of the period of bid validity prescribed by the purchaser pursuant to clause 16.
- 15.6 The successful Bidder's bid security will be discharged upon the Bidders executing the contract, pursuant to clause 34 and furnishing the performance security pursuant to clause 35.
- 15.7 The bid security may be forfeited;
- (a) If a Bidder withdraws its bid during the period of bid validity specified by the Bidder on the Bid form; or
  - (b) In case of successful Bidder, if the Bidder fails;
    - (i) to sign the contract in accordance with clause 34; or
    - (ii) to furnish performance security in accordance with clause 35.
  - (c) If the Bidder does not accept the corrected amount the Bid will be rejected, and the Bid security may be forfeited.

**16. Period of validity of Bids.**

- 16.1 Bids shall remain valid for 90 days after the date of bid opening prescribed by the purchaser pursuant to Clause 19.1. A bid valid for shorter period may be rejected by the purchaser as non-responsive.
- 16.2 In exceptional circumstances, the Purchaser may solicit the Bidders consent to an extension of the period of validity the request and the responses thereto shall be made in writing (or by mail). The bid security provided under clause 15 shall also be suitably extended. A bidder may refuse the request without forfeiting its bid security.

**17. Format and signing of Bid.**

- 17.1 The bid shall be typed or written in indelible ink and shall be signed by the Bidder or a person or persons duly authorized to bind the bidder to the contract. The latter authorization shall be indicated by written power-of-attorney accompanying the bid. All pages of the bid, except for unammended printed literature, shall be initialed by the person or persons signing the bid.
- 17.2 The bid shall contain no interlineations, erasures or overwriting except as necessary to correct errors and made by the bidder in which case such corrections shall be initialed by the person or persons signing the bid.

## D. Submission of Bids

### **18. Sealing and Marking of bids.**

18.1 The bids shall be uploaded (submitted) electronically, as described in the Invitation for Bids (Section –I).

18.2 The Bids shall be addressed to the purchaser at the following address:

The Managing Director, Plot No:09, survey number: 49, IT Park, Mangalagiri,  
Guntur District- 522503.

### **19. Deadline, for submission of bids.**

19.1 The Bids must be received by the purchaser, no later than the time and date specified in the Invitation for Bids (Section I). In the event of the specified date for the submission of Bids being declared a holiday for the purchaser, the Bids will be received up to the appointed time on the next working day.

19.2 The purchaser may, at its discretion, extend this deadline for submission of bids by amending the bid documents in accordance with clause 7, in which case all rights and obligations of the purchaser and bidders previously subject to the deadline will thereafter be subject to the deadline as extended.

### **20. Late Bids.**

20.1 Any bid received by the purchaser after the deadline for submission of bids prescribed by the purchaser, pursuant to clause 19, will be rejected and/ or returned unopened to the Bidder.

### **21. Modification and Withdrawal of Bids.**

21.1 No bid may be modified subsequent to the deadline for submission of bids.

21.2 No bid may be withdrawn in the interval between the deadline for submission of bids and the expiration of the period of bid validity specified by the Bidder on the Bid form. Withdrawal of bid during this interval may result in the Bidders forfeiture of its bid security, pursuant to Clause 15.7

## E. Bid Opening and Evaluation

### **22. Opening of Bids by Purchaser**

22.1 The Purchaser/or his authorized representative will download the technical bids on **28-10-2020 at 03.01 PM.**

22.2 The Financial Bids of the Technically responsive bidder would be downloaded subsequently from the e-platform, once the technical evaluation is completed.

**23. Clarification of Bids.**

23.1 To assist in the examination, evaluation and comparison of bids the purchaser may at his discretion, ask the Bidder for clarification of his bid. The request for clarification and the response shall be in writing and no change in price or substance of the bid shall be sought, offered or permitted.

**24. Technical Evaluation (Preliminary Examination and Pre-Qualification)**

24.1 The purchaser will examine the bids to determine whether they are complete, whether required securities have been furnished, whether the documents have been properly signed, and whether the bids are generally in order.

24.2 Prior to the financial evaluation, pursuant to clause 26, the purchaser will determine the responsiveness of each bid to the bidding documents. For purposes of these clauses, a responsive bid is one which conforms to all the terms and conditions of the bidding documents without material deviations. The purchaser's determination of bids responsiveness is to be based on the contents of the bid itself without recourse to extrinsic evidence.

24.3 Further the purchaser will determine to his satisfaction whether the Bidder is qualified to satisfactorily perform the contract. The determination will take into account the Bidder's financial, technical and production capabilities. It will be based upon an examination of the documentary evidence of the Bidder's qualifications submitted by the Bidder pursuant to clause 13 as well as such other information as the purchaser deems necessary and appropriate.

24.4 An affirmative determination will be prerequisite for the opening of the financial bids. A negative determination will result in rejection of the Bidder's bid.

24.5 A bid determined as not substantially responsive will be rejected by the purchaser.

24.6 The Purchaser may waive any minor informality or non-conformity or irregularity in a bid which does not constitute a material deviation, provided such a waiver does not prejudice or affect the relative ranking of any bidder.

**25. Deleted.**

**26. Evaluation and comparison of Bids.**

26.1 The Purchaser will evaluate and compare bids previously determined to be substantially responsive, pursuant to clause 24 for each schedule separately.

26.2 The purchasers evaluation of a bid will take into account; in addition to the bid price (Goods offered ), such price to include all costs as well as duties and taxes paid or payable and cost of incidental services required. The following costs to the extent specified:



- a. cost of inland transportation, insurance and other costs within India incidental to the delivery of goods to their final destination;
- b. the availability of spare parts and after-sales services for the repairs including any equipment offered in the bid. To this extent the bidders shall give:
  - An Undertaking Availability/ establishment to ensure uninterrupted after sales service during warranty and maintenance period shall be confirmed.

27. Deleted

**28. Contacting the purchaser.**

28.1 Subject to clause 23, no Bidder shall contact the purchaser on any matter relating to the bid, from the time of the bid opening to the time, the contract is awarded.

28.2 Any effort by a Bidder to influence the Purchaser in the purchaser's bid evaluation, bid comparison or contract award decisions may result in rejection of the Bidders bid.

## **F. Award of Contract**

### **29. Post - Qualification**

Not Applicable

### **30. Award Criteria**

- 30.1 Subject to clause 32, the purchaser will award the contract to the successful Bidder whose bid has been determined to be substantially responsive and has been determined as the lowest evaluated bid, provided further that the Bidder is determined to be qualified to perform the contract satisfactorily. The Client may award all vehicles to the lowest bidder and declare it as the sole Fabricator of Delivery Vans into Medicine cum Vaccine transport Vehicles. However, the Client shall have the right to ask other bidders to match the price quoted by lowest bidder and may distribute the vehicles among the bidders, if they agree to match the quote of the lowest bid. Allocation of number of vehicles to each bidder shall be made based on the repairs capacity of the Bidder and discretion of the Client. However, each fabricator shall be awarded with minimum of 3 lots each, wherein each lot comprises of 30 vehicles.

### **31. Purchaser's right to vary quantities at Time of Award**

- 31.1 The purchaser reserves the right, at the time of award of contract to increase or decrease to any extent of the quantity of goods and services specified in the schedule of requirements without any change in price or other terms and conditions.

### **32. Purchaser's right to accept any Bid and to reject any or all Bids.**

- 32.1 The purchaser reserves the right to accept or reject any bid and to annul the bidding process and reject all bids at any time prior to award of contract, without there by incurring any liabilities to the affected Bidder or Bidders or any obligation to inform the affected Bidder or Bidders of the grounds for the Purchaser's action.

### **33. Notification of Award.**

- 33.1 Prior to the expiry of the period of the bid validity, the purchaser will notify the successful Bidder in writing by registered letter or cable or telex, duly confirming that the bid has been accepted.
- 33.2 The notification of award will constitute the formation of the contract.
- 33.3 Upon the successful Bidder's furnishing of performance security, pursuant to clause 34, the purchaser will promptly notify each unsuccessful Bidder and will discharge their bid security, pursuant to clause 15.

### **34. Signing of contract**

- 34.1. Within 15 days of receipt of the notification of award the successful Bidder shall sign the contract.

### **35. Performance security**

- 35.1 Within 15 days of the receipt of notification of award from the purchaser, the successful Bidder shall furnish the performance security in accordance with the conditions of contract, in the performance security form provided in the Bidding documents or another form acceptable to the purchaser and signs the agreement.
- 35.2 Failure of the successful Bidder to comply with the requirement of clause 34 shall constitute sufficient grounds for the annulment of the award and forfeiture of the bid security, in which event the purchaser may make the award to the next lowest evaluated bidder or call for new bids.

### **36 Fraud and corruption**

- 36.1** It is the **purchaser's** policy that requires that the bidders, suppliers and contractors and their subcontractor observe the highest standard of ethics during the procurement and execution of such contracts. In pursuance of this policy, the **purchaser**;

(a) defines, for the purposes of this provision, the terms set forth below as follows:

(i) **“corrupt practice”** is the offering, giving, receiving or soliciting, directly or indirectly, of anything of value to influence improperly the actions of another party;

(ii) **“fraudulent practice”** is any act or omission, including a misrepresentation, that knowingly or recklessly misleads, or attempts to mislead, a party to obtain a financial or other benefit or to avoid an obligation;

(iii) **“collusive practice”** is an arrangement between two or more parties designed to achieve an improper purpose, including to influence improperly the actions of another party;

(iv) **“coercive practice”** is impairing or harming, or threatening to impair or harm, directly or indirectly, any party or the property of the party to influence improperly the actions of a party;

(v) **“obstructive practice”** is

(aa) deliberately destroying, falsifying, altering or concealing of evidence material to the investigation or making false statements to investigators in order to materially impede a investigation into allegations of a corrupt, fraudulent, coercive or collusive practice; and/or threatening, harassing or intimidating any party to prevent it from disclosing its knowledge of matters relevant to the investigation or from pursuing the investigation; or

(bb) acts intended to materially impede the exercise of the purchaser's inspection and audit rights provided for under sub-clause 36.2 (d) below.

36.2 The purchaser may, without prejudice to other terms of the bidding:

(a) will reject a proposal for award if it determines that the bidder considered for Award has, directly or through an agent, engaged in corrupt, fraudulent, collusive, coercive or obstructive practices in competing for the contract in question;

(b) will cancel the contract if the purchaser determines at any time that the bidder, supplier and contractors and their sub contractors engaged in corrupt, fraudulent, collusive, or coercive practices.

(c) will sanction a firm or individual, including declaring ineligible, either indefinitely or for a stated period of time, to be awarded a contract if it at any time determines that the firm has, directly or through an agent, engaged in corrupt, fraudulent, collusive, coercive or obstructive practices in competing for, or in executing, a contract; and

(d) will have the right to inspect the accounts and records of the bidders, supplier, and contractors and their subcontractors and to have them audited by auditors appointed by the Purchaser.

## **SECTION - III: GENERAL CONDITIONS OF CONTRACT**

### **TABLE OF CLAUSES**

<b><u>Clause Number</u></b>	<b><u>Topic</u></b>
1.	Definitions
2.	Application
3.	Country of Origin
4.	Standards
5.	Use of Contract Documents and Information
6.	Patent Rights
7.	Performance Security
8.	Inspection and Tests
9.	Packing.
10.	Delivery and Documents
11.	Insurance
12.	Transportation
13.	Incidental services
14.	Spare Parts
15.	Warranty
16.	Payment
17.	Prices
18.	Change Orders
19.	Contract Amendments
20.	Assignment
21.	Subcontracts
22.	Delays in suppliers Performance
23.	Liquidated Damages
24.	Termination for Default
25.	Force Majeure
26.	Termination for Insolvency
27.	Termination for convenience
28.	Resolution of Disputes
29.	Governing Languages
30.	Applicable Law.
31.	Notices
32.	Taxes and Duties.

## **Section III: General Conditions Of Contract**

### **1. Definitions**

1.1 In this contract, the following terms shall be interpreted as indicated;

- (a) "The contract" means the agreement entered into between the purchaser and the supplier, as recorded in the contract form signed by the parties, including all the attachments and appendices thereto and all documents incorporated by references therein.
- (b) " The contract Price" means the price payable to the supplier under the contract for the full and proper performance of its contractual obligations.
- (c) " The Goods" means all the Repairs repairs along with equipment as per Section V which the supplier is required to supply to the purchaser under the contract.
- (d) "Services " means services ancillary to the supply of the goods, such as transportation, insurance and any other incidental services, such as installation, commissioning, provision of technical assistance, training and other obligations of the supplier covered under the contract.
- (e) "An undependable Supplier/s' under contract means any Supplier who do not accept the purchase order or who delays the supply of required quantities beyond the permitted delays with liquidated damages
- (f) "The Purchaser or Corporation" means the APMSIDC, the purchasing agency or any other agency authorized by the APMSIDC
- (g) "The Supplier" means the individual or firm supplying the goods under this contract.
- (h) "The Government" means the Government of Andhra Pradesh or its authorized representatives
- (i) "The Project Site", where applicable means the place or places named in Schedule of Requirements
- (j) "The End-User" means the authorized user of the Repairs
- (k) "Day" means calendar day
- (l) "Delivery period" means the period applicable up to completion of supply.

### **2. Application**

2.1. These General conditions shall apply to the extent that they are not superseded by provisions in other parts of the contract.

### **3. Country of Origin: Deleted.**

#### **4. Standards**

- 4.1 The Goods supplied under this contract shall conform to the standards mentioned in the Technical specifications and when no applicable standard is mentioned the authoritative standard appropriate to the goods country of origin shall be followed and such standard shall be the latest issued by the concerned institution.

#### **5. Use of contract documents and Information**

- 5.1 The supplier shall not without the purchaser's prior written consent, disclose the contract or any provision thereof or any specification, plan, drawing, pattern, sample or information furnished by or on behalf of the purchaser in connection therewith to any person other than a person employed by the supplier in performance of the contract. Disclosure to any such employed person shall be made in confidence and shall extend only so far as may be necessary for purposes of such performance.
- 5.2 The supplier shall not, without the purchasers prior written consent make use of any document or information enumerated in para 5.1 except for purposes of performing the contract.
- 5.3 Any document other than the contract itself enumerated in para 5.1 shall remain the property of the purchaser and shall be returned (in all copies) to the purchaser on completion of the suppliers performance under the contract if so required by the purchaser.

#### **6. Patent Rights**

- 6.1 The supplier shall indemnify the purchaser against all third party claims of infringement of patent, trademark for industrial design rights arising from use of the goods or any part thereof in India..

#### **7. Performance Security**

- 7.1 Within 15 days after the supplier's receipt of notification of award of the contract, the supplier shall furnish performance security of 5% of contract value to the purchaser for the amount specified in the special conditions of contract.
- 7.2 The proceeds of the performance security shall be payable to the purchaser as compensation for any loss resulting from the supplier's failure to complete its obligations under the contract
- 7.3 The performance security shall be denominated in Indian Rupees and shall be in the form of a Crossed Demand Draft in favour of Managing Director, APMSIDC, Mangalagiri.
- 7.4 Performance security will be discharged by the *Purchaser* and returned to the supplier after the end of contract period i.e. following the date of completion of the supplier's performance obligations, including any warranty obligations.

## **8. Inspections and Tests.**

- 8.1 The purchaser or his representatives shall have the right to inspect and / or to test the Goods to confirm their conformity to the contract. The special conditions of contract and / or the Technical specifications shall specify what inspections and tests the purchaser requires and where they are to be conducted. The purchaser shall notify the supplier in writing of the identity of any representatives retained for these purposes.
- 8.2 The inspections and tests may be conducted in the premises of the supplier or its subcontractor(s) at point of delivery and/or at the goods final destination. Where conducted on the premises of the supplier or its subcontractor(s) all reasonable facilities and assistance including access to drawings and production data shall be furnished to the inspectors at no charge to the purchaser.
- 8.3 Should any inspected or tested goods fail to conform to the specifications the purchaser may reject them and the supplier shall either replace the rejected goods or make alternatives necessary to meet specifications, requirements free of cost to the purchaser.
- 8.4 The purchasers right to inspect test and where necessary reject the goods after the goods arrival at site and shall in no way be limited or waived by reason of the goods having previously been inspected, tested and passed by the purchaser or its representative prior to the goods shipment from the country of origin.
- 8.5 Nothing in clause 8 shall in any way release the supplier from any warranty or other obligations under this contract.

## **9. Packing**

- 9.1 The supplier shall provide such packing of the goods as is required to prevent their damage or deterioration during transit to their final destination as indicated in the contract. The packing shall be sufficient to withstand, without limitation, rough handling during transit and exposure to extreme temperatures, salt and precipitation during transit and open storage. Packing case size and weights shall take into consideration where appropriated the remoteness of the Goods final destination and the absence of heavy handling facilities at all points in transit.
- 9.2 The packing, marking and documentation within and outside the packages shall comply strictly with such special requirements, as shall be provided for in the contract and subject to clause 18 and any subsequent instructions ordered by the purchaser.

## **10. Delivery and Documents**



10.1 Delivery of the Goods shall be made by the supplier in accordance with the terms specified by the purchaser in the Notification of Award.

**11. Insurance**

11.1 The goods supplied under the contract shall be fully insured in Indian Rupees against the loss or damage incidental to manufacture or acquisition, transportation, storage and delivery in the manner specified in the special conditions of contract.

**12. Transportation**

12.1 The supplier is required to deliver the goods to the destinations specified in the contract and the cost thereof shall be included in the contract price.

12.2 The transportation of the Goods after the delivery at the final destination shall be the responsibility of the Purchaser.

**13. Incidental services.**

13.1 The supplier is required to provide the following services, including additional services, if any, specified in SCC:

(a) Performance of the on-site assembly and start-up of the supplied Goods;

(b) Furnishing of tools required for assembly and maintenance of the supplied Goods;

(a) Furnishing of detailed operations and maintenance manual for each appropriate unit of supplied Goods;

(b) Performance of maintenance and repair of the supplied Goods, for a period of 1 year, provided that this service shall not relieve the Supplier of any warranty obligations under this Contract; and

(e) Training of the users and maintenance personnel, in operation, maintenance and repair of the supplied Goods.

13.2 Prices charged by the Supplier for incidental services, if not included in the contract price of the Goods, shall be agreed upon in advance by the parties and shall not exceed the prevailing rates charged to other parties by the Supplier for similar services.

**14. Spare Parts:**

14.1 As specified in the special conditions of contract, the supplier may be required to provide the following materials and notifications pertaining to spare parts manufacturer:

- (a) Such of spare parts as the purchaser may select to purchase from the supplier providing that this selection shall not relieve the supplier of any warranty obligations under the contract and
- (b) In the event of termination of production of the spare parts;
  - (i) advance notification to the purchaser of the pending terminating in sufficient time to permit the purchaser to procure needed requirements : and
  - (ii) following such termination, furnishing at no cost to the purchaser, the blueprints, drawing and specifications of the spare parts, if and when requested.

## **15. Warranty**

- 15.1 The Supplier warrants that all the Goods are new, unused, and of the most recent or current models, and that they incorporate all recent improvements in design and materials, unless provided otherwise in the Contract. The supplier further warrants that the goods supplied under this contract shall have no defect arising from design materials or workmanship (except insofar as the design or material is required by the purchasers specifications) or from any act or omission the supplied goods in conditions obtaining in the country of final destination.
- 15.2 This warranty shall remain valid for 12 months.
- 15.3 The purchaser shall promptly notify the supplier in writing of any claims arising under this warranty.
- 15.4 Upon receipt of such notice, the supplier shall, with all reasonable speed, repair or replace the defective goods or parts thereof without cost to the purchaser other than, where applicable, the cost of inland delivery of the repaired or replaced goods or parts from the port of entry to the final destination.
- 15.5 If the supplier, having been notified, fails to remedy the defect (s) within a reasonable period, the purchaser may proceed to take such remedial action as may be necessary, at the suppliers risk and expenses and without prejudices to any other right which the purchaser may have against the supplier under the contract.
- 15.6 A warranty certificate (as per format in Annexure I) duly signed and with proper stamp of the institution concerned and also signed by the authorized signatory with the stamp of the successful tenderer shall be submitted to the Tender Inviting Authority for keeping it under safe custody along with the Installation Certificate. A copy of the original warranty papers has to be given to the Purchaser.

## **16. Payment**

- 16.1 The method and conditions of payment to be made to supplier under the contract shall be specified in the special conditions
- 16.2 The Suppliers request (s) for payment shall be made to the purchaser in writing accompanied by an invoice describing as appropriate the goods delivered and the services performed and by shipping document, submitted pursuant to clause 10, and upon fulfillment of other obligations stipulated in the contract.
- 16.3 Payments shall be made by the purchaser within sixty (60) days of submission of the invoices / claims by the supplier duly furnishing the certificate specified in the bid document from the competent authority.
- 16.4 Payment shall be made in Indian Rupees.

## **17. Prices**

- 17.1 Prices charged by the supplier for goods delivered and services performed under the contract shall not except for any price adjustments authorized by the special conditions of contract, vary from the prices quoted by the supplier in its bid.

## **18. Change Orders**

- 18.1 The Purchaser may at any time by written orders given to the supplier pursuant to clause 31, make changes within the general scope of the contract in any one or more of the following;
  - (a) drawings, designs or specifications, where goods to be furnishing under the contract are to be specifically manufactured for the purchaser;
  - (b) the method of shipping or packing;
  - (c) the place of delivery; or
  - (d) the services to be provided by the supplier;
- 18.2 If any such changes causes an increase or decrease in the cost of or the time required for the suppliers performance of any part of the work under the contract, whether changed or not changed by the order, an equitable adjustment shall be made in the contract price or delivery schedule or both and the contract shall accordingly be amended. Any claims by the supplier for adjustment under this clause must be asserted within thirty (30) days from the date of the suppliers receipt of the purchasers change order.

## **19. Contract Amendments**

- 19.1 Subject to clause 18, no variation in an modification of the terms of the contract shall be made except by written amendment signed by the parties .

## **20. Assignment**

19.2 The supplier shall not assign in whole or in part, its obligations to perform under the contract, except with the purchasers prior written consent.

## **21. Sub-contracts**

21.1 The supplier shall notify the purchaser in writing of all subcontracts awarded under the contract if not already specified in his bid. Such notification, in his original bid or later, shall not relieve the supplier from any liability or obligation under the contract.

## **22. Delays in the suppliers performance**

22.1 Delivery of the goods and performance of the services shall be made by the supplier in accordance with the time schedule specified by the purchaser in its schedule of requirements.

22.2 Any unexcused delay by the supplier in the performance of its delivery obligations shall render the supplier liable for any or all of the following; i.e. forfeiture of its performance security, imposition of liquidation damages and or termination of the contract for default.

22.3 If at any time during the performance of the contract, the supplier or its subcontractor (s) should encounter performance of the services the supplier shall promptly notify the purchaser in writing of the fact of the delay its likely duration and its causes. As soon as practicable after receipt of the suppliers notice, the purchaser shall evaluate the situation and may at its discretion extend the suppliers time for performance, in which case the extension shall be ratified by the parties by amendment of the contract.

## **23. Liquidated Damages**

23.1 Subject to clause 25, if the supplier fails to deliver any or all of the goods within the time period specified in the contract, the purchaser shall, without prejudice to its other remedies under the contract, deduct from the contract price as liquidated damages, an amount as specified in the SCC for the period of delay, until actual delivery or performance, up to a maximum deduction of 10 percent of the delayed goods or services contract price. Once the maximum is reached, the purchaser may consider termination of the contract.

## **24. Termination for Default**

24.1 The purchaser may, without prejudice to any other remedy for breach of contract by written notice of default sent to the supplier, terminate the contract in whole or part:

- (a) if the supplier fails to deliver any or all of the goods within the time periods specified in the contract or any extension thereof granted by the purchaser pursuant to clause 22; or
- (b) if the supplier fails to perform any other obligations under the contract.

24.2 In the event the purchaser terminates the contract in whole or in part, 24.1 the purchaser may procure, upon such terms and in such manner as it deems appropriate, Goods similar to those undelivered, and the supplier shall be liable to the purchaser for any excess costs for such similar Goods. However, the supplier shall continue the performance of the contract to the extent not terminated.

## **25. Force Majeure**

25.1 Notwithstanding the provisions of clauses 22,23,24, the supplier shall not be liable for forfeiture of its performance security liquidated damages or termination or default, if and to the extent that, its delay in performance or other failure to perform its obligations under the contract is the result of an event of Force Majeure.

25.2 For purposes of this clause " Force Majeure" means an event beyond the control of the supplier and not involving the suppliers fault or negligence and not foreseeable. Such events may include but are not limited to, acts of the purchaser either in its sovereign or contractual capacity, wars or revolutions, floods, epidemics, quarantine restrictions and freight embargoes.

25.3 If a force majeure situation arises, the supplier shall promptly notify the purchaser in writing of such conditions and the cause thereof. Unless otherwise directed by the purchaser in writing the supplier shall continue to perform its obligations under the contract as far as is reasonably practical and shall seek all reasonable alternative means for performance not prevented by the force majeure event.

## **26. Termination for Insolvency.**

26.1 The purchaser may at any time terminate the contract by giving written notice to the supplier, if the supplier becomes bankrupt or otherwise insolvent , provided that such termination will not prejudice or affect any right of action or remedy which has accrued or will accrue thereafter to the purchaser.

## **27. Termination for convenience.**

27.1 The purchaser, may by written notice sent to the supplier terminate the contract, in whole or in part at any time for its convenience. The notice of termination shall specify that termination is for the purchasers convenience the extent to which performance of work under the contract is terminated and the date upon which such termination becomes effective.

27.2 The goods that are complete and ready for shipment within 30 days after the suppliers receipt for notice of termination shall be purchased by the purchaser and the contract terms and prices. For the remaining goods the purchaser may elect.

- (a) to have completed and delivered at the contract terms and prices; and / or
- (b) to cancel the remainder and pay to the supplier and agreed amount for partially completed goods and for materials and parts previously procured by the supplier.

## **28. Resolution of Disputes**

- 28.1 The purchaser and the supplier shall make every effort to resolve amicably by direct informal negotiation any disagreement or dispute arising between them under or in connection with the contract.
- 28.2 If after thirty (30) days from the commencement of such informal negotiations the purchaser and the supplier have been unable to resolve amicably contract dispute, either party may require that the dispute be referred for resolution to the formal mechanisms specified in the special conditions of contract. These mechanisms may include but are not limited to conciliation, mediation by third party justification in an agreed national or international forum and / or international arbitration. The mechanism shall be specified in the special conditions of contract.

## **29. Governing Language**

- 29.1 The contract shall be written in English language, as specified by the purchaser in the instructions to bidders. Subject to clause 30, English language version of the contract shall govern

## **30. Applicable law**

- 30.1 The contract shall be interpreted in accordance with the laws of the union of India and the legal jurisdiction is Vijayawada.

## **31. Notices**

- 31.1 Any notices given by one party to the other pursuant to the contract shall be sent in writing and confirmed in writing to the address specified for that purpose in the special conditions of the contract. A notice shall be effective when delivered or on the notices effective date, whichever is later.

## **32. Taxes and duties**

- 32.1 The rates quoted by the bidder shall be deemed to be inclusive of the sales and other taxes that the bidder will have to pay for the performance of this contract, at the prevailing rates notified by the Government. The purchaser will perform such duties in regard to the deduction of such taxes at source as per applicable law.

## **SECTION - IV: SPECIAL CONDITIONS OF CONTRACT**

### **TABLE OF CLAUSES**

(The corresponding clause number of the General condition is in parenthesis)

<b><u>Item. No.</u></b>	<b><u>Topic.</u></b>
2.	Definitions (Clause - 1)
3.	Country of Origin (Clause -3)
4.	Performance security ( Clause 7)
5.	Inspection and Tests (Clause 8)
6.	Packing (Clause-9)
7.	Delivery and Documents (Clause 10)
8.	Insurance (Clause 11)
9.	Incidental services ( Clauses 13)
10.	Spare Parts (Clause 14)
11.	Warranty (Clause 15)
12.	Payment (Clause 16)
13.	Prices (Clause 17)
14.	sub-contracts (Clause 21)
15.	Liquidated Damages (Clauses 23)
16.	Resolution of Disputes (Clauses 28)
17.	Notices (Clauses 31)
18.	Comprehensive Maintenance Contract
19.	Actions against Misconduct of the Supplier
20.	Progress of Supplies

## Section IV: Special Conditions of the Contract

1. The following special conditions of contract shall supplement the general Conditions of contract. Whenever there is conflict, the provisions herein shall prevail over those of the general conditions of contract the corresponding clause number of the general conditions in parentheses.

### 2. Definitions (Clause I)

(a) The Purchaser is: The Managing Director, APMSIDC, Mangalagiri or any other authorized representative notified by the Purchaser.

(b) The Supplier is: -----

**3. Country of origin (Clause 3):** All goods and related services to be supplied under the contract / agreement shall have their origin in India or any other country with which India has not banned trade relations.

### 4. Performance security (Clause 7)

4.1 Performance security is 5% of the contract value and shall be valid up to 60 days after the date of completion of performance obligations including warrant obligations and maintenance obligations, as applicable.

4.2 Add clause 7.5 to the GCC as the following:

In the event of any contract amendment, the supplier shall within 7 days of receipt of such amendment furnish the amendment to the performance security rendering the same valid for the duration of the contract, as amended for further period of 60 days thereafter

### 5. Inspection and Tests (clause 8)

The following inspection procedures and tests are required by the Purchaser:

5.1 The Supplier shall get each repairs inspected by a competent authority in manufacturer's works, get shower tested in presence of purchaser or its representative and also provide a guarantee/warranty certificate that the instrument conforms to all specifications contained in the contract.

5.2 The *Purchaser* or its representative may inspect and/or test any or all the reappears to confirm their conformity to the Contract specifications, prior to dispatch from the manufacturer's premises. Such inspection and clearance will not prejudice the right of the Purchaser to inspect and test the Repairs on receipt at destination.

5.3 However, on arrival of the repairs, the purchaser or its representative shall have the right to inspect and/or test any or all the repairs to confirm their conformity to the contract.



5.4 The Purchaser may also get the tests such as shower tests conducted at the destination mentioned by Purchaser and not necessarily at the supplier's place.

5.5 If the performance of repairs and equipment provided by Supplier in Repairs is not as per specified conditions, or if there is any deficiency, then the Supplier shall repair or replace the component to the satisfaction of the purchaser's representative.

## **6. Packing (Clause 9)**

The Supplier will be required to pack the goods installed/placed inside the Repairs if required during transportation with following markings:

- i. Name of the contract, ii. Contract No., iii. Country of origin of Goods, iv. Supplier's Name and v. Packing of list reference number

## **7. Delivery and Documents (Clause 10)**

- (i) Three copies of the Supplier invoice showing Goods description, quantity, unit price, total amount;
- (ii) Railway receipt/acknowledgement of receipt of goods from the Purchaser
- (iii) Manufacture's/Supplier's Warranty and Factory Test certificate as applicable;
- (iv) Acceptance Certificate issued by the Purchaser
- (v) Inspection Certificate issued by the nominated inspection agency, as applicable

## **8. Deleted**

## **9. Incidental Services (Clause 13)**

No additional services are required to be provided over the services already covered under clause 13 of GCC.

## **10. Spare parts: (Clause 14)**

Add as clause 14.2 to the GCC the following:

During the warranty period, Supplier shall carry sufficient inventories to assure ex stock supply of consumables spares such as gaskets, plugs, washers, belts etc., other spare parts and components shall be promptly as possible but in any case within (3) days of placement of order.

## **11. Warranty (Clause 15)**

11.1 In partial modification of the provisions, the warranty period shall be 12 months, after the Goods, or any portion thereof, as the case may be, have been delivered

at site, installed, commissioned, successfully tested and accepted by the Purchaser or its authorized representative.

11.2 Substitute Clause 15.4 of the GCC with the following:

Upon receipt of such notice, the Supplier shall within 3 days, repair or replace the defective goods or parts thereof, free of cost at the ultimate destination. The Supplier shall take over the replaced parts/goods at the time of their replacement.

11.3 If the supplier has not done repair/replacement within the time specified above the purchaser will assess the cost of having the repairs/replacements done and the supplier will pay this amount.

11.4 All software updates, if any required, should be provided free of cost during Warranty period.

**12. Payment (Clause 16)**

12.1 Payments for the supply of vehicles shall be made in Indian Rupees, as and when delivered. 90% of the contract value after preliminary inspection tests such as shower test & any other tests will be paid to the supplier on submission of copy of invoice with original Delivery Challan as proof of supply to destinations, duly certified by the Client. Remaining 10% will be paid after three months from the date of installation on submission of performance satisfactory report (Annexure-III), obtained from the Purchaser or its authorized authorities.

**13. Prices (Clause 17)**

Prices payable to the Supplier as stated in the Contract shall not be subject to adjustment during performance of the Contract.

**14. Sub-contracts (Clause 21)**

Add at the end of sub-clause 21.1 of the GCC the following. "Sub-contract shall be only for bought-out items and sub-assemblies".

**15. Liquidated Damages (Clause 23)**

**15.1 For delays**

Substitute Clause 23.1 of the GCC by the following:

Subject to clause 25 of GCC, the Purchaser shall, without prejudice to its other remedies under the Contract, deduct from the Contract Price, as liquidated damages, a sum equivalent to 0.5 percent of the delivered price of the delayed Goods for each week of delay or part thereof until actual delivery, up to a maximum deduction of 10% of the contract price. Once the maximum deduction is reached, the Purchaser may consider termination of the Contract.

## 15.2 For Short fall in repairs/Maintenance services

Any major repair intimated by the *Purchaser* shall be rectified by the Supplier from the date of intimation within a period of 24 hours related to repairs to the satisfaction of the Purchaser. Failing which the Purchaser has a right to levy a penalty on the Supplier a sum of Rs.1,000/- per day of delay, until the defect is repaired and brought to the normal working condition to the satisfaction of the Purchaser.

## 16. Resolution of Disputes (Clause 28)

Add as Clauses 28.3 and 28.4 of the GCC the following:

28.3 The dispute resolution mechanism to be applied pursuant to clause 28 of the General Conditions shall be as follows:

- (a) In the case of dispute or difference arising between the Purchaser and a Domestic Supplier relating to any matter arising out of or connected with this agreement, such dispute or difference shall be referred to the award of two Arbitrators, one Arbitrator to be nominated by the Purchaser and the other to be nominated by the Supplier or in the case of the said Arbitrators not agreeing, then at the award of an Umpire to be appointed by the Arbitrators in writing before proceeding with the reference, and in case the Arbitrators cannot agree to the Umpire, he may be nominated by the Arbitration committee of the Indian Council of Arbitration, India. The award of the Arbitrators, and in the event of their not agreeing, of the Umpire appointed by them or by the Arbitration Council of India, India, shall be final and binding on the parties.
- (b) The amended Indian Arbitration and Conciliation Act 2015 the rules thereunder and any statutory modification or re-enactments thereof, shall apply to the arbitration proceedings.

28.4 The venue of arbitration shall be the place from where the Contract is issued.

## 17. Notices (Clause 31)

For the purpose of all notices, the following shall be the address of the purchaser and supplier.

Purchaser: The Managing Director, Plot No:09, survey number: 49, IT Park, Mangalagiri, Guntur District- 522503.

Supplier: (To be filled in at the time of Contract Signature)

## 18. Warranty Period

Supplier shall provide a minimum of one-year warranty.

## 19. **Actions Against the Misconduct of the Supplier**

- .1 A Supplier found being supplied similar items with similar tender conditions to any other agency in the country during the validity of the contract with the APMSIDC, at a rate lower than the rate at which they supplied under this tender, the difference amount is liable to be recovered apart from blacklisting the firm for a minimum period of 3 years. The Supplier should furnish undertaking (Section-XIII) that they will remit the differential cost, if they quote lower rate than the rate quoted to the APMSIDC to any other agency or department or state, during the period of contract
- .2 Any substandard supplies without meeting the quality specifications made under the contract shall also entail blacklisting of the firm for a minimum period of three years for that particular product.
- .3 If the bidder fails to demonstrate on asked to do so, of the products quoted with their bid, without any valid or convincing reason to the satisfaction of the Purchaser, the bids for other items offered against the bid notice will not be considered and he may be debarred for a certain period as decided by the Purchaser.

## 20. **Progress of Supply**

Supplier shall intimate progress of supply, in writing, to the Purchaser as under :

- Qty offered for inspection and date;
- Qty. accepted/rejected by inspecting agency and date;
- Qty. dispatched/delivered to Purchaser and date;
- Qty. where incidental services have been satisfactorily completed with date;
- Quantity where rectification/repair/replacement effected/completed, on receipt of any communication from consignee/Purchaser with date;
- Date of completion of entire Contract including incidental services, if any; and
- Date of receipt of entire payments under the Contract.

**SECTION V**

**SCHEDULE OF REQUIREMENTS AND TECHNICAL SPECIFICATIONS**

<b>S. No.</b>	<b>Item name</b>	<b>No. of Ambulances</b>	<b>EMD in INR</b>	<b>Average annual turnover of the Manufacturer/Bidder the last three years i.e. 2017-18, 2018-19, 2019-20 in INR</b>
1	Price for repair of 336 ambulances (As per annexure – I & II)	336*	10,00,000	20,00,00,000

**\* 336 – 249 are Tata Winger 2.2 dicor & 87 are Force Traveller 3350**

**Processing fee:** The participating bidders will have to pay tender processing fee (non-refundable) of Rs. **11,800/-** in the form of Demand Draft drawn in favour of Managing Director, APMSIDC, Mangalagiri.

## **Technical Specifications**

### **General Information**

1. Bidders are requested to offer the repairs as per the list attached.
2. All the spares, oils and tyres should be standard make/OEM.

**Specification for Tyres:**

1. TATA Winger Tyre with tube size: 195 R 15.
2. Force Traveler Tyre with tube size: 215/75 R 15

**A. Specification for Battery**

1. Automotive battery, capacity 80 AH, 12 volts with standard warranty

**B. Vehicles Model:**

1. Force Traveler: Model Force 3350 (ambulance)
2. Tata Winger Model: TATA Winger 2.2 Dicor (ambulance)

## **SECTION – VI**

### **PRE - QUALIFICATION CRITERIA**

**(Referred to in clause 13.3 of ITB)**

#### **Qualification criteria:**

1. The bidder should be a partnership firm/Proprietorship
2. Should have registered office in AP. Tender should have won workshop and should have experience in running workshop for more than 3 years
3. Turnover for the last three financial years FY 17-18, FY 18-19, FY 19-20 should be minimum of 20 Crores.
4. Minimum of five years experience in repairs and maintenance of vehicles, preferably TAT Wingers and Force Traveler.
5. Should have GST
6. Should have PAN card

#### **II. Terms of Disqualification:**

1. The Bidders who has withdrawn their bids in any of the previous tenders of APMSIDC
2. A bidder who is placed on the black-list by either APMSIDC or by any other State / Central government's department or organization in the last 3 years. The bidder should not be currently blacklisted from the above mentioned organizations.
3. The bidder who has been declared as 'undependable supplier' for two (2) instances in the last one year by the APMSIDC
4. The bidders against whom there have been reports of substandard Repairs Repairs and/ or service are liable for disqualification
5. The following shall be reason for rejection for repairs Repairs:

(General appearance of the vehicle shall not show any evidence of poor workmanship)

- a. Rough, sharp or unfinished edges, burrs, seam, sharp corners, joints, cracks, and dents.
- b. Non-uniform panels. Edges that are not filleted, beveled, etc.



- c. Paint runs sags, orange peel, "fish eyes", etc. and any other Imperfection or lack of complete coverage.
- d. Body panels that are uneven, unsealed, or have voids.
- e. Misalignment of body fasteners, glass, viewing panels, light housings, other items with large or uneven gaps, spacing etc. such as door, body panels, and hinged panels.
- f. Improper body design or interface with the chassis that could cause injury during normal use or maintenance.
- g. Improperly repairs and routed wiring or harnesses.
- h. Improperly supported or secured hoses, wires, wiring harnesses, mechanical controls.
- i. Loose, vibrating, abrading body parts, components, subassemblies, hoses, wiring harnesses or trim.
- j. Interference with chassis components, body parts, doors, etc.
- k. Leaks of any gas or fluid lines, (AC, coolant, oil, oxygen, etc.)
- l. Abnormal Noise, panel vibrations, etc.
- m. Sagging, non-form fitting upholstery or padding.
- n. Incomplete or incorrect application of rust proofing.
- o. Inappropriate or incorrect use of hardware, fasteners, components, or methods of construction.
- p. Incomplete or improper welding, riveting.
- q. Visual deformities.

- r. Lack of uniformity and symmetry where applicable.
- s. Unsealed appurtenances or other body components, gaskets, etc.
- t. In addition, any deviation from specification requirements or any other item, whether or not stipulated herein, that affects form, fit, function, durability, reliability, safety, performance or appearance shall be cause for rejection.
- u. Defective components shall not be furnished. Parts, equipment, and assemblies, which have been repaired or modified to overcome deficiencies, shall not be furnished without the approval of the Government. Welded, bolted, and riveted construction utilized shall be in accordance with the highest standards of industry. Component parts and units shall be manufactured to definite standard dimensions with proper fits, clearances, and uniformity. (All the old parts if any (removed parts from Repairs like partition, stretcher, etc. to be handed over to Govt office to the representative.

**Note:** In all the above cases, the disqualification cut-off date will be till the contract is signed

**III.** Notwithstanding anything stated above, the purchaser reserves the right to assess the Bidders capabilities and capacity to perform the contract should circumstances warrant such an assessment in the overall interest of the purchaser deciding on award.

**SECTION – VII (A): BID FORM**

(Name and Address of Purchaser)

**Date** \_\_\_\_\_

To  
The Managing Director,  
APMSIDC, Mangalagiri.

**Contract No.** \_\_\_\_\_

Having examined the Bidding Documents including Addenda No. \_\_\_\_\_ the receipt of which is hereby duly acknowledged, we, the under-signed, offer to supply and deliver \_\_\_\_\_ (Description of Goods and Services) in conformity with the said Bidding Documents for the sum as given in the Price Bid (electronically) or such other sums as may be ascertained in accordance with the schedule of prices furnished and made part of this bid.

We undertake, if our bid is accepted, to commence delivery as per the delivery schedule mentioned in this RFP and to complete delivery of all the items and perform incidental services as specified in the contract.

If our bid is accepted we will obtain the guarantee of a bank in a sum not exceeding 5% of the Contract price for the due performance of the Contract.

We agree to abide by this bid for a period of **90 (Number) days** from the date fixed for bid opening under Clause 22 of the Instruction to Bidders and shall remain binding upon us and may be accepted at any time before the expiration of that period.

We undertake that, in competing for (and, if the award is made to us, in executing) the above contract, we will strictly observe the laws against fraud and corruption in India like “The Prevention of Corruption Act 1988”

Until a formal contract is prepared and executed, this bid, together with your written acceptance thereof and your notification of award shall constitute a binding contract between us.

We understand that you are not bound to accept the lowest or any bid you may receive.

Dated this \_\_\_\_\_ day of \_\_\_\_\_

Signature: \_\_\_\_\_

(in the Capacity of): \_\_\_\_\_

Duly Authorized to sign bid for and on behalf of

\_\_\_\_\_

**Section VII (B)- Model Price Schedules (available on e-procurement Platform)**

S. No	Price for repairs of 336 ambulances (Rs.)

**Note:**

1. The price quoted shall be inclusive of all duties and sales and all taxes including transportation, installation, commissioning at site and all incidental charges associated with the contract.

**SECTION – VIII : BID SECURITY FORM**

To

The Managing Director  
APMSIDC, Mangalagiri.

Whereas \_\_\_\_\_ (hereinafter called "the Bidder" has submitted its bid dated \_\_\_\_\_ for the supply of \_\_\_\_\_ (hereinafter called "the Bid")

KNOW ALL MEN by these presents that WE \_\_\_\_\_ of \_\_\_\_\_ having our registered office at \_\_\_\_\_ (hereinafter called the Bank") are bound unto

\_\_\_\_\_ (hereinafter called "the purchaser") in the sum of \_\_\_\_\_ for which payment will and truly to be made to the said purchaser, the Bank binds itself, its successors and assigns by these presents. Sealed with the common Seal of the said Bank this \_\_\_\_\_ day of \_\_\_\_\_.

The conditions of this obligation are:

1. If the Bidder withdraws its Bid during the period of bid validity specified by the Bidder on the Bid form; or
2. If the Bidder, having been notified of the acceptance of its bid by the Purchaser during the period of bid validity:
  - Fails or refuses to execute the contract form if required;
  - Fails or refuses to furnish the performance security, in accordance with the Instruction to Bidders
  - Does not accept the correction of the bid price pursuant to Clause 15.7(c).

We undertake to pay the purchaser up to the above amount upon receipt of its first written demand, without the purchaser having to substantiate its demand, provided that in its demand the purchaser will note that the amount claimed by it is due to owing to the occurrence of one or both of the two conditions, specifying the occurred condition or conditions.

This guarantee will remain in force up to and including 45 days after the period of the bid validity, and any demand in respect thereof should reach the Bank not later than the above date i.e., upto \_\_\_\_\_.

..... (Signature of the Bank)

## SECTION – IX: CONTRACT FORM

THIS AGREEMENT made the \_\_\_\_\_ day of \_\_\_\_\_  
between \_\_\_\_\_ (Name of Purchaser) of  
\_\_\_\_\_ (Country of Purchaser) (hereinafter "the Purchaser")  
of one part and \_\_\_\_\_ (Name of the  
Supplier) of \_\_\_\_\_ (City and Country of Supplier)  
(hereinafter "the Supplier") of the other part.

WHEREAS the Purchaser is desirous that certain Goods and ancillary services should be provided by the supplier, viz, \_\_\_\_\_ (Brief description of Goods and Services) and has accepted a bid by the supply of Goods and services in the sum of \_\_\_\_\_ (Contract price in Words and Figures) (hereinafter "the Contract Price").

Now this Agreement witnessed as follows:

1. In this Agreement words and expressions shall have the same meanings as are respectively assigned to them in the conditions of Contract referred to;
2. The following documents shall be deemed to form and be read and construed as part of this Agreement, viz.:
  - (a) The Technical and Price bid of the Supplier
  - (b) The approved Technical Specifications,
  - (c) The General Conditions of Contract,
  - (d) The Special Conditions of Contract, and
  - (e) The Purchaser's Notification of Award.
3. In consideration of the payments to be made by the purchaser to the Supplier as hereinafter mentioned, the Supplier hereby covenants with the Purchaser to provide the Goods and Services and to remedy defects therein in conformity in all respects with the provision of the Contract.
4. The Purchaser hereby covenants to pay the Supplier in consideration of the provision of the Goods and Services and the remedying of defects therein, the Contract price or such other sum as may become payable under the provisions of the Contract at the times and in the manner prescribed by the Contract.
5. Brief particulars of goods and services which shall be supplied/provided by the Supplier are as under.

SL NO.	BRIEF DESCRIPTION TO GOODS & SERVICES	QUANTITY TO BE SUPPLIED	UNIT PRICE	DELIVERY TERMS

**TOTAL VALUE:**

**DELIVERY SCHEDULE:**

IN witness whereof the parties here to have caused this Agreement to be executed in accordance with their respective laws the day and year first above written.

Signed, Sealed and Delivered by the

Said \_\_\_\_\_ (For the Purchaser)

in the presence of \_\_\_\_\_

Signed, sealed and Delivered by the

Said \_\_\_\_\_ (For the supplier)

In the presence of \_\_\_\_\_

**SECTION- X: PERFORMANCE SECURITY FORM**

To

The Managing Director  
APMSIDC,  
Mangalagiri  
Guntur.

WHEREAS \_\_\_\_\_ (Name of the Supplier)  
hereinafter called "the Supplier" has undertaken, in pursuance of Contract No.  
\_\_\_\_\_ dated \_\_\_\_\_ to supply \_\_\_\_\_  
(Description of Goods and Services) hereinafter called " the Contract".

AND WHEREAS it has been stipulated by you in the said contract that the Supplier shall furnish you with a Bank Guarantee by a recognized bank for the sum specified therein as security for compliance with the Supplier's performance obligations in accordance with the Contract.

AND WHEREAS we have agreed to give the Supplier a Guarantee:

THEREFORE WE hereby affirm that we are Guarantors and responsible to you, on behalf of the Supplier, up to a total of \_\_\_\_\_  
(Amount of the Guarantee in Words and Figures) and we under take to pay you, upon your first written demand declaring the Supplier to be in default under the Contract and without cavil or argument, any sum or sums within the limit of \_\_\_\_\_  
(Amount of Guarantee) as aforesaid, without your needing to prove or to show grounds or reasons for your demand or the sum specified therein.

This guarantee is valid until the \_\_\_\_\_ day of \_\_\_\_\_.

Signature and seal of Guarantors

\_\_\_\_\_

\_\_\_\_\_

Date \_\_\_\_\_

Address \_\_\_\_\_

\_\_\_\_\_



**SECTION XI**

**FORMAT B1: PROFORMA FOR PERFORMANCE FOR FABRICATOR (for a period of last three years)**

(Please see Section VI: Qualification Criteria)

Bid No. \_\_\_\_\_ Date of Opening \_\_\_\_\_ Time \_\_\_\_\_ Hours

Name of the Firm \_\_\_\_\_

Order placed by _____ - (Full address of Purchaser )	Order No	Date	Description of Item	Quantity of ordered Repairs or Ambulances or similar health service vehicles	Value of order	Date of completion of delivery		Remarks indicating reasons for late delivery , if any	Has the Supplier received full payment towards the supplies made
						Purchase terms	Actual		
1	2	3	4	5	6	7	8	9	10

Signature and seal of the Bid Signatory

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

**SECTION XI**

**FORMAT B2**

**CA (STATUTORY AUDITOR) CERTIFICATE**

**(Please see Section VI: Qualification Criteria)**

**Certificate from the Statutory Auditor**

This is to certify that ..... (name of the Bidder) is a "Fabricator" of Repairs offered under the Bid. The Bidder had supplied the quantities shown in the past performance statement and also completed the respective supplies within the stipulated delivery period/s.

Further it is certified that the previously supplied <Insert appropriate vehicle type> are reported to be in working condition without any adverse remarks from the respective users and some are working for more than two year as per the records as on the date of this Tender notification.

The bidder has previous experience in maintenance and repairs of Repairs for \_\_\_\_\_ years and has qualified service staff working with him".

**Name of Authorized Signatory:**

**Designation:**

**Name of firm:**

**(Signature of the Authorized Signatory)**

**Seal of the Firm**

**SECTION XI**

### B3. FINANCIAL CAPACITY OF THE BIDDER

A. Details of Annual Turnover for Preceding 3 Years.

	Year 1 (2016-17)	Year 2 (2017-18)	Year 3 (2018-19)	Average Annual Turnover
Turn Over (In Rs. Crores)				

B. Details of Net Worth

	Year1 (Last Financial Year i.e. as on 31 <sup>st</sup> March 2019)
Paid up Capital (Rs. Cr)	
(Add) Free Reserves (Rs. Cr)	
Total Net Worth (Rs. Cr)	
<hr style="width: 80%; margin: 0 auto;"/> <p><b>(Signature of Bid Signatory)</b> <b>Seal of the Firm</b></p>	
<p>Certificate from the Statutory Auditor</p> <p>This is to certify that .....(name of the Bidder) has an average annual turnover (in the last three financial years) and Net Worth (in the last financial year) as shown above</p> <p>Name of Authorized Signatory: Designation: Name of firm:</p> <p style="text-align: right;">(Signature of the Authorized Signatory) Seal of the Firm</p>	

**Note:**

1. Bidder shall submit audited balance sheets for last three financial years

**SECTION - XII**

**DECLARATION FORM**

I / We ..... having Our  
..... office at ..... read and  
understood the terms and conditions contained in the bidding documents under this  
notification for bid and offer our bids unconditional, to the extent not stated at any  
other part of our bid.

We will not quote or supply the repairs Repairs similar to the ones offered  
under this bid notification to any agency or organization in the country, at the rate  
lower than the rate quoted in this present tender.

If we found quoting lower rate than the rate quoted to the APMSIDC, to any  
other agency in the country during the validity of the present contract, we will remit the  
differential cost to the APMSIDC, unconditionally.

Signature :

Date :

Name of the  
Firm and address :

## SECTION XIII

### Check List of Documents to be Uploaded as part of the Bid and Notes to Bidders

#### I. Documents with the Technical Bid

Sl. No	Document Description	Check (Yes or No)
1	Process Fee 11,800/-	Offline
2	EMD	Online & offline
3	Bid Form Section VII-A	Online & offline
4	List of items offered with Make and Specification details without prices (Tyre, Battery, Engine oil.. etc)	Online & offline
5	Past Performance Details Format B1( 5years Experience in repairing and Maintenance of vehicles, Preferably Tata Winger and Force Traveler.)	Online & offline
6	End-User Certificates or CA Certificate as per Format B2	Online & offline
7	Financial Capability Details Format B3	Online & offline
8	Details & proof of After Service facilities	Online & offline
9	Letter of authorization to sign the bids	Online & offline
10	Clause-by-clause commentary on identified issue as per the Annexure-I	Online & offline
11	Technical and Commercial deviations statements	Online & offline
12	Copy of the GST Certificate and Details of IT Returns- PAN / TIN copies.	Online & offline
13	The Service provider must have own workshop with more than 3 years running in AP.	Online & offline
14	Memorandum of Articles	Online & offline
15	All the uploaded documents to be attested by a Gazette Officer / Notarized / Self attested.	Online & offline
16	Workshop should be ISO certified	Online & offline

## **II. Financial (Price) Bid in the format available with the e-procurement platform**

- Please note that the Bidder runs the risk of his bid being rejected if the price schedule contains any conditions.

### **Notes to Bidders**

1. Upload the documents in ZIP format with suitable description as defined above.
2. The scanned documents shall be legible failing which they will not be considered.
3. Sign on all statements, documents, certificates uploaded owning responsibility for their correctness / authenticity.
4. All the statements copies of the certificates, documents etc., enclosed to the Technical bid shall be given page numbers on the right corner of each certificate
5. The format of B.G. towards E.M.D. should be adhered to as per prescribed format. Any deviation will result in making the bid non-responsive.
6. The tenderer is subjected to be black listed and the EMD forfeited if he is found to have misled or furnished false information in the forms / statements / certificates submitted in proof of qualification requirements or record of performance (Please see Corrupt and Fraudulent Practices Clause)
7. All the Bidders are requested to quote with single option only, for the each item offered and please note that bids with multiple options, for any one or all of the items offered, will be rejected by the purchaser as Non-responsive.

**Annexure -I**

**ANDHRA PRADESH MEDICAL SERVICES & INFRASTRUCTURE DEVELOPMENT CORPORATION (APMSIDC)**

**WARRANTY CERTIFICATE**

*(to be filled jointly by the Tenderer, Purchaser for every repairs)*

Date:

APMSIDC Supply order No : .....dated.....

The Repairs **Repairs** ..... (*Repairs Repairs Name*)

Model No..... bearing serial no ..... was commissioned successfully at ..... is offered with a comprehensive warranty for a period of ..... Years starting from ..... to ..... including all the following accessories;

Sl. No	Name of the accessory	Manufacturer's name	Repairs Serial No.	Qty

Name of the Supplier: Signature: Seal:	Name of the Purchaser / End User: Signature: Seal:
--	--

**Annexure - II**

**ANDHRA PRADESH MEDICAL SERVICES & INFRASTRUCTURE DEVELOPMENT CORPORATION (APMSIDC)**

**GENERAL INFORMATION ABOUT THE TENDERER**

Name of the Tenderer

Registered address  
of the firm:

State:

District

Telephone No.

Fax.No.

Email.

Address			
State		District	
Telephone No.		Fax	
Email		Website	

Type of Firm (Please ✓ relevant box)

Private Ltd.	<input type="checkbox"/>	Public Ltd.	<input type="checkbox"/>	Proprietorship	<input type="checkbox"/>
Partnership	<input type="checkbox"/>			Others, specify	<input type="checkbox"/>
Registration No. & Date of Registration.					
Nature of Business (Please ✓ relevant box)					
Fabricator	<input type="checkbox"/>	others (Please specify)	<input type="checkbox"/>		



## On Purchaser letter Head

Dt: \_\_\_\_\_

**ANDHRA PRADESH MEDICAL SERVICES & INFRASTRUCTURE DEVELOPMENT CORPORATION (APMSIDC)**

**THREE MONTHS PERFORMANCE CERTIFICATE**  
(to be filled by the head of user institution individually for every repairs)

Vehicle No.				
SUP.CODE / Name of the Supplier				
Repairs Details				
Name of the item:		Purchase Order No:		
Make / Manufacturer		Purchase Order Date:		
Model		Purchase Amount		
Serial no.		Project Name		
Date of Commissioning		Location / Department		
Whether <b>Repairs</b> working satisfactorily without any problem for one month?			YES <input type="checkbox"/>	NO <input type="checkbox"/>
If No, provide details of <b>Repairs</b> failure in the first month (attach additional details if any in a separate sheet)				
BREAK DOWN DETAILS				
Break down Reported Date	Attended date	Rectified date	Attended by	Details of beak down / service
Present status of the repairs		satisfied <input type="checkbox"/> Not satisfied <input type="checkbox"/>		
Recommended to settle the final 10% of payment		YES <input type="checkbox"/> NO <input type="checkbox"/>		
Recommend for trial run for one more month		YES <input type="checkbox"/> NO <input type="checkbox"/>		
Performance of accessories supplied				
Further Training		Required <input type="checkbox"/> Not required <input type="checkbox"/>		
Remarks of Purchaser				
Three months performance certificate was issued on (date to be filed in by the Purchaser or his authorized representative)				
Name of Purchaser		Sign.		

Signature of the Superintendent.		Sign. & Seal	
Date: Seal of supplier:		Date: Purchaser Seal :	

**Annexure – I – Vehicle wise details of repairs component**

**Annexure – II – District Wise Consolidated report on the details of  
repair components**

## Annexure-I - Vehicle wise details of repairs component

S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
1	AP16TH7805	TW	ANANTHAPUR	Engine oil level need to be changed, Valve cover gas kit leakage - Oil splash, Engine breather oil spill, Drain plug oil leakage, Engine oil chamber leakage	Gear box oil spill, Front & rear oil leakage, 2nd gear not working, drive shaft need to be replaced, Differential oil masks over the casing	Front lower arm bushes need to be replaced, shock absorbers bushes need to be replaced, front upper and lower arms need to be replaced, rear rod need to be replaced	Nil	Four tyres need to be replaced	1 battery need to be replaced	AC compressor not working	Front and rear lights not working, High beam not working, L/H not working, fog lamps not working	Front bumper damage, front windshield damage, side wall damage, front L/H foot step damage, weather strip needs to be replaced, minor dents, rear bumper L/H damage
2	AP16TH9940	F	ANANTHAPUR	Valve cover oil service to be done, Breather pipe damaged, Timing case oil leakage around surface, Engine oil spill near filter	4th gear not working	Fully suspension work should be done from high leaf spring and bushes front and back	Nil	Nil	1 battery need to be replaced	AC compressor not working	Fuel gauge not working, Front and back both door light switches not working, Wipers fuction need to be replaced, Windshield fluid shower nozzle to be replaced	Dense over the surface, pilot & copilot seat cover damaged, stoppers damaged, Hinger damaged, Front RH door hinger to be replaced
3	AP16TH7806	TW	ANANTHAPUR	Oil leakage near hose pipe, Oil leakage from valve door, Oil leakage from brake pipe, Oil spill over the engine coup, L/H mounting weak, Abnormal noise from engine	Oil leakage from drive shaft boot	Bushes and link rod need to be replaced, Bushes to be replaced	Disk to be replaced	Nil	Nil	Nil	Front both doors light switches damaged, Pilot cabin light damaged, Windshiled fluid shower motor & nozzles to be adjusted	Dents, Front bumper damaged, Show grill damaged, Pilot cabin floor rusty.
4	AP16TH7800	TW	ANANTHAPUR	Oil leakage from valve door, Connector pipe need to be cleaned	Oil boots to be replaced	R/H suspension complete noise, Bushes and anti roll bar need to be replaced, Rear bushes need to be replaced	Rear brake shoes & drums lines to be replaced, Front both side brake disc and pads need to be replaced	Front both side tyres need to be replaced, Spare wheel tyre need to be replaced	2 batteries need to be replaced	AC compressor not working	Fog lamps not working, Brake light function not working, Reverse gear indication light not working, Wipers not working, Windshield fluid shower nozzle need to be cleaned	Tail door LH inner lock and stopper not there, Pilot seat and co-pilot seat damaged, L/H stopper damaged, L/H side damaged, Outer lock damaged, Weather strips damaged
5	AP16TH7745	TW	ANANTHAPUR	Wall door packing replacement, engine r/h mounting bad replacement	Gear lever bushes and bush kit to be replace, drive shafts to be replace	Rear leaf spring bushes to be replace, ball joints replacement	Nil	Nil	Nil	AC gas filling, AC blowers replacement	Wipers, Nozzles replacement, minor electrical wiring checkup	Tyre rod ends replacement, pilot, copilot seats repair, locks setting
6	AP16TH9834	F	ANANTHAPUR	Leakage over the engine valve door, Oil spill near breathe pipe, timing case oil leakage near surface, Engine oil drain plus leakage, Engine oil filter base leakage	Nil	Suspension noise at front shock absorbers, Rear suspension leaf spring and bushes to be replaced	Oil hub greasing to be done, Hand brake efficiency not working	1 tyre need to be replaced	1 battery need to be replaced	AC compressor not working	Speedometer reading not working, Front both door light switches not working, Front and rear side parking lights not working, Low beam right side not working, Windshield fluid shower nozzle need to be replaced, Wiper blades need to be replaced	Front bumper damaged, Side view mirror minor damaged, Black grill damaged, Pilot seat cover damaged, Tail door L/H and R/H damaged, Rear both doors body stopper damaged

S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
7	AP16TH8431	TW	ANANTHAPUR	Nil	Gear box 3 RD Gear slip, Gear oil, Housing oil replacement, drive shaft boot replacement	Front shock absorbers replacement, Rear leaf spring bushes replacement	Nil	Nil	Nil	Nil	Heater plugs replacement, Wiring check up connections, Wiper Nozzles replacement	Doors setting, pilot seat, copilot seat repair
8	AP16TH8122	TW	ANANTHAPUR	Leakage over valve door, Engine breather need to be cleaned, Engine oil drain plug need to be replaced, Leakage near injector	2nd gear hard not engaged suddenly, Gear box oil spill over the surface, Oil spill around the shaft boot, Differential oil spill	Rear shaft bushes need to be replaced	Rear brake wheel cylinder (L/H) need to be replaced	5 tyres need to be replaced	2 batteries need to be replaced	Nil	Sppedometer gauge not working, Front & Rear parking lights not working, L/H side panel light not working, Reverse gear indication light not working, Wipers fuction blades need to be replaced, Windshield fluid shower nozzle need to be cleaned	Minor dents, door dents, Front R/H stopper not working, Front L/H Stopper need to be replaced, pilot and co-pilot seat covers damaged, Jack rod lock damaged
9	AP16TJ6892	TW	ANANTHAPUR	Nil	Nil	Rear leaf spring bushes to be replace, Front strut to be replace	Nil	4 tyres to be replacement	Nil	Nil	Minor electrical wiring checkup, Wiper Nozzle replacement	Nil
10	AP16TH7763	TW	ANANTHAPUR	Valve cover leak over head, Engine need to be cleaned, L/H monitoring leak & clog indicator not working, Radiator leakage	2nd gear not working, Gear levers hard, Clutch pedal hard, Drive shaft oil spilling, differential oil spilling	L/H shock absorber leakage, Rear suspension bushes and spring leave to be refabricated, L/H side upper and lower arms need to be replaced	Brake disc problem	5 tyres need to be replaced	2 batteries need to be replaced	Patient cabin AC coolant not working	Front one door light switch not working, Front and rear backlight not working, fog lamps damaged, reverse gear indication light not working, horn not working, Windshield fluid shower nozzle damage	Side view mirror damaged, front windshield frame rust formed, Single lock only working, Outer lock damaged
11	AP16TH8417	TW	ANANTHAPUR	Oil spill from top head, Oil leak from engine half, Engine oil drain plug minor spill	Gear cable head need to be replaced, Drive shaft boot oil spill, Differential oil spill	L/H suspension and L/H shock absorbersbushes need to be replaced, L/H side lower arm need to be replaced, Rear leaf bush need to be replaced	Front both side brakes discs and pads need to be replaced	1 tyre need to be replaced	1 battery need to be replaced	AC Gas need to be filled, No cooling	Both door light switches loose connection, Indication lamps not working, Windshield flud shower nozzle damage, L/H front parking light not working, High beam not working, L/H front indicator not working	Front bumper damaged, Fender L/H damaged, Front L/H door one lock only working, Weather strip need to be replaced
12	AP16TH8123	TW	ANANTHAPUR	Head gasket replace, Valvedoor pack replace	Drive shafts boots to be replaced	Front struts to be replace, all bushes replacement	Nil	Two tyres to be replaced	Nil	AC compressor not working to be over hauling, AC Gas to be fill	Minor electrical wiring checkup, Nozzles, Wiper blades replacement	Steering getting noise while taking turns steering rack and pinion bolts to be replace, door locks replace, pilot cabin seats repair
13	AP16TH7825	TW	ANANTHAPUR	Valve door & Head gasket replacement	Gear box over hauling, gear oil, Housing oil replacement	Rear leaf spring bushes to be replace, Lower Arm bushes replacement	Nil	Nil	2 batteries replacement	Gas filling & servicing	Minor electrical works wiring checkup	Pilot seat repair
14	AP16TH7771	TW	ANANTHAPUR	Air filter replacement, crank oil seal to be replace	Drive shaft boots replacement	Rear leaf spring bushes to be replace	Nil	1 tyre to be replace	1 Battery to be replace	AC gas to be fill, compressor to be replace	Wiper motor to be replace, minor wiring check up	Pilot, copilot seat repair, regulators repair, handle, setting
15	AP16TH8425	TW	ANANTHAPUR	Valve cover oil leakage, Timing case need to be replaced, Crank front seal leakage, Heater plugs needs to be replaced	Gear box oil spill leakage, Brake side oil spill, 2nd gear hand operating, Grease leak from both the boots	Front suspension noise on L/H side, Rear bushes need to be replaced, Front both upper and lower arms need to be replaced	Nil	4 tyres need to be replaced	2 batteries need to be replaced	Compressor not working, Gas need to be filled	Front both door light switches damaged, Reverse gear indication lights not working, Brake light function not working	Front bumper minor crack, dents on side wall, pilot & copilot seat damaged

S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
16	AP16TH8131	TW	ANANTHAPUR	Engine oil and filters to be replace walldoor packing to be replace, IDLER pulley to be replace, Injectors to be calibrate	Drive shaft boots to be replace	Rear leaf spring bushes to be replace	Nil	Tyres to be replace	1 Battery to be replace	AC gas to be replace, compressor over hauling	Speedometer not working, Heater plugs to be check	Rack and Pinion getting noise
17	AP16TH8435	TW	ANANTHAPUR	Nil	Gear box-2nd gear not engaging, clutch hard	Rear leaf spring bushes to be replace	Brake pads, Rear wheel liners to be replace	4 tyres replacement	Nil	AC gas to be fill, compressor to be check	Minor electrical wiring checkup	Nil
18	AP16TH7673	TW	ANANTHAPUR	Low oil level, Oil spill impression marks, Engine abnormal noise - white smoke	Lower oil spill marks at gear box front & rear, Front wheel drive at UJ cross condition, No leakage rear differential	Bushes to be replaced	Nil	Nil	1 battery need to be replaced	AC compressor need to be replaced	ABS engine light glow, Front & rear parking lights not working, Front both door light switches damaged, Wiper fuction blades need to be replaced	Front bumper damaged, Front windshield frame rust formed, Minor dents at side wall R/H, Beeding damage, Locks not working, Weather strips & stoper damaged
19	AP16TH7868	TW	ANANTHAPUR	Wall door packing replacement	Clurch hard, raising	Rear leaf spring bushes to be replace	Nil	Nil	Batteries to be replace	AC Gas to be fill	Minor electrical work	Door locks and lock sets to be replace, copilot seat repair
20	AP16TH7675	TW	ANANTHAPUR	Coolant level need to be replaced, Engine need to be cleaned	Axles (Front wheel drive) play abnormal noise	Bushes need to be replaced	Rear brake hose connector need to be cleaned	1 tyre need to be replaced	2 batteries need to be replaced	No gas in pipes, Cover damaged	Front & Rear parking lights not working, Front parking rear tail lamp damaged, Front both doors light switches not working, Pilot cabin light now working, Fog lamps not working, Break light function not working, Indication lamp not working	Body casing damaged, Front LH door stopper not working, dents over the body, Pilot seat damaged over cover, copilot seat damaged over cover and sponge
21	AP16TH9833	F	ANANTHAPUR	Nil	Nil	Rear bushes replacement, spring leaf bushes	Hand brake cable replace	Nil	Nil	Gas filling, servicing	Minor wiring check up	Pilot copilot seat repair
22	AP16TJ0017	F	ANANTHAPUR	Coolant oil replacements	Nil	Leaf spring bushes replacement	Nil	Nil	Nil	Gas filling, servicing, pipes replacement	Dynamo overhauling, wiper nozzle replacement, minor electrical repair, Horn repair	Doors, Hinges, Repair

S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
23	AP16TH7824	TW	ANANTHAPUR	Fan belt replacement, Engine bed replacement, Aie filter replacement	Gear box 2nd gear engaging hard, drive shaft boot replacement	Suspension bush kit replacement	Brake disc, brake pads replacement, rear brake liners replacement	Tyres four replacement	Nil	AC Compressor repair, Gas replacement	Minor electrical work, Wiper blades and Nozzle replacement	Tie rod ends replacement wind screen glass replacement, doors, pilot copilot seat repair
24	AP16TH8117	TW	ANANTHAPUR	Oil seal parts to be replaced, Engine oil chamber oil spill, Engine oil drain plug oil spill over surface, Turbo charger high pressure & return hose pipes need to be cleaned, Need to replace mounting bushes, Diesel wash to be done	Drive shaft boots to be replaced, L/H device shaft sound	Rear shock absorbers and bushes to be replaced	Nil	Mud flap only 1 missing	2 batteries need to be replaced	AC Gas filling, No cooling, High pressure pipe damaged	Instrument panel gauge not working, Pilot cabin light now working, Front & rear parking lights not working	Single lock working, minor dents, pilot & copilot seat cover and sponge damaged, Weather strip damaged, Outer lock damaged, R/H damage
25	AP16TH7867	TW	ANANTHAPUR	Nil	Nil	Rear leaf spring bushes to be replace, Front R/H strut to be replace, Lower Arm bushes replacement	Nil	Nil	2 Batteries replacement	AC Gas filling, servicing	Wiper nozzles replacement, minor electrical wiring checkup	Front wind screen glass replace, pilot seat, copilot seat repair, door handle repair
26	AP16TH7871	TW	ANANTHAPUR	Air filter replacement, Hose clips replacement	Gear Box 2 Nd Gear shifting Hard, Drive shafts boots replacement	Rear leaf spring bushes to be replace, lower arm bushes replacement	Nil	Nil	Nil	Gas filling, servicing	Minor electrical repair	Tyre rod ends replacement, doors, locks, regulator, door handles setting & repair
27	AP16TJ6842	TW	ANANTHAPUR	Nil	Nil	Rear Leaf Spring bushes to be replace, Front L/H strut to be replace	Nil	Nil	Nil	AC gas filling, AC compressor overhauling	Minor electrical wiring checkup	Nil
28	AP16TJ6902	TW	ANANTHAPUR	Nil	Nil	Rear Leaf Spring bushes to be replace, Front L/H strut to be replace	Nil	Nil	Nil	Nil	Minor electrical repair	L/H Side mirror replace
29	AP16TH9928	F	ANANTHAPUR	Nil	Center joint bearing replacement	Nil	Nil	Tyres replacement	Nil	Compressor pulley, A/C belt replacement, GAS filling, servicing	Minor electrical works, wiper blades replacement	Drag link replacement wind screen glass replacement
30	AP16TH7847	TW	ANANTHAPUR	Injector pipelines replacement, Engine oil to be replace, Engine bed replacement, air filter replacement	Gear box 2nd gear shifting hard gear oil, Housing oil replacement, Drive shaft boot replacement	Front suspension bush kit, Leaf spring bushes replacement	Brake booster replacement	Nil	One battery replacement	Gas filling, Servicing	Minor electrical check up, Wiper nozzle replacement	Tyre rod ends replacement, doors, locks, regulator, door handles setting & repair

S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
31	AP16TJ1643	F	ANANTHAPUR	Valve cover gas kit oil leakage, engine breather oil leakage, engine oil chamber leakage, turbo charger high pressure & return hose clips to be changed, air filter need to be cleaned	Differential oil minor leakage	Suspension bushes needs to be replaced, R/H 3rd spring leaf damaged	Nil	5 tyres need to be replaced	2 batteries need to be replaced	AC Gas need to be filled, AC compressor to be repaired	Instrument panel indication light not working, L/H front and rear indicators not working, Wiper fuction need to enlarge	Front bumper damage, Side view mirror damaged, Pilot and copilot seat cover damaged, dent on fender
32	AP16TH7651	TW	East Godavari	Nil	Gear box overhauling	Suspension major overhauling	Brake over overhauling to replacement brake pads and liners	Rear two tyres with tubes required	Nil	AC gas filling, AC pipes replacement and service charges	Minor repair to replace head light bulbs, fuse changes	Required for tools, Door lock settings and supporters etc.
33	AP16TJ6865	TW	East Godavari	Nil	Gear level cable with kit to changed	Front suspension overhauling and rear leaf springs recambering shockles with pins	Brakes overhauling, front brake pads to be changed	4 Tyres with tubes	Nil	AC Gas filling, filter changing and service charges	Nil	Minor patch work, body dents leveling, lock settings etc.,
34	AP16TJ6851	TW	East Godavari	Engine top overhauling to replace piston rings and head gasket including FIP nozzles overhauling	Nil	Rear springs recambering to replace shockles with bushes	Brakes overhauling to replace front brake pads and rear brake liners to be changed	4 tyres with tubes	Nil	AC Gas filling and filter changing, service charges	Nil	Damaged front bumper side corder, minor lock setting
35	AP16TH7652	TW	East Godavari	Engine oil leakage from the bottom crank case and value cover replaces mounting beds	Gear lever and clutch free play adjustment	Suspension bush kit and rear leaf spring recamering to be changed	Brake over hauling to replacement break liners and kits	4 tyres with tubes	Nil	Nil	Speedometer, front and rear parking lights and danger lights, fog lamps is to be changed	Required for body bed bolts and supports and tools
36	AP16TH7832	TW	East Godavari	Engine top overhauling to replace piston rings and head gasket. FIP with nozzles overhauling	Nil	Suspension major overhauling, replacement of bush kit, rear leaf springs recambering, shock absorbers, shockles with bushes and wheel alignment	Brake overhauling to replacement brake pads and liners	1 tyre with tube	1 Battery	AC gas filling, Compressor repair and AC pipes replacement and service charges	Instrument pannel gauges, front rare pannel indicators, brake lights, vipers	Required for body bed bolts and supports and tools
37	AP16TH9930	F	East Godavari	Engine oil leakage from the bottom crank case and valve cover, timing case oil seal	Gear box overhauling, 3rd gear slip, Clutch overhauling, replace sleeve cylinders and pressure plate assembly, Yoke and teeth to be changed	Suspension bush kit, Front and rear leaf springs recambering and shockle bush kit to be changed	Brakes overhauling and replace front and rear brake pads and liners	4 tyres with tubes	1 battery	AC as filling and filter changing and service charges	Minor repair to replace parking light and side blinkers etc.	Tools required, all door lock settings



S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
38	AP16TJ0467	F	East Godavari	Engine oil leakage from the bottom crank case and valve cover, turbo high pressure pipe leak	Gear lever bush kit changing	Front suspension overhauling, replacement of bush kit, shock absorbers to be replaced	Brakes overhauling to replace front and rear brake pads and liners	Nil	Nil	Nil	Odo meter to be replaced and front and rear parking lights, horns repair	Front bumper corner damaged, left right side walls damaged required patch work, all doors lock settings
39	AP16TH7852	TW	East Godavari	Engine oil leakage from the bottom crank case and valve cover and air filter required	Clutch sleeve cylinder lower and upper replacement	Front suspension overhauling to replace bush kit and rear leaf springs recamer, replacement of shockles with bushes	Nil	4 Tyres with tubes	Nil	AC gas filling, filter changing, compressor not working and service charges	Odo meter, front both danger lights and rear parking lights and danger lights, fog lamp required	Damaged front bumper and RH regulator, pilot seat damaged patch work and tinkering, all hinges and lock settings etc.
40	AP16TH8043	TW	East Godavari	Nil	Front wheel axles to be replaced with differential packing	Rear shock absorbers to be replaced	Brake overhauling to replace front brake pads and rear brake liner to be changed	4 tyres with tubes	Nil	AC pipes replacement, AC compressor and gas filling, filter to be changed	Instrument panel indication lights, front both danger lights, reverse gear ignition switch	Body minor patch work and tinkering and door dents leveling to replace locks and beedings
41	AP16TH8124	TW	East Godavari	Leakage from engine oil filter, valve cover, turbo charger pipes and air filter required	Gear box oil leakage to replace packing kit, and retainer oil seals, clutch overhauling to	Front shock absorbers to be replaced and rear leaf springs recambering to replace shockles with bushes	Brakes overhauling to replace front brake pads rear brake liners	4 tyres with tubes	1 New battery	Complete AC repair	Odo meter, front both danger lights and rear parking lights and danger lights, fog lamp required	Damaged front bumper, windshield frame, pilot seat frame tinkering and patch work all body hinges, lock settings etc
42	AP16TJ6870	TW	East Godavari	Filter camp damaged is to be replaced and air filter required	Gear box oil leakage to replace packing kit, oil seals etc.,	Rear leaf springs recambering to replace shockles with bushes	Brakes overhauling to replace front brake pads and rear brake liners to be changed	2 tyres with tubes	1 New battery	Complete AC repair	Dynamo overhauling, if necessary overhauling, rear parking and danger lights, fog lamp	Pilot seat damaged and patch work door lock settings and hinges, beeding to be replaced etc.,
43	AP16TH7830	TW	East Godavari	Engine oil leakage from the bottom crank case and valve cover	Gearbox packing kit to be replaced	Suspension bush kit need to be done	Nil	4 tyres with tubes	Nil	AC gas filling, Compressor and filters to be changed	Front and rear parking lights, danger lights, indicators, fog lamp to be replaced	Required for tools, body bed bolts and supporters etc.
44	AP16TJ6913	TW	East Godavari	Engine top overhauling piston ring and gaskit replaced including FIP with nozzles	Gear box overhauling charges to replace 4th gear wheel synchronizing hub assembly	Suspension rear leaf springs recambering and bush kit changing	Brakes overhauling to replacement of brake liners and cylinder kits	Four tyres with tubes	Nil	Nil	Head lihths, Parking lights, fog lamp and arms required	Tools required, Jack with rod
45	AP16TH9882	F	East Godavari	Engine oil leakage from the bottom crank case and valve cover, Filter cap, breather pipe, turbo charger high pressure pipes and air filter is to be changed	Gear lever and clutch lever bush to be changed	Front and rear suspension overhauling and to replace bush kit and rear shockle kits with bushes and shock absorbers	Brake overhauling to replacement brake pads and liners	2 tyres with tubes	Nil	AC gas filling, AC compressor and filters changing, AC pipes replacement	Front and rear parking lights and head lights and instrument panel indication lights, fog lamps	Pilot seat minot patch work, tail door patch work, door and glass settings

S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
46	AP16TH7648	TW	East Godavari	Engine oil leakage from the bottom crank case and valve cover	Gear lever and clutch free play adjustment	Suspension bush kit to be changed	Brake overhauling and replacement brake pads and liners	Four tyres with tubes	Nil	AC gas filling charges, AC pipes replacement and servicing charges	Mainer repair to replace parking light and side blinkers etc.	Required tools, body bed bolts and supports etc.
47	AP16TH7649	TW	East Godavari	Nil	Clutch overhauling and to replace clutch pressure plate assembly	Suspension rear leaf springs recambering and bush kit to be charged	Brake overhauling to replacent break liners and cylinders kit charges	Nil	Nil	AC gas filling and filter and servicing charges	Minor charges repair to replace parking light and side blinkers etc.	Required for tools, body bed bolts and supporters etc.
48	AP16TH7855	TW	East Godavari	Engine oil leakage from the bottom crank case and valve cover, turbo charges pipes leakage, engine mounting beds required and air filter	Gear box overhauling, 2nd gear wheel to be replaced and clutch overhauling to replace clutch sleeve cylinder lower and upper	Front shock absorbers to be replaced and rear leaf spring recambering to replace shockles with bushes	Brakes overhauling to replace front brake pads with brake discs	4 tures with tubes	Nil	AC Gas filling, compressor and filters and pipes and servicing charges	Front and rear parking and danger lights, fog lamps, vipre motor overhauling	Dmaged front bumper, bonet, front wind shield frame patch work, pilot seat patch work and tinkering all door hinger lock settings etc.
49	AP16TH9891	F	East Godavari	Engine oil leaking from the bottom crank case and valve cover	Gear box overhauling, replacement of 2nd gear wheel synchronizing hub assembly to be changed	Front and rear leaf springs recambering and bush kit changing	Brake overhauling to replacement brake pads and liners	2 tyres with tubes	2 new batteries	Complete AC repair	Odo meter changing, indicator lights, rear parking lights, head lights, fog lamp, vipre maching overhauling	Front left side bumper damaged is to be replaced, front wind shield frame patch work and other minor repairs
50	AP16TJ0475	F	East Godavari	Engine oil leakage from the sump and drain cplug and valve cover, breather pipe, engine mounting beds and air filter required	Gear oil required leakage to replace packing kit and retainer oilm seals, clutch overhauling	Front suspension, overhauling and rear leaf springs recambering, bush kit to be changed	Brakes overhauling, front brake drums with pads to be changed	2 tyres with tubes	Nil	Complete AC repair	Self starter overhauling, odo meter changing, front and rear danger lights and parking lights to be changed	Front bumper damaged, front bonet lock setting, all door lock setting and minor patch work
51	AP16TH8358	TW	East Godavari	Engine oil leakage from the bottom crank case and valve cover, air filter required	Gear lever and clutch free play adjustment	Suspension bush kit, rear leaf springs recambering with bush kit	Brake over overhauling to replacement brake liners and pads	4 tyres with tubes	1 Battery	AC gas filling, pipes replacement and service charges	Pilot cabin light, front and rear parking lights, Self starter overhauling, fog lamp, reverse gear indication switch	Front bumper, Front and rear doot hinges, pilot sear patch work, all door lock settings
52	AP16TH9932	F	East Godavari	Engine oil leakage from the bottom crank case and valve cover	Nil	Suspension front and rear leaf spring recambering to replace shockles with bush kit	Rear brake liners to be changed	1 tyre with tube	Nil	Nil	Odo meter changing, head lights, parking lights, fog lamp, front and rear panel indicators	Front left door lock setting, side wall frame patch work, pilot seat patchwork, all door lock setting
53	AP16TJ6854	TW	East Godavari	Engine oil leakage from valve cover and engine oil filter bed. Air filter to be changed	Nil	Front shock absorbers to be replaced, rear leaf springs recambering to replace shockels with bushes	Brakes overhauling to replace brake pads and brake liners	4 Tyres with tubes	Nil	AC gas filling and filter changing and service charges	Fog lamp, horns required	All door lock setting and beeding, hibges and pilot seat repair patchwork
54	AP16TJ6861	TW	East Godavari	Engine oil filter cap, oil leakage from valve cover, air filter required	Nil	Front shock absorbers to be replaced and rear leaf springs recambering to replace shockles with	Nil	1 tyre with tube	Nil	AC gas filling and filter changing, servicing etc.,	Front both danger lights and head lights, brake lights, Horns repair required	Damaged front bumper and side walls, pilot seat patch work and tinkering all door lock

S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
55	AP16TH7663	TW	East Godavari	Nil	Nil	Suspension bush kit, back leaf springs recambering, shock absorbers replacement	Nil	Rear two tyres with tubes	Two batteries	Nil	Nil	Pedal lock setting, spot lights and wall mounted fans repairs charges
56	AP16TJ1445	F	East Godavari	Engine oil leakage from the valve corner and engine mounting beds, airfilter to be replaced	Gear oil leak, oil seal replacement, side packings	Front and rear leaf springs recambering to replace shockles with bushes	Brakes overhauling to replace brake lines with drums near, front brake pads to be changed	1 tyre with tube	Nil	Gas filling, Filters servicing charges	Self starter overhauling, odo meter changing, front and rear danger lights and parking lights to be changed	Front bumper patch work, rear corners patch work, pilot seat patch work
57	AP16TH7828	TW	East Godavari	Engine oil leakage from the bottom crank case and valve cover	Gear lever and clutch free play adjustment	Suspension major bush kit need to be done including rear leaf spring and cambering charges	Brake overhauling to replacement brake pads, brake liners, wheel cylinder assemblies, brake disks and drums	4 tyres with tubes	2 new batteries	AC complete repair	Major repair. All lights, bulbs, vipre motor, arms required	Required for tools, body bed bolts and supporters etc.
58	AP16TJ0465	F	East Godavari	Engine oil leakage from the bottom crank case and valve cover	Nil	Front and rear leaf springs recambering	Brakes overhauling to replace front and rear brake pads and liners	1 tyre with tube	2 new batteries	AC gas filling and filter changing and servicing charges	Odo meter, instrumental panel gauges, pilot cabin light, front and rear parking lights and danger lights, vipre motor overhauling	Front bumper damaged to replace, all door glass and lock settings, side view mirrors to be replaced
59	AP16TH8041	TW	East Godavari	Nil	Nil	Suspension bush kit and shock absorbers to be replaced	Brakes overhauling, replacement of brake pads and liners	4 tyres with tubes	2 new batteries	AC gas filling and service charges	Minor repair to replace parking light and side blinkers etc.	Required for tools, body bed bolts and supporters etc.
60	AP16TH7766	TW	East Godavari	Engine oil filter cap damaged is to be replaced, air filter required	Gear box overhauling to replace the packing kit and retainer seals	Front suspension overhauling and rear leaf springs recambering shockles with bushes to	Brakes overhauling to replace front brake pads and rear brake lines with drums	4 tyres with tubes	1 new battery	Nil	Front both door lights and rear parking and danger lights, self starter overhauling and rever gear wheel indication light	Damaged front bumper, front RH regulator arm patch work, pilot seat patch work and tinkering, all door lock setting and hinges etc

S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
61	AP16TH8125	TW	Kadapa	1. Gasket rocker cover and Engine mtg beds replacement required	1. Transmission oil seals replacement required 2. Transmission assly O/H required 3. Clutch O/H required	Front suspension work and rear leaf springs recambering work, Bushes replacement required	Nil	Front and rear tyres replacement required	Required new inverter battery	AC gas filling, filters changing and O/H	Electrical work required	1. Fuel injector pipe replacement required 2. FIP O/H required 3. Power steering house pipes replacement required 4. Pilot seat rexin work required 5. Inverter repair required
62	AP16TH8033	TW	Kadapa	1. Water pump assly replacement required 2. Radiator hose pipes replacement required 3. Engine oil replacement required 4. Gasket rocker and Engine mt beds replacement required	Transmission oil seal replacement required	1. Front suspension O/H required 2. Rear leaf springs recambering work required and bushes replacement required	4 wheel hub O/H required	Front and rear tyres replacement required	Inverter new battery required	AC compressor, Gas filling, Connecting pipes and O/H required	Complete electrical work required	1. Front RH and LH door locks and regulator replacement required 2. Pilot and copilot seat rexin work required
63	AP16TJ0460	F	Kadapa	Water pump assly replacement required and Engine mtg beds replacement required	Transmission oil seal replacement required and clutch O/H required	1. Front suspension O/H required 2. Front and Rear leaf springs recambering work required. Bushes replacement required	4 wheel hub O/H required	Rear left and spare tyres required	New starting and inverter battery required	AC compressor, Gas filling, Connecting pipes and O/H required	Electrical work required	1. Propellar shaft bearing replacement required 2. Pinion oil seal replacement required 3. Body tinkering and painting work required
64	AP16TH8351	TW	Kadapa	1. Radiator fan (viscous fan) replacement required 2. Engine O/H required 3. Engine mtg beds replacement required	Transmission oil seal replacement required and clutch sleeve cylinder replacement required	1. Front suspension work required 2. Rear leaf spring recambering work and bushes replacement required	4 wheel hub O/H required	Front and rear new tyres required	Required new inverter battery	AC compressor, Gas filling, Connecting pipes and O/H required	Electrical work required	1. Self motor O/H required 2. Pilot seat rexin work required 3. Rear foot step denting work required 4. Speedometer cable and worm replacement required
65	AP16TH9931	F	Kadapa	Engine mtg neds and Gasket rocker cover replacement required	Transmission assly O/H required	Front suspension work required. Front and rear leaf springs recambering work required	Nil	Front and rear new tyres required	New starting and inverter battery required	AC gas filling, filters changing and O/H	Electrical work required	1. Power steering hose pipes replacement required 2. Rear doors denting and painting work required 3. FIP O/H required
66	AP16TH8415	TW	Kadapa	Gasket rocker cover replacement required	Transmission oil seal replacement required	Front suspension work and Rear leaf springs recambering work and bushes replacement required	4 wheel hub O/H required	Front and rear new tyres required	New inverter battery required	AC gas filling, filters changing and O/H	Electrical work required	1. FIP O/H required 2. New front windshield glass required
67	AP16TH8128	TW	Kadapa	Engine O/H required and Engine mtg beds replacement required	Transmission assly O/H required	Front suspension O/H required, Rear springs recambering work and bushes replacement required	4 wheel hub O/H required	Rear new tyres required	New starting and inverter battery required	AC gas filling, filters changing and O/H	Electrical work required	1. FIP O/H required 2. Speedometer cable and worm replacement required

S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
68	AP16TH7645	TW	Kadapa	Engine mounting beds and Air filter element replacement required	Nil	Front suspension O/H, Rear leaf spring recambering work and O/H	4 wheel hum and brake O/H required	New front left, Rear left and right and spare tyre required	New inverter battery required	AC gas filling and Check up	Inverter repair required and Electrical work required	Pilot and Copilot seat work required, Speedometer cable and worm replacement required
69	AP16TH7743	TW	Kadapa	1. Gasket rocker cover replacement required 2. Crank shaft front & rear oil seal replacement required 3. Engine mtg beds replacement 4. Engine oil and filters replacement	Transmission oil seal replacement required	Front suspension work O/H required. Rear leaf springs recambering and bushes replacement required.	4 wheels hub overhauling required	Front RH side tyre and rear both tyres replacement required	New inverter battery required	AC compressor, Gas filling, Connecting pipes and O/H required	Electrical work required	1. Spare Tyre and RIM not available 2. Front RH and LH side door locks and regulator replacement required 3. Minor tinkering and painting work required 4. LH door hinges replacement required 5. Pilot and copilot seat rexin work required
70	AP16TH7802	TW	Kadapa	1. Radiator fan replacement required (Viscous fan) 2. Gasket rocker cover replacement	Transmission oil seal replacement required	Front suspension work and rear leaf springs recambering work required	Nil	Front and rear tyres replacement required	Starting battery and inverter battery required	AC compressor, Gas filling, Connecting pipes and O/H required	Electrical work required	1. Self motor O/H required 2. Pilot and Copilot seat rexin required
71	AP16TH7795	TW	Kadapa	1. Crank shaft front and Rear oil seal replacement required 2. Gasket rocker cover replacement required	1. Transmission oil seals replacement required 2. Clutch O/H required	Front suspension work required and Rear leaf springs recambering work required	Rear brake linings replacement required	Front, Rear tyres required	New inverter battery required	AC compressor, Gas filling, Connecting pipes and O/H required	Electrical work required	1. Steering box hose pipes replacement required 2. Wiper blades replacement required 3. Minor tinkering and painting work required at front windshield glass frame 4. Front RH side door locks, Regulator and Hinges replacement required 5. Pilot and Copilot seat rexin work required 6. New jockey required 7. Alternator O/H required
72	AP16TH9937	F	Kadapa	1. Engine oil and filters replacement 2. Gasket rocker cover, front crank shaft oil seal and Engine mtg bed replacement required 3. Air filter element replacement required	Nil	1. Front suspension work required 2. Front and Rear leaf springs recambering work, bushes replacement required	1. 4 Wheel brakes O/H required 2. Front RH side brake drum and caliber assly replacement required	Front and rear tyres replacement required	New starting and inverter battery required	AC gas filling, filters changing and O/H	Electrical work required	1. Propeller shaft bearing and bed replacement required 2. Differential oil seal replacement required 3. Front RH door bottom and Bonnet minor tinkering work required 4. Pilot and Copilot seat rexin work required

S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
73	AP16TJ1651	F	Kadapa	1. Crank shaft front and Rear oil seal replacement and Gasket rocker cover replacement required	Gear lever bushes and oil seals replacement required	1. Front suspension work required 2. Rear leaf spring recambering work and bushes replacement required	Nil	Rear left and spare tyres required	Starting battery and inverter battery required	AC gas filling, filters changing and O/H	Electrical work required	Accalator pedal assy required
74	AP16TH8126	TW	Kadapa	1. Radiator fan replacement required (Viscous fan) 2. Engine mtg beds and Gasket Rocker cover replacement required	Transmission oil seal replacement required	Front suspension O/H required and Rear leaf springs recambering work required	Rear brake linings replacement required	Rear and spare tyres replacement required	Inverter new battery required	AC gas filling, filters changing and O/H	Electrical work required	1. Pilot seat rexin work required 2. Rear door handle lock replacement required 3. Inverter alternator O/H required
75	AP16TJ6895	TW	Kadapa	Nil	Transmission oil seal replacement required	Front suspension O/H required	Nil	Front tyres and Spare tyre required	Nil	Nil	Minor electrical work required	Nil
76	AP16TH7753	TW	Kadapa	1. Replacement of Gasket rocker cover required and Engine mtg beds replacement required 2. Air filter element replacement required	Transmission oil seals replacement required	Front suspension work required and Rear leaf springs work and bushes replacement required	Rear brake linings replacement required	Front, Rear tyres replacement required	New starting battery and inverter battery required	AC compressor, Gas filling, Connecting pipes and O/H required	Electrical work required	1. Cabin floor mat required 2. Front RH side door glass regulator replacement required 3. Pilot and Copilot seat rexin work required 4. Rear door lock replacement required 5. RPM meter replacement required 6. Denting work required at top of the Cabin
77	AP16TH7808	TW	Kadapa	Engine oil, filters and gasket rocker cover replacement required	Clutch O/H required (Clutch disc, Clutch master and sleeve cylinder to be replaced)	Rear leaf spring recambering work required, Front suspension work required	4 wheel hub O/H required, Brake master cylinder assy and brake booster replacement required	Rear new tyres replacement required	New starting battery and inverter battery required	Compressor, Gas filling and O/H required	Light bar and public system not working, Electrical work required	Fuel pump and fuel injectors O/H required, Front left door O/H required (Replaced pad, Handle and locks to be replaced)
78	AP16TJ0463	F	Kadapa	Engine O/H Required, Engine Mtg beds replacement	Clutch O/H required	Front king pin work required, Front and rear leaf springs recambering work required	Nil	New rear left and spare tyre required	New starting battery and inverter battery required	Gas filling and checkup	Minor electrical work required	Power steering O/H required, Pilot and copilot seat work required, Differential O/H required
79	AP16TJ0461	F	Kadapa	Engine oil and filters replacement required, Crank shaft front oil seal replacement required	Transmission O/H required (4th gear not engaged)	Front leaf spring recambering work and Rear shock absorber bushes replacement required	4 wheel hub O/H and Hand brake O/H required	Required 1 No tyre and Tube	New starting battery and inverter battery required	Compressor, Gas filling and O/H required	Minor electrical work required	Speedometer cable and speedometer worm replacement required

S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
80	AP16TJ6910	TW	Kadapa	Turbo charger O/H required	Clutch O/H required and Transmission oil seal replacement required	Front suspension O/H required and Rear leaf springs recambering work and Bushes replacement required	4 Wheel hub O/H required	Front left and Spare New tyre required	New inverter battery required	AC gas filling and Check up	Electrical work required	1. Front LH door regulator replacement required 2. Co pilot seat rexin work required
81	AP16TJ6844	TW	West Godavari	Engine oil changing, Engine oil filter, Fuel filters and Air cleaner element	Nil	Front coil springs inside shock absorbers 2 Ns. Ball joints 4 Ns. and labour charges	Brake pads change Brake liners rear WC Assy. Oil seals grease foundry work	5Nos	Nil	Compressor Gas filling & Testing Labour charges	Horns 1 Set	Nil
82	AP16TJ0657	F	West Godavari	Nil	Nil	Steering System O/H - Replacement of Rock, Pinion, Kit & Labor Charge	Nil	5Nos	2Nos	Compressor Gas filling & Testing Labour charges	Alternator O/H, All Door Lights repair and bulbs replace	Side view Mirror-(RH), Front RH Door Locks repair
83	AP16TH8132	TW	West Godavari	Nil	Nil	Nil	Nil	2Nos	2Nos	Compressor Gas filling & Testing Labour charges	Nil	Right and left side view mirrors
84	AP16TH7660	TW	West Godavari	Nil	Nil	Front coil springs inside shock absorbers 2 Ns. Ball joints 4 Ns. and labour charges	Nil	5Nos	2Nos	Compressor Gas filling & Testing Labour charges	Horns 1 Set	Front Bonnet Lock repair, Front Wind shield frame tinkering
85	AP16TJ0656	F	West Godavari	Engine oil changing 7Lt-2100/-, Engine filter 155/-, Air Cleaner element 300/-	Nil	Replacement of Front Shock absorbers 2Ns	Hand brake wire & Labor Charge	4Nos	2Nos	Compressor Gas filling & Testing Labour charges	Pilot Cabbine light, Parking Light bulbs	Side Mirror (RH)
86	AP16TH7860	TW	West Godavari	Nil	Gear Box O/H	Nil	Nil	2 Nos	2 Nos.	Compressor Gas filling & Testing Labour charges	Nil	Nil
87	AP16TH7810	TW	West Godavari	Front porsation complete damage up to front cabin	Transmission complete overhauling	Front Suspension complete overhauling	Braking system overhauling	3Nos	2Nos	Air condition system complete damage except blower	Front electrical system damage	Front porsation complete damage up to front cabin
88	AP16TJ6835	TW	West Godavari	Nil	Nil	Front coil springs inside shock absorbers 2 Ns. Ball joints 4 Ns. and labour charges	Nil	4Nos	2Nos	Compressor Gas filling & Testing Labour charges	Nil	Nil
89	AP16TH8034	TW	West Godavari	Engine oil changing, Engine oil filter, Fuel filters and Air cleaner element	Nil	Front coil springs inside shock absorbers 2 Ns. Ball joints 4 Ns. and labour charges	Nil	5Nos	2Nos	Compressor Gas filling & Testing Labour charges	Nil	Nil
90	AP16TJ1648	F	West Godavari	Nil	Nil	Steering System O/H-	Nil	5Nos	2Nos	Compressor Gas filling & Testing Labour charges	Nil	No Ripers
91	AP16TH9892	F	West Godavari	Nil	Nil	Replacement of Front Shock absorbers 2Ns-6000/-, Steering system O/H-5300/-	Nil	5Nos	1Nos	Compressor Gas filling & Testing Labour charges	Horns 1600/-, Cobination Swith 2500/-	No Ripers

S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
92	AP16TH7998	TW	West Godavari	Nil	Drive Shafts 2Nos., Shafts Big Bearings 2Ns., Shaft small Bearings 2Ns	Front coil springs inside shock absorbers 2 Ns. Ball joints 4 Ns. and labour charges	Nil	3Nos	1Nos	Compressor Gas filling & Testing Labour charges	Nil	Nil
93	AP16TH7752	TW	West Godavari	Nil	Gear Box O/H	Power string system - repair and oil filling	Brake booster diaphragm replacement and vaccume testing	5Nos	2Nos	Compressor Gas filling & Testing Labour charges	Self starter overhauling	Nil
94	AP16TJ6918	TW	West Godavari	Nil	Nil	Front coil springs inside shock absorbers 2 Ns. Ball joints 4 Ns. and labour charges	Nil	3Nos	Nil	Compressor Gas filling & Testing Labour charges	Electrical Minor Wiring	Wind shield frame tinkering, and rubber beading
95	AP16TH9880	F	West Godavari	Nil	Nil	Nil	Nil	2Nos	2Nos	Compressor Gas-3000/-, Filter-2500/-, Compressor valve-2000/-, Condencer Channels-2Nos-4000/-, Labour Charge-7000/-	Wiper Blades 2Nos.600/-, Parking Bules.120/-	Bumper, Emblem spring, Front Cabin both seats repair, Rear door locks repairs
96	AP16TH8416	TW	West Godavari	Nil	Nil	Front coil springs inside shock absorbers 2 Ns. Ball joints 4 Ns. and labour charges	Replacement of left side caliper Assy. And labour Charge	3Nos	1Nos	Compressor Gas filling & Testing Labour charges	Brake light, reverse gear indication light, horns	Wind shield frame tinkering and rubber beading
97	AP16TH7672	TW	West Godavari	FIP Overhauling - Replacement of Element, Delivery Valves, Toothed Quadrents, Countrol Road, Facing & Calibration	Nil	Front coil springs inside shock absorbers 2 Ns. Ball joints 4 Ns. and labour charges	Nil	5Nos	1Nos	Compressor Gas filling & Testing Labour charges	Horns 1Set.	Wind shield frame tinkering, left side view mirror
98	AP16TJ6852	TW	West Godavari	Nil	Drive Shafts 2Nos., Shaft Big Bearings 2Ns., Shaft small Bearings 2Ns.	Nil	Nil	5Nos	Nil	Compressor Gas filling & Testing Labour charges	Nil	Nil
99	AP16TH8003	TW	West Godavari	Nil	Nil	Front Suspension Work & Rear Leafe Recambering works bushes Replacement required	Nil	5Nos	2Nos	Compressor Gas filling & Testing Labour charges	Head Light Assy.2Nos	Pilot & Co.Pilot Seats repair
100	AP16TJ0660	F	West Godavari	Nil	Replacement of Gear Shifting Lever Bussing Kit and Laber	Front rear road springs recambering busses 12 Nos.1200/- Eye pins & bolts-12Nos.840/- Center Bolts-4Nos.200/- Labour-3000/-	Hand brake cable & reaper.1000/-	5Nos	Nil	Compressor Gas filling & Testing Labour charges	Horns, Blubs, 2320/-	Rear door locks repair
101	AP16TH9638	F	West Godavari	Coolent water 3Lt., Air Cleaner Element	Nil	Recambering Four Road Spring Assb	Nil	3Nos	2Nos	Compressor Gas filling & Testing Labour charges	Horns 2Nos	Rear left door tinkering



S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
102	AP16TH8350	TW	West Godavari	Changing Coolent, Air filter	Nil	Front coil springs inside shock absorbers 2 Ns. Ball joints 4 Ns. and labour charges	Rear wheel brake system O/H	5Nos	2Nos	Compressor Gas filling & Testing Labour charges	Horns 1 Set	Front Cabin seats repair
103	AP16TJ6841	TW	West Godavari	Radiator Assy., Hoseipe Set.	Nil	Front coil springs inside shock absorbers 2 Ns. Ball joints 4 Ns. and labour charges	Nil	5Nos	2Nos	Compressor Gas filling & Testing Labour charges	Nil	Front Bumper Tinkering, right side view mirror, bonnet tinkering, grill, bonnet lock repair, front (RH) glass lifting mission. Wind shield glass
104	AP16TH7856	TW	Guntur	Air fiter change coolent change 3 liters,wall door package	Changing of Gear oil & Differational oil 4.5 liters ,drive shafts 2nos, cluch slave cylinder replacement	Rear suspension system O/H	Break pads change 1 set &Break Liner ,Rear WC Asembly ,Oil seals, Grease Breaking system O/H and Pondary charges	One tyres wanted	One battery wanted	Air condistor Unit Removing & Cleaning ,Fitting vacum dust & Gas filling Labour charge	Wiper baldes 2no	Upholstory
105	AP16TH7995	TW	Guntur	1.Engine oil changing-7 Lts 2,Engine oil filters3.Fuel filters Air fiter change coolent change 3 liters,wall door package	Gear shifting lever bushing kit ,cluch master cylinder and cluch slave cylinder assembly	Streaing system -Replacement power oil pipe rock and pinion rear road springs recambering	Breake pads change 1set & brake liners ,Rear WC Asembly ,Oil seals Grease Breaking system O/H and pondary charges	Two Tyres wanted	One battery wanted	Air condistor Unit Removing & Cleaning ,Fitting vacum dust & Gas filling Labour charge	Head light bulb right side one number and parking lights bulbs abd wiper blades 2nos	Left side mirror ,wind shiled tinkering ,front door left side glass lefting meachine, driver seat question filling and staching ,rear door lock repair
106	AP16TH7765	TW	Guntur	1.Engine oil changing-7 Lts 2,Engine oil filters3.Fuel filters Air fiter change coolent change 3 liters,wall door package	Gear shifting lever bushing kit ,cluch master cylinder and cluch slave cylinder assembly anddrive saft	NIL	Break pads change 1 set &Break Liner ,Rear WC Asembly ,Oil seals, Grease Breaking system O/H and Pondary charges	Two Tyres wanted	One battery wanted	Air condistor Unit Removing & Cleaning ,Fitting vacum dust & Gas filling Labour charge	HL bulb right side one number and parking lights bulbs abd wiper blades 2nos	Wind Shiled tinkering,upholstory,rear view mirror ,right side door gas lefting meachine repairs ,rear door locks repairs
107	AP16TJ6883	TW	Guntur	1.Engine oil changing-7 Lts 2,Engine oil filters3.Fuel filters Air fiter change coolent change 3 liters,wall door package	NIL	NIL	NIL	Onr tyre wanted	NIL	Air condistor Unit Removing & Cleaning ,Fitting vacum dust & Gas filling Labour charge	Front cabin light replacement wiper blades	NIL

S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
108	AP16TH7990	TW	Guntur	1.Engine oil changing-7 Lts 2,Engine oil filters3.Fuel filters Air filter change coolant change 3 liters,wall door package	Drive shaft two numbers ,drive shift big bearing 2nos , small bearing 2nos and Labour charge and clutch cylinder assembly,clutch slave cylinder assembly replacement	Rear suspension system O/H	NIL	Three Tyres Wanted	One Battery Wanted	Air condistor Unit Removing & Cleaning ,Fitting vacuum dust & Gas filling Labour charge	Head lights beams and bulbs,pop lamps,wiper blades and horn	Right side mirror ,Front right side door lock repair ,supholstory Rear door hinges replacement , Rear door locks, front and rear bumper right side corner tinkering
109	AP16TJ6843	TW	Guntur	coolant change 3 liters,	Gear shifting lever bushing kit	Rear suspension system O/H	NIL	NIL	NIL	Air condistor Unit Removing & Cleaning ,Fitting vacuum dust & Gas filling Labour charge	NIL	Front both seat covers repair
110	AP16TH9660	F	Guntur	1.Engine oil changing-7 Lts 2,Engine oil filters3.Fuel filters 4. Raditor Hose pipes 1 set 3 Nos	Gear & Differational oil changes(4.5 Lts)	Strering system O/H,King pins, Bearing ,Grease ,poundary charges ,sims and Nipples	Breake pads change 1set & brake liners ,Rear WC Assembly ,Oil seals Grease Breaking system O/H and pondary charges	Tyre one number (spare)	NIL	Air condistor Unit Removing & Cleaning ,Fitting vacuum dust & Gas filling Labour charge	Rear parking Lights Assembly,Wiper Blades	Front Door Glass Lifting Mechine Repair,Front Cabin both Seats Repair
111	AP16TH9640	F	Guntur	FIP O/H,Replacement of Elements ,Delivery valves,Toothed quardrent , control soft , Radiator Hose pipes 1Set 3Nos and Hose pipes replacement,Wall door cover package	NIL	Strering system O/H,king pins, Blearing ,Grease ,poundary charges , sims and nipples,Rear springs Recambering	Break pads change 1 set &Break Liner ,Rear WC Assembly ,Oil seals, Grease Breaking system O/H and Pondary charges	5 Tyres Wanted	Invertor Battery	Air condistor Unit Removing & Cleaning ,Fitting vacuum dust & Gas filling Labour charge	Pilot cabin lights repair ,Minor Electrical Repair DCDF ,Wiper blades	Front Bamber tinkering &Show grill Replacement ,Front cabin both seats repairing &Rear locks repairs,Rear right side bumper tinkering
112	AP16TH9827	F	Guntur	1.Engine oil changing-7 Lts 2,Engine oil filters3.Fuel filters 4. Raditor Hose pipes 1 set 3 Nos 5.Raiator servicing and Hose pipes Replacement	NIL	NIL	Breake pads change 1set & brake liners ,Rear WC Assembly ,Oil seals Grease Breaking system O/H and pondary charges	NIL	One Battery not Working	NIL	NIL	NIL

S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
113	AP16TH8009	TW	Guntur	1.Engine oil changing-7Lts 2.Engine oil filter3.Fuel filter ,Air fiter change coolent change 3 liters, wall door package	Changing of gear oil & Diferational oil 4.5 liters ,power stering oil,replacement of drive shafts and ball joints	Rear suspension system O/H	Brake pads change 1set& brake liners.Rear WC assembly ,oil seals,Grease braking system O/H and pondary	Spare wheel & with disk and wheel alignement	One battery wanted	Air condistor Unit Removing & Cleaning ,Fitting vacum dust & Gas filling Labour charge	Both door lights repairs ,wiper blades ,orns ,fog lamps,self starter O/H	Right side view mirror,front bumper right corner tinkering ,front right side glass machine lefting repair
114	AP16TJ1448	F	Guntur	1.Engine oil changing-7 Lts 2,Engine oil filters3.Fuel filters 4. Raditor Hose pipes 1 set 3 Nos	NIL	NIL	Brake pads change 1set & Labour charge	Three Tyres Wanted	NIL	Compressor Gas ,Compressor valve ,filter ,condinsor chanel, Air condistor unit Removing & cleaning , Fitting vacum dust & Gas filling Labour charge	Wiper Blades,Parking lights DCDF,minior Electrical wiring	Rear Door locks Repairs &pilot seat Repair
115	AP16TH7854	TW	Guntur	1.Engine oil changing-7 Lts 2,Engine oil filters3.Fuel filters Air fiter change coolent change 3 liters,wall door package	Replacement cluach cylinder assembly and slave cylinder assembly, labour charge	Rear suspension system O/H	Breake pads change 1set & brake liners ,Rear WC Asembly ,Oil seals Grease Breaking system O/H and pondary charges	Two Tyres wanted	NIL	Air condistor Unit Removing & Cleaning ,Fitting vacum dust & Gas filling Labour charge	pilot cabin light & horns	Left door pach work,Supholstory and rear door lock repair
116	AP16TH9644	F	Guntur	Radiator Hose pipe 1 sets(3Nos) Air Filter Element	NIL	Rear Road springs Recambering ,Bushes snackle and 1-pin boards,Center Boards,Grease and Labour	Breake pads change 1set & brake liners ,rear WC Asembly , Oil seals Grease and pondary charges	Tyre one number (spare)	One Battery not Working	Compressor Gas ,Compressor valve ,filter ,condinsor chanel, Air condistor unit Removing & cleaning , Fitting vacum dust & Gas filling Labour charge	Head lights one number ,speedo meter cable wiper blades	Front door glass Liffing Mechine Repairs,Front cabin both Seats Repair
117	AP16TJ6832	TW	Guntur	Coolent change 3 liters,Wall door package	NIL	NIL	Breake pads change 1set & brake liners ,rear WC Asembly , Oil seals Grease and pondary charges	Two Tyres wanted	NIL	Air condistor Unit Removing & Cleaning ,Fitting vacum dust & Gas filling Labour charge	Horns repairs ,Wiper motor repair,Wiper blades 2nos,HL bulb(RH), Reverse Gear indicator bulb	Front door glass Liffing Mechine Repair,rear door glass repair ,rear foot board tinkering

S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
118	AP16TJ6880	TW	Guntur	1.Engine oil changing -7 Lts 2.Engine oil filters 3.Fuel Filters	NIL	NIL	NIL	Spare tyre with disk	NIL	Air condistor Unit Removing & Cleaning ,Fitting vacum dust & Gas filling Labour charge	Front both door lights	NIL
119	AP16TH7775	TW	Guntur	Radiator Hose pipes 1Set 3Nos,Hosr pipes Replacement, Wall door package replacement ,fan belt replacement	Drive shaft two numbers ,drive shift big bearing 2nos , sml bearing 2nos and Labour charge	Rear Road springs Recambering ,Bushes shackle and 1-pin boards,Center Boards,Grease and Labour	NIL	4 Tyres Wanted	NIL	NIL	Wiper blades 2nos,side indicators bulb,RH bulb	Wind Shiled frame tinkering ,Front both sides door lock repairs,rear door lock repair
120	AP16TH9633	F	Guntur	1.Engine oil changing-7 Lts 2,Engine oil filters3.Fuel filters 4. Raditor Hose pipes 1 set 3 Nos 5.Raiator servicing and Hose pipes Replacement	NIL	Strering system O/H,King pins, Bearing ,Grease ,poundary charges ,sims and Nipples,Rear springs Recambering	NIL	NIL	NIL	Air condistor Unit Removing & Cleaning ,Fitting vacum dust & Gas filling Labour charge	Pilot cabin lights repair ,Minor Electrical Repair DCDF	Front Bamber tinkering &Show grill Replacement ,Front cabin both seats repairing &Rear locks repairs,Rear right side bumber tinkering
121	AP16TH7760	TW	Guntur	1.Engine oil changing -7 Lts 2.Engine oil filters 3.Fuel filter Air fiter change coolent change 3 liters,wall door package ,adjest valve tapped clearance	Gear shifting leaver kit replacement with labour charge	Rear suspensson system O/H	Rear brake lings and hub gerasing	Two Tyres wanted	NIL	Air condistor Unit Removing & Cleaning ,Fitting vacum dust & Gas filling Labour charge	Frront cabin light ,reverse gear light indicator ,wiper blades&horns	Front both glass lifting repair ,pilot &emt seats repair ,seat cover straching ,rear bumper right side tinkaring
122	AP16TH9631	F	Guntur	1.Engine oil changing-7 Lts 2,Engine oil filters3.Fuel filters 4. Raditor Hose pipes 1 set 3 Nos	NIL	Rear suspension system O/H	NIL	Tyre one number (spare)	NIL	Air condistor Unit Removing & Cleaning ,Fitting vacum dust & Gas filling Labour charge	Wiper Blades,Team Guage Thermo plugs with wire DCDO 4members	Rear both Doors Hanges replacement & Door locks repairs ,Both seats chustions filling and sctaching
123	AP16TH7996	TW	Guntur	Air fiter change coolent change 3 liters,wall door package,Engine beads replacement	NIL	NIL	Breake pads change 1set & brake liners ,Rear WC Asembly ,Oil seals Grease Breaking system O/H and pondary charges	Two Tyres wanted	One battery wanted	Air condistor Unit Removing & Cleaning ,Fitting vacum dust & Gas filling Labour charge	Wiper baldes 2 no	Right side mirror,wind shield frame tinkering ,wind shield glass,Front door glass lefting mechine repair , Upholstory,Rear door lock repairs

S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
124	AP16TH7870	TW	Guntur	Engine oil pressure pipe replacement ,wall door packing replacement,Air fiter replacement	NIL	Rear suspensson system O/H ,ball joints	Breake pads change 1set & brake liners ,rear WC Asembly , Oil seals Grease braking system O/H and pondary charges	One tyres wanted	One battery wanted	Air condistor Unit Removing & Cleaning ,Fitting vacum dust & Gas filling Labour charge	Door lights repairs ,fog lamp wiper blades	Wind filed tinkering ,all door locks repairs
125	AP16TH7772	TW	Guntur	1.Engine oil changing -7 Lts 2.Engine oil filters 3.Fuel Filters,Air fiter change coolent change 3 liters, wall door package	Gear shifting liver bushing kit ,cluch master cylinder and cluch slave cylinder assembly and drive saft	Rear suspensson system O/H ,ball joints	NIL	One Battery wanted & Wheel alignment	NIL	Air condistor Unit Removing & Cleaning ,Fitting vacum dust & Gas filling Labour charge	Front cabin light replacement wiper blades	Both side view mirror ,front wind shield tinkering wiper arms and blades both side ,Upolostory front rigt side door lefting mechine repair rear door locks repair
126	AP16TH8004	TW	Guntur	1.Engine oil changing -7 Lts 2.Engine oil filters 3.Fuel Filters,Air fiter change coolent change 3 liters, wall door package	NIL	Ball joint replacement ,rear raod springs recambering	Hand brake repair	Three Tyres Wanted	One battery wanted	Air condistor Unit Removing & Cleaning ,Fitting vacum dust & Gas filling Labour charge	Door lights ,back left side parking assembly ,Fog lamp	Front bumper tinkering ,boanet lock repair ,rear bumper left corner repair,Upholstory
127	AP16TH7993	TW	Guntur	1.Engine oil changing -7 Lts 2.Engine oil filters 3.Fuel Filters,Air fiter change coolent change 3 liters, wall door package	NIL	Rear suspensson system O/H ,ball joints	NIL	Two Tyres wanted	NIL	Air condistor Unit Removing & Cleaning ,Fitting vacum dust & Gas filling Labour charge	Frront and rear indicators repairs ,parking lamps ,wiper blades,horn repair	Front door locks repairs ,front glass lefting repair ,front cabin seats repair, rear door lock repair
128	AP16TH7823	TW	Guntur	1.Engine oil changing -7 Lts 2.Engine oil filters 3.Fuel Filters,Air fiter change coolent change 3 liters, wall door package	Belt transiner & engine timming belt,changing of Gear oil& differational oil 4.5 liters, power stering oil	Rear suspensson system O/H ,ball joints ,front left spring coil replacement ,front tarsan bar	NIL	NIL	NIL	Air condistor Unit Removing & Cleaning ,Fitting vacum dust & Gas filling Labour charge	Front door light HL bulbs ,wiper blades	Front bumper tinkering & welding at center ,left side view mirrior ,front both side door lock repairs cabin seats repairs rear door lock repair
129	AP16TH7751	TW	Guntur	1.Engine oil changing -7 Lts 2.Engine oil filters 3.Fuel Filters,Air fiter change coolent change 3 liters, wall door package	NIL	Rear suspensson system O/H,Tyre rod ends and ball joints	Rear brake lings and hub gerasing	Spare tyre with disk	NIL	Air condistor Unit Removing & Cleaning ,Fitting vacum dust & Gas filling Labour charge	Front cabin light,Front left side parking lights ,fog lamps ,wiper blades	Wind shield frame tinkering ,front left side door locks repairs,rear door locks repairs and hings replacement

S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
130	AP16TJ0462	F	Krishna	Engine oil with filter changing ,Engine timing case oil seal and packing replace	Clutch mater cylinder and clutch slave cylinder replace	Suspension over hauling with tie rod ends replace and UJ cross new,centre joint bed with bearing new	Four wheels over hauling front brake discs and pads new replacement	Spare tyre 1.no	Inverter battery 1.no	NIL	Rear new indicator light Assys	Cabin seats striching,
131	AP16TJ0663	F	Krishna	Engine oil change ,engine oil filters change,diesel oil filter- 2.no,Air filter change, valve door packing change ,timing case gasket change,engine cleaning.	NIL	Front sides(both) spring leafs recambering and shackles and bushes replace,front torsion bar bushes replace,rear shock absorbers bushes replacement	Four wheels over hauling and front both sides discs and disc pads replacement	NIL	Battery 1.no(inverter)	NIL	All panel lights repalce,pilot cabin light replace head light reflectors replace, rear LHS and RHS brake lights replace ,wiper blades replace	Left side mirror replace ,front door right side lock replace ,cabin seats stiching
132	AP16TH9744	F	Krishna	Engine oil and filter replace,TC oil seal and packings replace.	NIL	Four wheels hub greasing ,suspension bush kit,tie rod ends,drag links end ,spring recambering	Brakes over hauling and four wheels hub grasing	Rear tyres 2.no 's,spare tyre 1.no	NIL	NIL	Speedo meter guage new,wiper motor new,emergency light bar new.PA systems repair	Seat rails new,cabin seat and EMT seat striching and tail door locks
133	AP16TH7646	TW	Krishna	Engine oil and filter change,engine timing belt changing ,timing case oil seal and packing replace, accelator cable replace.	Gear box oil seals and packing replace,clutch master and slave cylinder replace,clutch over hauling	Rear spring recamaring and suspention bushes and rear shock absorbers bushes and buffer beds replace.	Front and rear brakes over hauling and hub greasing ,drive shaft oil seals,bearing replace.	spare tyre new 1.no	Inverter battery new 1.no	AC over hauling gas filling and servicing	Full wiring rectification,head lights and tai lamps and parking lamps new changing ,wiper blade change,arms and wiper motor change	All doors locks repairs,pilots seat and co-pilot seat striching ,side view mirror replace,silencer welding ,front RH door glass regulator new
134	AP16TH8005	TW	Krishna	All oil seals and packings replacement,engine beds new	Clutch master cylinder and clutch slave cylinder kits ,gear box packing and oil seals new replace .and drive shaft oil seals new	Suspension over hauling -shock absorber bushes new ,Rear springs nrecambering with new shakils and I pins	Front both brake discs facing and pads new,rear brake liner new and drums foundry work	Tyres new 2 nos	New battery 1 no	AC gas filling and servicing	Front and rear parking lights replace ,pilots cabin light,rear number plate light replace ,wind shield shower motor ,emergency light bar,P/A ssystem repair ,blinkers LH,RH and rear flood light LH ,RH and rear ,exhaust fan,spot light and wall mounted fan	Front and rear door locks replace,pilot and co pilot seats stitching and EMT seat striching.

S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
135	AP16TH7674	TW	Krishna	Engine oil and filter replace ,diesel oil filters replace,engine all packings replace engine beds replace,timing belt new replace.	clutch master cylinder assembly and sleeve cylinder assembly replace	Rear road springs reambling and shake and bushes replace,front and back shack absorbers bushes replace ,ball joint new replace.	NIL	Tyre new 4.no	Battery 1.no	AC gas filling and servicing	Head light switches replace ,reverse indicators lights replace ,wiper blades replace,front rear parking lamps replace,rear number plate replace horns new replace battery terminals replace	All door locks in and out replace,pilot and co pilot seatscovers striching side mirror both sides replace.
136	AP16TH7658	TW	Krishna	Valve door packing ,valve door cap,engine oil changing with new filters, accelator cable changing , accelator pedal changing	Clutch master cylinder changing ,clutch slave ,clutch pedal boot, UJ cross ,differential oil seal and packing ,gear box differential oil change centre joint bed with bearing new	Rear roadsprings recambering ,shock absorbers bushes , balancing rod bushes changing	Front wheel bearing 4 new ,Hub greasing,master cylinder assembly new	3.no Tyres new	Battery's new 2.no's	A C Overhauling gas filling and servicing	Fans 2 nos and wiring rectification.Head lights bulbs changing , top lamps changing ,pilots cabin lights change	Front bonnet lock ,front LH door lock,Tail door RH lock and cabin seats stitching.
137	AP16TH9645	F	Krishna	All engine packings and oil seal replace	Gear box bush kit replace and gear box oil seals and packing repalce new	Suspension over hauling,king pins over hauling ,all bushes replace	Four wheels over hauling brake pads,caliper kits new replace and discs foundry work	spare tyre new 1.no	NIL	AC gas filling and servicing	Fuel gauge ,head lights holders replace ,front and rear indicators replace cabin electrical wiring rectification, rear number plate board replace.	Water shower motor replace,all doors locks repalce,front RH door glass regulator replace front LH glass regulator replace
138	AP16TH7768	TW	Krishna	All oil seals and packing replace	Clutch master cylinder and clutch salve cylinder assemblies replace,centre joint bed with bearing replace.	Suspension bush kit new replace	Drive shaft oil seals new replace,front wheel brakes over hauling and brake pads new replace ,caliper kit new, rear brake liners new and foundry work	Tyres 4 nos new	Nil	AC compressor over hauling gas filling and servicing	Front and rear parking lamps and rear number plate indicator lamp replace ,emmergency light bar ,AC DC charging sockets ,exhaust fans replace,P/A system repair.	Front door both sides door locks replace pilots and co pilot seats seats striching tail door locks replace

S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
139	AP16TH7671	TW	Krishna	Engine oil and filter replace ,diesel oil filter replace,engine oil filler cap replace,all packing and oil seals replace ,timing belt new replace	NIL	Suspension over hauling ,suspension bush kit new replace rear springs recambering and bal joints news and shackle asembly and l pins and centre bolts replace.	NIL	Spare tyre new 1.no	Inverter battery new 1.no	AC gas filling and servicing	Wiper blade replace ,indicator panel lights and pilot cabin light replace ,front and rear parking lights replace ,head lights reflectors ,horns ,brake,lights ,reverse gear indicators lights replace,rear number plate indicators and exhaust fan,AC DC Socket replace.	Front doors glass regulators replace .cabin seats covers striching and back door locks inner and outer replace .Accelerator cable new changing
140	AP16TH7642	TW	Krishna	All engine packings and oil seal replace	Gear box paking kit new replace	Suspension over hauling ,rear springs recambaring ,shock absorbers bushes ,tension and balancing rod bushes change ,tie rod ends, drive shaft ball bearing replace	Four wheels over hauling	tyre new 1.no	NIL	AC over hauling gas filling and servicing	Pilot cabin light and wiring rectification,front and rear parking lights ,panel indicators, wind shield shower motor ,alla lights and emergency light bar new ,public address system repair.fans new,horn new	All door locks and handles ,beading replace and cabin seats striching
141	AP16TH7638	TW	Krishna	Timing belt ,valve door packing ,engine beds change ,timing case oil seal and packings replace	Clutch master and slave cylinder replace ,differential oil seals and packing's replace	Suspension over hauling ,rear springs recambaring and bushes change,shock absorbers bushes change. Road spring buffer beds replace	Front drive shaft ball bearings replace	5.no's tyres and tubes replace	Inverter battery new 1.no	NIL	Wiring rectification and lights repairs ,wiper motor replace,AC DC sockets changing, External charging sockets,wiper blades and arms changing ,spot light replace	All doors locks repairs
142	AP16TJ0661	F	Krishna	Engine oil and filter change,diesel oil filters replace,sump nut replace ,all oil seals and packing replace.	Clutch pedal boot new gear box packing kit and oil seals replace	Suspension over hauling ,king pins bearings new and foundry work four road springs recambering and shaklls and l pins new replace,suspension bush kit new replace.	NIL	Tyres 4 nos new	NIL	AC gas filling and servicing	Speedo meter guage replace.instrucment panel indicator replace,front and rear parking lamps replace ,front and rear indicators,back lights replace,reverse gear indicator light,rear number plate lamp replace,wiper moter and wiper blades replace MSD swithes,wind shield fluid shower motor replace ,flood light RH and LH rear,exhaust fans replace,	Front both side door lock replace ,cabin seat covers replace,front bonnet lock replace ,front RHS door glass regulator,front LH door stopper,front LH door glass regulator
143	AP16TJ6906	TW	Krishna	Engine oil and filter change ,diesel oil filter 2.nos change,valve door packing replace ,engine oil seals and packing replace timing belt replace	Clutch over hauling ,differential oil seal and packings replace.	Front shock absorbers bushes replace,upper and lower arms bushes replace,rear road springs recambering with new shackles and l pins, rear shock absorbers bushes replace ,ball joint replace.	NIL	Spare tyre1.no	NIL	NIL	Front and rear parking lights replace ,fog lamps bulbs replace ,rear number plate bulbs replace ,wind shield glass shower motor and AC DC socket,flood light RH and LH and rear replace	Side view mirror replace ,front LHS door glass regulato replace



S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
144	AP16TJ1650	F	Krishna	Air filter replace	clutch pedal boot 1.no replace	Front and rear spring leafs recambering ,front shock absorbers bushes replace.	Hand brake repairs	NIL	NIL	NIL	Front and rear parking lights replace,RH side head lights,indicator lamps replace,wiper blades replace ,horns replace,speedo meter guge replace ,top lamp replace	NIL
145	AP16TJ6911	TW	Krishna	NIL	NIL	Suspension over hauling and suspension bushes all replace	NIL	NIL	NIL	AC gas filling and servicing	NIL	Rear door locks replace.
146	AP16TJ6920	TW	Krishna	Valve door gasket,timing belt engine oil filling cap,engine oil guage dip stick replace new	NIL	Front shock absorbers bushes ,torsion bar bushes,front upper lower arm bushes replace ,tie rod ends new replace,ball joint replaces	NIL	Spare tyre 1.no	NIL	NIL	Exhaust fans and wall mounting fans replace,front and rear parking lights new replace	Side view mirror RHS replace ,pilot co pilot seat covers stitching with new cloth ,EMT seat cover stricking
147	AP16TH7986	TW	Krishna	Engine oil and filter replace ,diesel filters replcae ,engine oil filter beds replace,drain nut replace, valve door packings replace.	Clutch master cylinder replace clutch slave cylinder replace ,centre joint bed with bearing new replace	Rear springs recambering and suspension bushes replace	NIL	NIL	Inverter battery new	AC gas filling and servicing	Front and back both doors lights replace ,pilots cabin light replace ,wind shield shower motor replace horns new replace side blinkers both sides snd switches replace ,exhaut fan replace ,cabin fan repalce.	LH side view mirror replace .front RH side door locks inner and outer replace ,pilot and co pilot seats stricking
148	AP16TH8008	TW	Krishna	All oil seals and packing replacement and timing belt replacement	Gear box packing replace, gear box front and rear oil seals replace	suspension over hauling	Master cylinder assembly replace	Front tyre 2.nos	NIL	AC blower moter replace and servicing	Panel indicator lamp replace ,front and back parking lights replace,front and rear indicator lamps replace, rear number plate lights replace,horns replace.batter terminals 2.nos replace.Back side blinkers replace,emergency light bar replace	Front left side door inner and outer locks replace ,pilot seat,co pilot seat stricking
149	AP16TH7643	TW	Krishna	Radiator upper and lower hose pipes replace,Engine oil drain nut replace , engine chamber gaskets and packing replace	NIL	Front shock absorbers and anti roller bushes ,tons bar bushes	Brake booster pipe new	Spare tyre1.no	Inverter battery 1.no	AC over hauling gas filling ,Blower fan motor new and servicing	Pilot cabin light replace,front and rear parking lights replace ,head lights replace , revers gear indication lights replace,rear number plate light replace ,wiper blade replace wind screen shower motor replace.	Front and rear door locks replace ,cabin seat repairs

S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
150	AP16TH7653	TW	Krishna	Engine oil and filter ,diesel filter,engine beds replace	Clutch master cylinder and slave cylinder replace,centre joint bed with bearing ,UJ cross replace.	Road springs recambering and shackles and bushes replace ,rear shock absorbers bushes replace, wheel alignment balancing rod bushes and clamps replace.	Drive shaft bearing replace ,Hub greasing	spare tyre1.no	Inverter battery 1.no	AC gas filling and servicing	Front and rear both side indicator replace,rear number plate indicator lamps replace,horns replace,wind shield flood shower motor replace,head lights reflectors Assemblies ,emergency light bay ,blinkers LHS and RHS ,flood light RHS and LHS and rear replace.	Pilot seat cover and co pilot seat cover new striching
151	AP16TH8006	TW	Krishna	All engine packings seals and oil seals replace.	clutch master cylinder assembly and slave cylinder assembly,clutch pedal boot centre joint bed with bearing ,UJ cross replace	Suspension over hauling ,Rear springs recambering withr new bushes shackle and I pins change	Drive shafts ball bearing replace	Five tyres new	NIL	AC gas filling and servicing	Front and rear parking lamps replace ,pilot cabin light replace ,front and rear side indicators LH and RH replace,rear number plate light replace horn replace ,head light assembly 2. nos replace, flood light RH and LH and rear replace ,emergency light bar ,exhaust fan ,spot lights wall mounting fans replace.	Front door lacks both sides replace ,front LH door glass regulator replace ,pilot and co pilot seats striching and tail door all locks replace.
152	AP16TJ0473	F	Krishna	Sump packing replace	Gear box oils seals and packings replace,gear shifting livers and bushes replace,clutch pedal boot replace, steering box oil seal replace,clutch over hauling.	Rear road springs fourth leaf broken and new leaf replace, spring recambering with shackles I pins, bushes and centre bolts replace	Hub greasing	NIL	Inverter batter 1.no	AC Gas filling and servicing	Wiper blades 2.no replace,front and rear panel indicators replace,horns replace rear light number plate light replace ,front and rear parking lamps assembly replace.	LHS mirror replace ,front RHS doors locks inner and outer replace ,cabin seat cover striching ,front LHS door glass regulator replace
153	AP16TH7994	TW	Krishna	Engine packing and oil seals replace.engine oil breather pipe new replace	Gear box packing kit replace ,gear box bush kit new replace(5th gear wheel)	Suspension bush kit new replace	NIL	Tyre new 1.no	NIL	AC over hauling and ac compressor over hauling gas filling and pipes new replace	Wind shield motor replace,parking lamps replace,emergency light bar new replace,spot light and wall mountain fans	Front door both sides doo locks replace pilot and co pilot seats stitching and speedometer cable new
154	AP16TJ0654	F	Krishna	Engine oil and filters and fuel filter changing,TC oil seals and packings and replace.	NIL	NIL	NIL	NIL	Inverter battery new 1.no	NIL	Fuel guage new,Instrument panel indication Lights,wind shield fluid shower motor new, Horn new,Exhaust fan and spot light new	All doors locks repairs,pilots seat and co-pilot seat striching ,side view mirror replace
155	AP16TH7757	TW	Krishna	Engine oil filler cap replace valve door gasket replace,engine breather pipe replace.	Clutch over hauling ,	Suspension over hauling and suspension bushes kit new replace ball joints new replace and wheel alignment	NIL	Tyre new 1.no	NIL	AC over hauling AC blower fan motor new gas filling and servicing	Panel indicator lamps and revers gear indicator lights and rear number plate light replace ,exhaust fan AC DC charging sockets ,tail lamps assembly	LH side mirror replace ,front door RHS glass regulator replace,pilot and co pilot seat covers stitching ,rear door lock handles new replace.

S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
156	AP16TJ6891	TW	Krishna	Engine oil and filter replace,diesel oil filters replace,engine oil filler cap new replace,	Clutch master cylinder assembly and clutch slave cylinder assembly ,gear box packing major kit raplace	NIL	NIL	Spare tyre new 1.no	NIL	AC Gas filling and servicing	Front and rear parking lights replace r ,rear number plate replace , all blinkers replace exhaust fan replace ,spot light,wall mountain fans raplace,orns new replace ,AC DC charging socket replace	Front and rear door locks replace ,pilot and co pilots seats stitching and EMT seat stitching
157	AP16TH7764	TW	Krishna	Engine oil filter cap replace, valve door packing replace,	Cutch master and clutch sleeve cylinder assembly new,gear box packing kit new replace	Suspension over hauling,front shock absorbers bushes replace,rear springs recambering with bushes and ball joints replace	NIL	Spare tyre new	NIL	AC Gas filling and servicing	Front and rear parking lamps replace dimmer switch replace ,fog lamps replace ,rear number plate light replace.	Front and rear door lock replace ,pilot and co pilot seats stiching with new cloth,speedo meter cable replace.
158	AP16TJ0452	F	Krishna	NIL	NIL	NIL	NIL	NIL	NIL	AC compressor over hauling ,gas filling and servicing	NIL	NIL
159	AP16TH7803	TW	Kurnool	rdiator O/H, coolant oil replacement	NIL	suspension bushkit, leafspring bushes replacement , front left shock absorber replacement.	Brake pads and Discs replacement ,rear wheels hubgreising	NIL	NIL	gasfilling,servicing	NIL	Tie rod ends replacement, door setting, rear door outer lock& key replacement
160	AP16TH9632	F	Kurnool	NIL	NIL	suspension bushkit,leafspring bushes replacement, king pin replacement ,one leaf spring replacement	Brake pads and discs replacement ,4 wheels hubgresing	2 batteries replacement	NIL	pipe replacement ,gas filling ,servicing	NIL	2 head lights replacement, tail lamps replacement , wiper blades and nozzles replacement
161	AP16TH7782	TW	Kurnool	engine oil changing ,air filter replacement	cluth assembly replacement	NIL	brake padsand front leaf bearing replacement,rear whell hubgresing	NIL	one battery replacement	gas filling required,a/c servicing,pipes cheku p	horn repair	NIL
162	AP16TH7801	TW	Kurnool	ENGINE OIL Changing	Gear oil changing,Front left drive shaft	NIL	Brake pads and Discs replacement	NIL	NIL	one battery replacement	Nil	Tie rod ends replacement
163	AP16TH9532	TW	Kurnool	Fan Belt replacement	NIL	supension bushkit,leafspring bushes replacement	Brake pads andDiscs replacement	NIL	NIL	GAS Filling &SERVICING	Horon replacement	NIL
164	AP16TH9890	F	Kurnool	Timing chain replacement	4th Gear repair	King pin replacement,leaf spring bushes replacement	Brake pads and Discs replacement	NIL	one battery replacement	gas filling required	NIL	NIL
165	AP16TH8130	TW	Kurnool	radiater OVERHAULING,FAN RELAYS REPLACEMENT,timing case leakage,filler cap, valve door packing replacement	NIL	suspension bushkit,Leafspring bhushes replacement	Brake pads replacement,rear whells Hub greising	NIL	NIL	Gas filling required,A/c pipes replacement.	Heater plugs replacement	NIL
166	AP16TH8418	TW	Kurnool	coolent oil change,radiator O/H engine oil change , valve door packing change	NIL	suspension bushkit,Leafspring bhushes replacement	Brake pads & liners replacement	NIL	NIL	GAS Filling &SERVICING	wiper blades replacement , horn repair	silencer cleaning, tie rod ends replacement ,doors & lock setting
167	AP16TH7756	TW	Kurnool	rdiator O/H, coolant oil replacement	cluth cable replacement	suspension bushkit,Leafspring bhushes replacement	Brake pads andDiscs replacement	NIL	NIL	GAS Filling &SERVICING compressor belt	nozzles replacement, fuse box replacement , tail lamp replacement , head lights repair	tie rod ends replacement ,doors &locks & hinges replacement
168	AP16TH1442	F	Kurnool	NIL	NIL	NIL	NIL	2 tyres replacement	NIL	NIL	NIL	NIL

S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
169	AP16TJ6834	TW	Kurnool	NIL	gear rod bush replacement , drive shaft repair	suspension bushkit,Leafspring bhushes replacement	brake pads and discs replacement , rear wheel hubgreising	4 tyres replacement	one battery replacement	GAS Filling &SERVICING	NIL	Tie rod ends replacement
170	AP16TH9656	F	Kurnool	radiator O/H	NIL	rear leaf spring recambering, leaf spring bushes replacement	Brake pads and Discs replacement	4 tyres replacement	NIL	AC pipes repair ,AC central switch replacement , gas filling	NIL	tie rodsends, rear door inside door & lock repair
171	AP16TH9533	TW	Kurnool	coolant oil replacement	Gear oil changing ,both Drive shaft repair	rear leaf spring recambering, leaf spring bushes replacement	Brake pads and Discs replacement	2 tyres replacement	NIL	GAS Filling &SERVICING	indicator light ,fog lamp,wiper blads, horn replacement	tie rod ends replacement
172	AP16TH7770	TW	Kurnool	radiator o/h ,engine beds replacement	TMC kit replacement,both drive shafts replacement	suspension bushkit,leaf spring bushes replacement	Brake pads and Discs replacement	NIL	NIL	GAS Filling &SERVICING	nozzles&wiper blades , horn replacement	tie rod ends replacement, doors hinges,lock repair, rear lock replacement
173	AP16TH7851	TW	Kurnool	coolant oil replacement ,engine oil cahange,crack oil seal replacement ,engine beds replacement	NIL	suspension bushkit,leaf spring bushes replacement	brake pads and discs replacement ,brake cylinder replacement	4 tyres replacement	NIL	GAS Filling &SERVICING	wiper blades replacement ,horn replacement,speedometer repair.minor electrical work	tie rod ends replacement ,ball joint replacement ,doors &lock setting, rear door lock
174	AP16TH7863	TW	Kurnool	timing case replacement	gear box synchroniser rings replacement ,drive shaft replacement	suspension bushkit,leaf spring bushes replacement	Brake pads andDiscs replacement	4 tyres replacement	NIL	GAS Filling &SERVICING	wiper blades replacement	tie rods ends replacement ,doors ,locks ,hings,regulator,rear door&lock repair
175	AP16TH7846	TW	Kurnool	engine oil changing	NIL	suspension bushkit,leaf spring bushes replacement	brake pads and discs replacement,cluth cable replacement	NIL	NIL	GAS Filling &SERVICING	NIL	tie rod ends replacement
176	AP16TH8421	TW	Kurnool	NIL	3rd gear repair	suspension bushkit,leaf spring bushes replacement	Brake pads andDiscs replacement	4 tyres replacement	NIL	GAS Filling &SERVICING	emergency light replacement	NIL
177	AP16TH7872	TW	Kurnool	engine oil changing	cluth assembly replacement	suspension bushkit,leaf spring bushes replacement	NIL	NIL	NIL	GAS Filling &SERVICING	NIL	tie rod ends replacement, door lock& key setting
178	AP16TH8121	TW	Kurnool	radiator O/H ,coolant oil replacement	cluth assembly replacement,front left drive shaft repair	suspension bushkit,leaf spring bushes replacement	Brake pads andDiscs replacement	2 tyres replacement	one battery replacement	GAS Filling &SERVICING	speedomere repair,wiper blades &nozzles replacement ,emergency light repair	top rod ends replacement ,front RH glass lifting mission repair
179	AP16TH7826	TW	Kurnool	radiator O/H, fan belt replacement	2nd gear,schronizers rings replacement	suspension bushkit,leaf spring bushes replacement	Brake pads andDiscs replacement	NIL	NIL	GAS Filling &SERVICING	speedometer repair,wiper blades &nozzles replacement, tail lamp replacement	doors& lock setting
180	AP16TH8120	TW	Kurnool	Fan Belt replacement,engine bed mounting replacement	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL
181	AP16TJ6850	TW	Kurnool	NIL	cluth assembly replacement	suspension bushkit,leaf spring bushes replacement	Brake pads replacement,rear whells Hub greising	4 tyres replacement	NIL	GAS Filling &SERVICING	minor electrical work	doors,locks,hingers setting
182	AP16TJ0450	F	Kurnool	NIL	cluth assembly replacement	NIL	Brake pads and discs replacement ,4 wheels hubgresing,brake liners replacement	4 tyres replacement	NIL	A/C belt replacement	NIL	Tie rods ends, drag link replacement, doors setting
183	AP16TH8353	TW	Kurnool	coolent oil change, engine hider bearing replacement	NIL	suspension bushkit,leaf spring bushes replacement,shock absorber replacement	Brake pads andDiscs replacement	NIL	NIL	GAS Filling &SERVICING	NIL	Tie rod ends replacement

S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
184	AP16TH8420	TW	Kurnool	NIL	NIL	NIL		4 tyres replacement	NIL	NIL	NIL	NIL
185	AP16TJ6836	TW	Kurnool	NIL	NIL	leaf spring bushes replacement		NIL	NIL	GAS Filling &SERVICING	NIL	NIL
186	AP16TH8661	TW	Nellore	Radiator Leakage	Nil	shock absorber bushes needs replacement	Nil	1 tyre reqd	Nil	Gas filling and overhaul	Emergency light bar, fans, fog lamps, blinkers, not working	window regulators, seat covers to be replaced running board damage toos
187	AP16TH7807	TW	Nellore	valve tappet cover leakage	Nil	suspension overhaul	NIL	Nil	1 battery required	Gas filling and overhaul	emergency light bar, blinkers, public address system,flood light,fans , etc not working	Wind screen frame rusting window regulator not working, fender RH and running board damages, LHS rear bumper corner piece not available etc.
188	AP16TH9634	F	Nellore	NIL	Nil	king in set ,tie rod ends replacement and others	brake liners replacement ,hand brake not working	3 tyres required	Nil	Gas filling ,blower ,pipelines,cleaning &overhaul	inverter,floodlights, door lights horn,charging sockets et not working	Door locks not working ,wash basin work ,etc.
189	AP16TH7864	TW	Nellore	NII	Drive shaft wornout	Struts &shock absorber bushes replacement	front wheel baring replacement	NIL	Nil	Gas filling and overhaul	selfstarter Oh, emergency light bar covers &blinkers damage, fog lamps not working etc	wind screen frame work ,LHS bumper damage ,door locks &glasss regulator machinrs not working , tools ,etc
190	AP16TH8427	TW	Nellore	Engine mountings to be replaced	2nd gear noise , drive shaft noise	suspension bush kit to be replaced , struts to be reconditioned	brake liners replaced	3 tyres required	Nil	Gas filling and overhaul	Fans,doorlights,foglamps,blinkers,flood lights,exhaustfan,etc.not working	RHS bumper damage , window regulator replacement,rear door stoppers ,tools,etc.
191	AP16TH8657	TW	Nellore	NIL	noise in 3rd gear	NIL	brake pads & liners to be replaced	3 tyres required	Nil	Gas filling and overhaul	horn,blinkers, parking lights, fog lamps not working .cabin light not available	tools
192	AP16TH8660	TW	Nellore	NIL	NIL	NIL	NIL	1 tyre required	Nil	Gas filling ,blower cleaning &OH	wiper motor , public address system , hooter , fog lamps,cabin light , charging sockets not working .charging cable not available	jack not working and other minor body repairs
193	AP16TH9650	F	Nellore	Engine oil, gear box , differential oils, filters to be replaced. Tappet cover leakage	NIL	kingpin set, tierod ends , drag link , front leaf spring (1) to be replaced . Rear leaf springs requires recambering	pads and liners to be replaced	NIL	1 battery required	Gas filling and overhaul	Fans , flood light not working	Door locks not working ,tools& others
194	AP16TJ6907	TW	Nellore	change engine , differential oils &filters	Drive shaft noise	NIL	NIL	1 tyre required	Nil	Nil	Blinkers not working	window regulators& door locks not working .oxegen door rusty.
195	AP16TH7761	TW	Nellore	NIL	Gear leaver play	suspension bush kit to be replaced , struts to be reconditione	break pads and liners be replacement	1 tyre required	Nil	Gas leakage , filters cleaning & overhaul	window regulator machine not working ,tools,etc	window regulator machine not working ,tools, etc
196	AP16TJ1450	F	Nellore	NIL	NIL	kingpin set, tierod ends , drag link to be replaced ,leaf springs recambering required	brake liners to be required	NII	Nil	NIL	emergency light bar , public address system not working .LHS rear indicator damage	doors locks not working ,tools and others
197	AP16TH7774	TW	Nellore	NIL	NIL	suspension bush kit replaced	break pads and liners to be replaced	2 tyres	Nil	gas filling ,filters & blower cleaning and others	self starter OH ,public address system ,hooter& fans not working	rear corner bumper not available

S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
198	AP16TH9538	TW	Nellore	valve tappet cover leakage	Steering box oil leakage	suspension bush kit to be replacement	pads and liners to be replaced	1 tyre required	Nil	Gasfilling, filters cleaning and overhaul	Emergency light bar ,public address system hooter ,inventor ,blinkers,flood lights, exhaust fan , fans ,charging sockets not working	wind screen frame denting , glass replacement ,running board damage, window regulator & door locks not working , seat repair
199	AP16TH8653	TW	Nellore	Roller bearing noise	NIL	recondition of struts& suspension bush kit replacement	Brake pads to be replaced .Hand break not working	5 new tyre required & wheel alignment	Nil	Gasfilling, filters cleaning and overhaul	wiper motor , public address system , flood lights , charging sockets not working . Hooter not available	Front bumper replacement ,door locks not working , tail door handle
200	AP16TH7641	TW	Nellore	NIL	Noise in second gear	tie rods end ,suspension bush kit to be replaced	liners to be replaced	3 tyres required	Nil	Gasfilling, filters cleaning and overhaul	blinkers not working ,hooters not available	wind screen frame rusted, window regulators not working , front LH door out side rusting
201	AP16TH9885	F	Nellore	NIL	NIL	king pin set replacement , front and rear springs recambering, minor front suspension work	NIL	2 tyres required	NIL	Gasfilling, filters cleaning and overhaul	fuel guage ,fans , instrument panel gauges not working , wiper blades and LHS indicators to be replaced Hooter not available	Door stopers not working .rear foot step repair& others
202	AP16TH7670	TW	Nellore	Change of engine oil, filters & differential oil change	steering oil leakage	suspension bush kit to be replaced	liners to be replaced	1 tyre required	2 batteries required	Gasfilling, filters cleaning and overhaul	wind screen glass to be replaced .window regulator machine replacement ,rear foot step denting, rear RH bumper corner not available, medical racks and rails not working	wind screen glass to be replaced. Window regulator machine replacement ,rear foot step denting, rear RH bumper corner not available, medical racks and rails not working
203	AP16TH7861	TW	Nellore	Change of engine oil&filters&Differential oils	steering oil leakage	suspension bush kit to be replaced	liners to be replaced	1 tyre required	2 batteries required	Gasfilling, filters cleaning and overhaul	Fuel meter & charging sockets not working .charging cable and hooter not available	wind screen glass to be replaced .window regulator machine replacement ,rear foot step denting, rear RH bumper corner not available
204	AP16TH9635	F	Nellore	Change of engine oil ,filters ,gearbox & differential oils	NIL	leaf spring recambering required and minor suspension work	liners to be replaced	NIL	Nil	NIL	Door light switches, public address system, flood lights, fans inventor and charging sockets not working	Front bumper assembly replacement and others
205	AP16TJ6897	TW	Nellore	Change of engine oil&filters&Differential oils	Nil	suspension bush kit replacement	pads and liners to be replaced	1 tyre required	Nil	NIL	flood lights not working & others	Window regulator machines not working , jack not working
206	AP16TH8434	TW	Nellore	NIL	Noise in second gear	suspension bush kit replacement	pads and liners to be replaced .Hand brake not working	NIL	Nil	Gas filling and overhaul	Selfstrater OH , Wiper blades replacement , emergency light bar, public address system ,blinkers,flood lights not working	wind screen frame rusty, glass replacement, window regulator machines replacement , seats repair and others
207	AP16TH9938	F	Nellore	change of engine oil&filters	4th gear not engaging	king pin set replacement leaf spring recambering and other suspension work	liners to be replaced	1 tyre required	1 battery required	Gas filling ,blowers, filters cleaning and overhaul	blinkers and flood lights not working < ss bendix drive slippage	fuel tank leakage, seat repair etc

S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
208	AP16TH7835	TW	Nellore	crank oil seal & sump packing leakage	steering hard & hose leakage	Front suspension overhaul & struts reconditioning	brake liners replacement	5 new tyres & wheel alignment	Nil	Nil	Emergency light bar, public address system, flood lights, reverse gear lights not working, wiper blades & combination switch needs replacement	Seat repair, door locks replacement etc.
209	AP16TH8436	TW	Nellore	NIL	NIL	front suspension overhaul	NIL	1 tyre require	Nil	Gas filling, filters cleaning and overhaul	fog lamps, flood lights, charging sockets not available	wind screen frame using
210	AP16TH7781	TW	Nellore	change of oils and filters. Valve cover gasket leakage	NIL	NIL	brake liners replacement	5 tyres & wheel alignment	1 battery required	Gas filling- filters cleaning and overhaul	inverter, indicators not working, emergency light bar replacement, wiper arm and blades, public address system, hooter not available, side view mirror damage	chassis bending, front bumper damage, front door and post bending, bumper bed not available & tools
211	AP16TJ6860	TW	Nellore	Requires engine major overhaul (vehicle at dealers workshop)	NIL	NIL	NIL	2 tyres	1 batteries required	Gas filling- filters cleaning and overhaul	NIL	NIL
212	AP16TJ0457	F	Chittoor	Not audited								
213	AP16TH8032	TW	Chittoor	Engine oil. Filters and air filter to be replacement	Oil leakage at gear box, power steering oil leakage	Suspension O/H (bush kit, tie rod ends and shock absorbers- 4 no's to be replaced)	4 wheels brakes O/H	2 tyres to be replaced	Inverter battery to be replaced	AC gas to be filled	Emergency light covers damaged. Brake light indicators both sides damaged and electrical minor repairs	Front bumper, front door locks (both sides) to be replaced. Front cabin seat cover to be replaced. Side wall-25% damaged
214	AP16TH8039	TW	Chittoor	Engine oil, filters and air filter to be replacement	Oil leakage at Gear box	Suspension O/H (bush kit, tie rod ends to be replaced)	Brakes O/H	4 tyres to be replaced	Nil	Nil	Electrical minor repairs	Front doors both sides inner locks to be replaced. Bumper & boynet painting to be done.
215	AP16TJ0474	F	Chittoor	Engine top O/H (oil enter into exhaust manifold)	Gear box O/H (2nd 3rd gear hard engage)	Suspension O/H (bush kit, center joint bed to be replaced)	Front wheel brakes O/H	2 tyres to be replaced	Nil	AC compressor belt and gas filling	Nil	Speedometer not working, Front cabins seat covers to be replaced
216	AP16TJ6912	TW	Chittoor	Engine top O/H (Oil consumption)	Gear box O/H (Clutch hard & Gear box, shift lever oil leakage)	Suspension O/H (bushkit & tie rod ends to be replaced)	Front brakes O/H	2 tyres to be replaced	Inverter battery not working	AC gas to be filled	Electrical minor repairs	Wind shield frame, side wall RH, front right side door completely damaged. Front cabin seat covers to be replaced, rear door stopper to be replaced
217	AP16TJ6905	TW	Chittoor	Engine oil and filters replacement, air filter replacement	Gear box oil leakage, clutch hard	Suspension O/H (bushkit & tie rod ends to be replacement, shock absorbers - 3no's (Front LH-1 and rear-2no's)	Nil	2 tyres to be replaced	Nil	Nil	Nil	Nil
218	AP16TH7748	TW	Chittoor	Oil leakage at engine, Inter coolant leakage FIP O/H (White smoke)	Gear box oil leakage and differential oil leakage	Suspension O/H (Bush kit, tie rod ends to be replaced)	Brakes O/H	Nil	Inverter battery not working	AC Gas to be replaced	Public address system and hooter not working. Wiper water motor, front indicator, side indicator and reverse light not working. Exhaust Fans 2 No.s not working	Door locks-2no.s not working. Pilot seat covers stitching and speedometer cable not working

S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
219	AP16TH7750	TW	Chittoor	Engine oil, filters and air filter to be replaced, valve door oil leakage	Oil leakage at gear box, clutch hard	Suspension O/H (bushkit, tie-rod ends to be replaced)	Nil	4 tyres to be replaced	Inverter battery to be replaced, inverter to be repaired	Nil	Fans-2nos, exhaust fan-1no not working. Emergency light left side not working and electrical minor repairs	Speedometer not working, front LH door damaged. Rear door inner and outer locks to be replaced. Front cabin seat covers to be replaced
220	AP16TJ0451	F	Chittoor	Engine oil, filters and air filter to be replaced, fuel filterbed to be replaced, FIP packing kit to be replaced	Oil leakage at gear box, clutch hard differential oil package	Suspension O/H (bush kit to be replaced, king pins O/H)	Nil	2 tyres to be replaced	Inventor battery to be replaced, inventor to be replaced	AC compressor problem	Electrical minor repairs	front door handlers - 2 Nos, seat cover, gear bumper corner LH side to be replaced show grill and silencer damaged
221	AP16TH9647	F	Chittoor	FIP O/H (Engine not taking pickup). Engine oil, filters and air filter to be replaced	Gear hard, oil leakage at gearbox and differential	Suspension O/H (bush kit, tie-rod ends and shock absorbers (front)-2no's to be replaced)	4 wheels brakes O/H	2 tyres to be replaced	Nil	Compressor not available & fan cowl damaged	Public address system, hooter not working and electrical minor repairs	Speedometer cable not working. Front doors RH&LH regulators, door locks (front and rear) to be replaced. Front cabin seat covers to be replaced. Rear door stopper bed-50% damaged. Wash basin not working
222	AP16TH9651	F	Chittoor	Engine oil filters and air filter to be replacement, coolant reserve tank damaged. Valve door & breather oil leakage	oil leakage at gear box, shift lever bush kit to be replaced	Suspension O/H (bush kit to be replaced, tie-rod ends to be replaced, center joint bed to be replaced)	Nil	2 tyres to be replaced	Invetor battery to be replaced	AC compressor problem	Fan - 1No not working, public address system not working and electrical minor repairs	Seat covers to be replaced front door locks (inner and outer), handles to be replaced
223	AP16TJ0471	F	Chittoor	Engine oil and filter replacement, oil leakage at valve door packing	Clutch hard	Suspension O/H (bush kit to be replaced front & rear shock absorber to be replaced)	brakes O/H	4 tyres to be replaced	Nil	AC gas to be filled	MP3 player not available and electrical minor repairs	speedometer not working, front LH inner lock, regulator to be replaced
224	AP16TH7811	TW	Chittoor	Engine oil, filters, air filter to be replaced	Shifting cover and gear box oil leakage, clutch hard	Suspension O/H (bush kit, tie-rod ends, draglink kit to be replaced)	Nil	4 tyres to be replaced	Nil	Nil	Public address system, hooter not working and electrical minor repairs	Front bumper-50% damaged, show grill-50% damaged, front wind shield frame-80% damaged, front LH door complete damaged. Rear door locks (inner and outer), stopper to be replaced
225	AP16TH8036	TW	Chittoor	Engine oil, filters and air filter to be replaced	Oil leakage at gear box	Suspension O/H (bush kit, tie-rod ends to be replaced)	Front wheels brakes O/H, wheel wearings	Nil	Nil	AC not working compressor problem	Nil	Seat covers to be replaced. Front LH inner lock RH outer lock to be replaced. Rear left side stopper to be replaced
226	AP16TJ6908	TW	Chittoor	Engine oil filters and air filter to be replacement	Oil leakage at gear box and shifting level, differential both sides axle play and oil leakage	Suspension O/H (bush kit, tie-rod end, draglink kit to be replaced)	Rear wheels brakes O/H	2 tyres to be replaced	Nil	AC gas to be filled	Electrical minor repairs	Diesel tank damaged front bumper 75% damaged, front LH door locks to be replaced, cabin ceiling 25% damaged, pilot seat cover to be replaced. Rear inner & outer locks to be replaced. Rear bumper corner piece-2 no's to be replaced



S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
227	AP16TH7812	TW	Chitoor	Timing case broken, valve door oil leakage. Engine oil filters to be replaced	Oil leakage at Gear box, clutch hard, differential oil leakage, noise and axle play.	Suspension O/H (bush kit, tie-rod ends to be replaced, Shock absorbers-2nos to be replaced)	Front wheel brakes O/H	2 tyres to be replaced	Invertor battery to be replaced, invertor repair.	AC gas to be filled	Exhaust fans-2 No's, Fan-2no not working and electrical minor repairs	Front doors both sides locks (inner&outer) to be replaced. Front cabin seat covers to be replaced.
228	AP16TH8042	TW	Chitoor	Engine oil filters and air filter to be replaced	Clutch hard oil leakage at gearbox	Suspension O/H (bush kit, tie-rod end to be replaced)	Nil	4 tyres to be replaced	Invertor battery to replaced	AC Compressor, condenser not working	Exhaust fans-2 No's, Fan-2no not working and electrical minor repairs	Front bumper to be replaced. Fenner-100% damaged. Front cabin seat covers to be replaced. Front foor regulators-2no's to be replaced. Rear door locks to be replaced.
229	AP16TH7680	TW	Chitoor	Engine O/H (heavy engine oil consumption, engine oil coming from beather)	Oil leakage at gear box	Suspension O/H(Bush kit, tie rod ends to be replaced shock absorbers-2no's to be replaced)	Rear brakes O/H	2 tyres to be replaced	Nil	AC not working due to compressor problem	Emergency light LH side damaged, fog lights, brake lights not working and electrical minor repairs	Speedometer to be replaced. Front cabin seat covers to be replacement. Rear door outer lock, stopper to be replaced.
230	AP16TH8347	TW	Chitoor	Engine O/H (black smoke & engine abnormal noise)	Oil leakage at gearbox and differential clurch hard. Differential abnormal noise	Suspension O/H (bush kit & tie rod end to be replaced)	Front wheels breaks O/H	2 tyres to be replaced	Invertor battery to be replaced	AC gas to be filled	Public address system, MP3 player, Wall clock, hooter not working. Exhaust fans 2no's not working and electrical minor repairs	Boynet lock not working and boynet 50% damaged. Cabin seat covers to be replaced. Foot boards patchwork to be done
231	AP16TH7809	TW	Chitoor	FIP O/H (white smoke coming), engine oil, air filters to be replaced	Oil leakage at gear box, clutch hard	Suspension O/H (Bush kit, tid-rod ends, shock absorbers to be replaced (rear)-2nos to be replaced)	4 wheels brakes O/H (Brake discs, pads linings, bearings to be replaced)	2 tyres to be replaced	Inverter battery to be replaced	AC not working due to compressor problem	Emergency light bat at one side, public addressing system not working, front side indicator fog lights, brake lights, wiper blades to be replaced.	Front and rear door locks to be replaced. Front wind shield frame, front bumper damaged. LH & RH front door regulators, front cabin seat covers to be replaced. Rear door glass broken. AC DC charger not working. LH door-50% damaged.
232	AP16TH7662	TW	Chitoor	FIP O/H (heavy white smoke)	Gear box O/H (2 nd gear hard engage,gare oil leakage)	Suspension o/h (bush kit to be replaced)	Front brakes O/H( Break disk has to be replaced)	2 tyres to be replaced	Invertor battery not available	AC compressor problem	Dynamo not working , Exhaust fans 2 no.s not working and electrical minor repairs	Front bumper, show grill, support grill and rear door lock to be replaced.Front cabin seat power to be replaced
233	AP16TH9536	TW	Chitoor	Engine O/H (Heavy black smoke coming from engine, engine oil enter into air filter)	Gear box O/H (2nd, 3rd gear hard engage, oil leakage), power steering hose pipes damaged	Suspension O/H (bush kit, tie rod ends to be replaced)	4 wheel brakes O/H	2 tyres to be replaced	Inverter battery not working	AC gas to be filled	Public address system, hooter not working and electrical minor repairs	Front doors both sides regulators, locks not working. Rear door lock not working. Front cabin seat covers to be replaced
234	AP16TH7665	TW	Chitoor	Engne O/H (Engine oil coming from breather, heavy block smoke)	Gear box O/H (Gear box abnormal sound oil leakage)	Suspension O/H (bushkit & tie rod ends to be replaced)	Front wheel brakes O/H	2 tyres to be replaced	Inverter battery to be replaced	AC not working (compressor problem)	Electrical minor repairs	Speedometer not working. Front bumper-100% damaged. Front cabin seat covers to be replaced. Rear foot step-75% damaged. Rear door locks, stopper to be replaced. Front door, side, wall LH&RH, front feeder piece (damaged) patchwork to be done.

S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
235	AP16TH7661	TW	Chittoor	Engine oil and filters to be replaced	Gear Box O/H gear hard engine and gear box both sides oil leakage	Suspension O/H (Bush kit and tie rod ends to be replaced and front RH shock absorber-1No.Replacement)	4 wheels brakes O/H	4 Tyres to be replaced	Nil	AC Compressor, fan, switch not working	Front indicators, 2 No.s fog light, 2.No.s water motor-1no fans -2 No.s not working	Front bumper replacement.Front centre piece and LH & RH side wall 25% damaged.Show grill, support grill complete damaged.Front RH & LH doors lock repairs and door settings and patch work.Front seat covers stiching.Front wind screen glass frame 75% damaged
236	AP16TH8000	TW	Chittoor	Nil	Oil leakage at gear box, shift lever and shift lever play	Suspension O/H (bush kit, tie rod ends to be replacement and shock absorbers -4no's replacement)	Front brakes O/H	2 tyres to be replaced	Nil	AC not working compressor problem and wiring problem	Nil	Front wind screen frame. 25% damaged. Front 2 door locks, door settings. Front cabin ceiling-50% damaged. Front seats and attendant seat stiching. Rear door stopper replacement. Rear foot door step, front LH door step
237	AP16TH7676	TW	Chittoor	Engine oil and filters replacement	Nil	Suspension O/H (bushkit replacement & front shock obsorber-1no replacement)	Brakes O/H	4 Tyres to be replaced	Inverter battery replace	AC condenser problem	Fog lights, bumper lights, blinkers not working and electrical minor repairs	Front right side door-75% damaged. Front seat covers stiching-speedometer cable replacement
238	AP16TJ6904	TW	Chittoor	Engine oil, filters & air filter to be replacement	Oil leakage at Gear box and gear shifting lever, clurch master cylinder oil leakage	Suspension O/H (Torison bar and bushes to be replaced. Left front shock absorber mounting crack to be weilding)	Nil	2 tyres to be replace	Inverter battery to be replace, Inverter repair	A/C not coming in body	Nil	Front cabin seat cover damage. Rear right side wall damaged. Rear right side stopper corner piece damaged
239	AP16TH7654	TW	Chittoor	Engine oil. Filters and air filter to be replacement	Oil leakage at gear box, shift lever and differential	Suspension O/H (bushkit, tie-rod ends to be replaced)	Nil	2 Tyres to be replaced	Inverter battery replaced	AC gas to be filled	Nil	Front wind shield frame-25% damaged, front LH door-25% damaged, rear doorlocks (inner and outer) to be replaced. Front cabin seat covers to be replaced
240	AP16TH9537	TW	Chittoor	Engine oil, filters and air filter to be replacement	Oil leakage at Gear box	Suspension O/H (bush kit to be replaced, tie rod ends to be replaced)	Brake pad to be replaced	4 Tyres to be replaced	Invertor battery to be replaced, invertor to be repaired	AC compressor not working	Exhaust fans-2 No's, Fan-1no not working and electrical minor repairs	Front wind shield frame-75% damaged. Front LH&RH inner locks to be replaced
241	AP16TH7640	TW	Chittoor	Engine oil filters and air filter to be replacement, timing belt to be replaced	Gear box both sides oil leakage, clutch hard	Suspension O/H (Bush kit to be replaced, front shock absorbers - 2 nos to be replaced)	Nil	4 Types to be replaced	Nil	AC gas to be filled	Emergency light damaged, exhaust fas 2 nos wall clock not working	front bumper - 25%, front wind shield frame - 75%, LH rear door - 50%, side wall RH - 50% damaged, front door regulators-2nos not working, copilot seat cover to be replaced
242	AP16TH7796	TW	Chittoor	Engine oil, filters and air filter to be replacement. Timing belt cover to be replaced	Oil breakage at gear box both sides. Differential both sides oil leakage, steering hose pipes damaged	Suspension O/H(Bush kit, tie rod ends to be replaced shock absorbers-2no's to be replaced)	Brakes O/H (brake pads, linings)	2 tyres to be replaced	Invertor battery to be replaced	AC not working due to compressor, fan, condenser problem	Public address system, hooter, MP3 player not working. Exhaust fans-2no's not working and electrical minor repairs	Speedometer not working. Support grill, show grill damaged. Front cabin seat covers to be replaced. Rear door locks to be replaced. Rear bumper corner-2no's to be replaced

S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
243	AP16TH8001	TW	Chittoor	Engine oil, filters and air filter to be replaced. Hose pipes to be replaced	Gear box O/H (abnormal sound in Gear box, clutch hard)	Suspension O/H (bushkit, tie-rod ends, drag link to be replaced. Shock absorbers-2 no's to be replaced)	Rear wheels brakes O/H	2 tyres to be replaced	Invertor battery not working	AC not working (fan motor, compressor not working)	Dynamo not working and electrical minor repairs	Front cabin seat covers to be replaced
244	AP16TJ0662	F	Chittoor	Engine oil and filter replacement	Nil	Suspension PH ( Bush kit to be replaced)	front brakes O/H	Nil	Nil	AC gas to be filled	fog lights, wiper blades, HL bulbs replacement and electrical minor repairs	Door lock repairs, boynet-25% damaged, front wind screen frame - 50% damaged, side RH & LH - 25 % damaged and pilot seat cover stitching
245	AP16TH8652	TW	Chittoor	Engine oil, filters and air filter to be replaced, valve cover oil leakage	Clutch hard, leakage at gear box	Suspension O/H (bush kit to be replaced)	4 wheels brakes O/H	2 tyres to be replaced	Nil	compressor problem lack of gas	emergency bas light not working fans - 3 nos not working, Spot light not working, LH side blinkers not working, temp gauge not working	LH side wall 25% damaged, front cabin seat covers to be replaced, rear LH corner piece to be replaced
246	AP16TJ0655	F	Chittoor	FIP O/H (Heavy white smoke coming from engine). Engine oil, filters to be replaced	Gear box O/H (3rd, 4th gear hard engage)	Suspension O/H (bush kit, king pins, center joint bed to be replaced)	4 wheels brakes O/H	Nil	4 wheels brakes O/H	AC not working due to compressor problem	Total wiring damage and electrical minor repairs	Front bumper-100% damaged. Front door locks to be replaced. Front door LH regulator to be replaced. Front cabin seat covers to be replaced. LH & RH mirrors to be replaced.
247	AP16TH8422	TW	Chittoor	Engine oil and filters, air filter to be replaced, valve door, crank front, engine chamber filter oil leakages, hose pipe inter cooling leakage	oil leakage at gear box and shaft gear, clutch hard	Suspension O/H (bush kit to be replaced, tie rod ends to be replaced)	Nil	4 tyres to be replaced	invertor battery to be replaced, invertor to be repaired	AC compressor not working	Electrical minor repairs	Front boynet-50% damaged. LH&RH front doors patchwork. Rear door locks, stopper to be replaced. Front door locks to be replaced. Right rear bumper corner-1no to be replaced. Front cabin seats stitching
248	AP16TH8426	TW	Chittoor	Engine oil filter, and air filter to be replaced. Wall door oil leakage, breather damaged. Turbo charge return pipe leakage	Nil	Suspension O/H (bush kit, tie-rod ends to be replaced)	Nil	2 tyres to be replaced	Invertor battery to be replaced	AC compressor not working	Nil	Front wind shield frame-25% damaged. Front bumper - 50% damaged. Front doors both sides 25% damaged. Cabin seat covers to be replaced. Rear door stopper to be replaced.
249	AP16TJ0472	F	Vizayanagaram	engine Oil filter cap leak and Valve cover Gas kit leak, engine oil drain plug leak, mount bed replacement	GB Shifting Lever is not working, clutch adjustment	Complete suspension OH	4 wheel brakes OH and hub greasing	Nil	1 New battery reqd	AC complete OH including compressor, Pipelines, Gas filling, Servicing, Filters	Fuel gauge, pilot cabin light, F and rear parking lights, Head light bulbs	pilot seat not working, Emergency siren damage
250	AP16TH8546	TW	Vizayanagaram	Engine oil filter cap leak and Valve cover gas kit leak, Engine oil drain plug leak	Clutch O/H	complete suspension OH/Shock absorbers	Nil	1 New Tyres with Tubes%	Nil	AC complete OH including compressor, Pipelines, Gas filling, Servicing, Filters	Self motor check, Electrical check up	front wind shield damaged, front right side door lock not working, pilot/copilot seats covers and stitching
251	AP16TH7754	TW	Vizayanagaram	Nil	GB O/H replacement of the gas kit, Packing kit	front suspension bush kit changing	4 wheel brakes OH and hub greasing	1 new tyre with tubes	Nil	AC gas filling, Servicing, Filters	Pilot cabin lights, front blinkers, signal lights	Front right side door lock and glass not working, pilot seat/copilot seats stitching and covers

S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
252	AP16TH9643	F	Vizayanagaram	Nil	Nil	Complete Suspension OH	4 wheel brakes OH and ub Greasing	1 new tyre with tubes	Nil	Gas filling, Pipes check, Servicing, Filters	all signal lights, fuel guage, odometer charges	Front and back door locks, Emergency siren not working
253	AP16TH8433	TW	Vizayanagaram	Engine oil filter cap leak and volve cover gas kit leak, engine oil drain plug leak	GB O/H, Clutch OH	Complete suspension OH	Nil	2 new tyres with tubes	Nil	AC Gas filling, Servicing, Filters charging	Nil	Front wind shield night visibility poor
254	AP16TJ6853	TW	Vizayanagaram	Engine oil filter cap leak and volve cover gas kit leak, engine oil drain plug leak	Clutch O/H	Complete suspension OH	4 wheel brakes OH and hub greasing with cylinders	2 new tyres with tubes	Nil	AC complete OH including compressor, Pipelines, Gas filling, Servicing, Filters	Starter OH, Head light lamps, danger lights replacement	Front Bumper, front wind shield glass, Pilot, Copilot seat
255	AP16TH9830	F	Vizayanagaram	Engine Oil leak and Engine mount beds replacement	GB O/H, Cluch O/H, 4th Gear wheel replacement and Synchronising	Complete suspension OH	Brake liner change	Nil	1 New Battery Reqd	Nil	Self Motor check. Stater and Dynamo O/H, Bulbs, side Blinkers, Danger replacements	Fender L/H Forewall L/H damaged rusted, Frond and Rear Door Locks, Rear Foot test
256	AP16TH7862	TW	Vizayanagaram	Engine oil leakage	Nil	Complete suspension OH	4 wheel brakes OH and hub greasing	4 New Tyres with Tubes	1 new battry Reqd	AC complete OH including compressor, Pipelines, Gas filling, Servicing, Filters	frint cabin lights, rear, danger lights, high beam not working	Nil
257	AP16TJ6840	TW	Vizayanagaram	Engine oil filter gap, leak and volve cover gas kit leak, engine oil drain plug leak	Clutch repair	Complete suspension OH	4 Wheel brakes OH and hub greasing	Nil	Nil	Gas filling, Pipes check, Servicing, Filters	front both danger lights, parking lights, head lights	rear foot step not working
258	AP16TH8432	TW	Vizayanagaram	Engine oil filter cap leak and volve cover gas kit leak, Engine oil drain plug, leak, timing gear oil seal replacement, crank case packing, mount beds	Nil	Front suspension O/H	4 wheel brakes OH and hub greasing	2 new tyres with tubes	Nil	AC complete OH including compressor, Pipelines, Gas filling, Servicing, Filters	Pilot cabin lights, Danger light, filters	Front wind shield replacement, front R/S door lock, rear foot step damaged. Front roof water leakage
259	AP16TH8423	TW	Vizayanagaram	Engine oil filter cap leak and Volve cover gas kit leak, Engine oil drain plug leak	GB oil leakage/Yoke and teeth Replacement, OH	Complete suspension OH	Brakes O/H charges	4 New Tyres with Tubes	Nil	AC complete OH including compressor, Pipelines, Gas filling, Servicing, Filters	Monor, HL Reflectors, Bulbs, Odometer charges	Front Bumper Damaged, Pilot/Copilot seat covers and Stiching, Emergency siron bars lights not working
260	AP16TJ1649	F	Vizayanagaram	Engine oil leakage, Turbo charges kit replacement, Engine mount beds replacement	Nil	Complete suspension OH	4 wheel brakes OH and hub greasing	Nil	Nil	AC complete OH including compressor, Pipelines, Gas filling, Servicing, Filters	Both side danger lights, Pilot cabin lights, Head lights replacement	Back Door Foot step, Pilot seat not working, Emergency Siren complaint
261	AP16TH7834	TW	Vizayanagaram	Nil	Nil	Complete Suspension OH	4 Wheel brakes OH and hub greasing	Nil	1 New Battery Reqd	AC Gas Filling, Pipes check, Servicig Filters changing	Minor Charges	Front left side door locks, Pilot/Copilot seats covers/Stiching
262	AP16TJ6915	TW	Vizayanagaram	Nil	Gear shifting lever, cable replacement	Complete Suspension OH	4 wheel brakes OH and hub greasing	1 New tyres with tubes	1 new battry Reqd	Nil	Nil	Nil
263	AP16TH7831	TW	Vizayanagaram	Engine oil leakage	GB complete O/H, Clutch O/H	Complete Suspension OH	Nil	1 New Tyres with Tubes	1 New Battery reqd	Gas filling/Pipes check/ Condensor/Blower/Repairs/Servicing/Filters	Door, Danger, Parking, Head light replacement and sself starter	Front bumper damaged, wind Shild main glass and Beedings, emergency light not Working
264	AP16TH7850	TW	Vizayanagaram	Engine oil filter cap leak and Volve cover gas kit leak, Engine oil drain plug leak	GB OH, Replacement of 2nd gear wheel and synchronising assly	Bushkit Replacement	4 Whee brakes OH and hub greasing/MC assly	2 new tyres with tubes	1 battry is reud	AC complete OH including compressor, Pipelines, Gas filling, Servicing, Filters	Monor, F and R parking Lights, Blinkers	Gront bumper damaged, front L/R Door Locks and glasses change, Pilot/copilot seats damaged, Emergency siren not working

S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
265	AP16TH9883	F	Vizayanagaram	Engine Condition Good	Gear Box O/H, Clutch O/H	Complete suspension OH including wheel leave springs recambering	4 wheel brakes OH and hub greasing/replacement of brake liner and kits	Nil	Nil	AC complete OH including compressor, Pipelines, Gas filling, Servicing, Filters	Minor Charges	Front wind shield class, front door lock and glass, front foot rest rusted
266	AP16TH8035	TW	Prakasam	Engine oil damage	Nil	Clutch and bushes repair	Break adjustment	4 Tyres	1 Battery	Gas filling, servicing	Brake light, indicator lights, switches, wiring checkup	Seats, door locks
267	AP16TH7987	TW	Prakasam	Engine oil & cooling system change	Cluth repair	Stock replacement, oil leakage	Break pads reqd.	4 Tyres	1 Battery	AC Compressor, gas filling, servicing,	Indicator lights	Seats, door locks
268	AP16TH7664	TW	Prakasam	Engine oil change	1st and 3rd gear problem, clutch repair	Stocks obsobers, bushes kit replacement	Break adjustment	5 Tyres	1 Battery	AC Compressor belt, gas filling, servicing,	Fuel Gauge not working, pilot cabin light problem, front and rear parking lights	Doors, seats, Dents
269	AP16TH9642	F	Prakasam	Engine oil damage, coolest pipe broken	Nil	Stocks obsobers, bushes kit replacement	Break adjustment	5 Tyres	1 Battery	Nil	Rear indicator assembly	Doors, seats, Dents
270	AP16TJ6914	TW	Prakasam	Connection joint engine oil leakage	oil leakage from drive shaft	steering oil	Break adjustment	4 Tyres	Nil	Nil	Electrical check up	Seats, door locks repair
271	AP16TH8361	TW	Prakasam	Engine oil damage	Cluth repair	Stock replacement, oil leakage	Break adjustment	5 Tyres	2 Batteries	Gas filling, servicing	Hand lights not working	glass lifters, door locks
272	AP16TH9535	TW	Prakasam	Engine oil damage	Gear oil changing and oil check ups	Clutch repair	Break adjustment	5 Tyres	1 Battery	Gas leakage	Brake light, indicator lights	Seats, doors, lifters handles repair
273	AP16TH8354	TW	Prakasam	Engine oil damage	Clutch hard	Stocks repair & bush damage	Break pads reqd.	5 Tyres	1 Battery	AC Compressor, gas filling, servicing	Horns, back lights, reverse lights	Seats, Doors, Left window, right window glasses
274	AP16TH7984	TW	Prakasam	Engine oil damage, coolest pipe broken	Drive shaft oil change	Stocks & bush kits replacement	Break liners replacement	4 Tyres	1 Battery	AC Compressor, gas filling, servicing	wiper motor indicator assemblies	Seat works, doors and handles
275	AP16TH7746	TW	Prakasam	Engine oil damage	4th gear engine repair	Stocks repair & bush damage	Break adjustment	3 Tyres	1 Battery	AC Compressor, gas filling, servicing, filters	Alternator not working, Reverse gear indication lights problem	Seat door repair
276	AP16TH8544	TW	Prakasam	Engine oil change	Clutch adjustment	Stock & bushes Kit repair	Break adjustment	5 Tyres	2 Batteries	AC Compressor, gas filling, servicing,	Broken lights, wiper, horn	Door, Seats, Dents
277	AP16TJ1443	F	Prakasam	Engine oil change	3rd gear adjustment	Clutch bush broken lever spring	Break pads adjustment	5 Tyres	1 Battery	belt loose adjustment	Lights and wind shield shower repair	Doors, seats, Dents
278	AP16TH8548	TW	Prakasam	Engine oil change	Clutch repair	Stock & bushes Kit repair	Break booster assembly	3 Tyres	2 Batteries	Gas filling, servicing	Horns, Bulbs	Seats, Dents, Doors, Handles
279	AP16TH8360	TW	Prakasam	Engine oil change	Clutch assembling	steering oil	Break adjustment	2 Tyres	1 Battery	Nil	Cabin lights, signal lights	Seats repair, handles, Dents
280	AP16TH7650	TW	Prakasam	Engine oil changing	Nil	Stock replacement, bushes replacement	Break adjustment	2 Tyres	1 Battery	Nil	Self motor problem, fog lamps not working	doors, seats repairs, glass lifters
281	AP16TH8550	TW	Prakasam	Engine oil & cooling system change	Clutch repair	Front stock obsorbes to be replaced	Break pads repair	4 Tyres	1 Battery	Gas filling, servicing	Indicator assemblers, N/W	Seats doors and handles
282	AP16TH8002	TW	Prakasam	Engine oil changing	Drive shaft repair & clutch pad hard	Stockles and steering oil	Breaks adjustment	2 Tyres	1 Battery	Compressor, gas filling, servicing	Horns, lights, reverse lights	seat repairs, door handles, glass lifters, door locks
283	AP16TH7829	TW	Prakasam	Engine oil changing	Drive shaft changing	stock replacement	Adjustment	4 Tyres	2 Batteries	Gas filling, servicing	Wiper blades, reverse gear indicators	Seat repairs, glass channels, door locks
284	AP16TH7991	TW	Prakasam	Engine oil & cooling system change	Nil	All bushes replacement, stock obsobers 2 no.s	Breaks adjustment	2 Tyres	1 Battery	Gas leakage, Servicing	Key problem, laptops not working, complete electrical checkup	Seats, doors repair
285	AP16TJ6893	TW	Prakasam	Engine oil changing	3rd gear problem	Nil	Breaks adjustment	4 Tyres	1 Battery	Gas filling, servicing	Indicators not working	seat covers & handles repair
286	AP16TH7833	TW	Prakasam	Engine oil changing & leakage	Clutch problem, drive shaft problem	Front stock obsorbes & bushes to be replaced	Cylinder leakage and wires/cylinder replacement	2 Tyres	1 Battery	AC Compressor, gas filling, servicing, filters	Heater plugs replacement, hand light assembling	seat covers, door & handles

S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
287	AP16TH9934	F	Prakasam	Engine Oil leakage from valve cover, rectifing of oil leakage	Gear Box Front and Rear leakage, Front UJ cross damaged	Front stockles, spenser and bushes 4 No.s, Front shock absorbers and bushes	Brake adjustment and break oil filling	2 Tyres	1 Battery	Gas filling, servicing, filters change	Complete electrical checkup	Up holstry & door repairs
288	AP16TJ6890	TW	Prakasam	Engine oil changing	Draft shaft oil replacement	NILL	Breaks adjustment	4 Tyres	1 Battery	Gas filling & servicing	Wind field shower lights	Seat covers and door knobs
289	AP16TH9652	F	Prakasam	Engine oil damage and cooling system problem	Gear Box Front and Rear leakage, Front UJ cross damaged	Bushes replacement, bearing damaged	Break oil change and adjustment	5 Tyres	1 Battery	Gas filling check up	Speed meter, door light, cabin light	Doors, seats small dents
290	AP16TH6881	TW	Srikakulam	Nil	Nil	Complete suspension OH	4 wheel brakes OH and hub Greasing	2 New tyres with Tubes	Nil	Low cooling, Pipe check up and gas filling, Servicing, Filter Changing	Nil	Emergency Siron lights check up changing
291	AP16TH7742	TW	Srikakulam	Engine Oil Filter Cap leak, Air Filters Changing	Gear box Bush changing and cluth O/H and 2nd Gear Slipping Charges	Complete suspension OH	Nil	Nil	Nil	Complete Pipes Check up wiring and gas filling and filters, servicing, compressor checkup	Headlamps Changing, Wiring Check up and other Bulbs	Front Left and Right Door Locks, Backside Door Repair, Emergency Siron and Lights not working and Minor Tinkering
292	AP16TH7853	TW	Srikakulam	Volve Cover Gas Leak, Eoil Chamber Leak, Engine oil Drain Plug Leak and Turbe Charger	Clutch Cylinder Assly, Clutch Sleeve Cylinder, Gear lever Bush Kit Changing, Drive Shaft Oil Leak	Complete suspension OH	4 wheel brakes OH and hub Greasing	Nil	1 New Battery Required	AC Compressor, Gas Filling, Pipes Changing, Filters, Servicing	Front Headlight Reflectors Changing, Ignition Switch Change and Electrical Check	Rear Bumper Corner damaged reqs welding and minor Tinkering
293	AP16TH7865	TW	Srikakulam	Nil	Gear lever Gasket Changing, Clutch O/H	Complete suspension OH	Nil	Nil	Nil	AC complete check up includes compressor, Pipelines, Servicing, Gasfilling Filters	Self Motor Check, Head Lights Changing	Front wind glass broken, Frame Rusted, Front and Rear Door locks repairs, Pilot seats stiching, Back Foot rest repair and other Minor Repairs
294	AP16TH8348	TW	Srikakulam	Valve Cover Gasket Leak, Crank Front Seal Leak, Engine oil drain plug leakage	Nil	Complete suspension OH	4 wheel brakes OH and hub Greasing	4 New Tyres with Tubes	2 New Batteries required	AC complete check up includes compressor, Pipelines, Servicing, Gasfilling Filters	Nil	Emergency Light Siren not working
295	AP16TH8428	TW	Srikakulam	Engine Oil Filter Cap Leak and Volve cover Gas Kit Leak, Engine Oil Drain Plug Leak	2nd Gear Hard	Complete suspension OH	4 wheel brakes OH and hub Greasing	4 New Tyres with Tubes	Nil	Nil	Electrical check up F/R Indicators assly changing	Rear Door Lock Repair, Pilot Seat Repair, Backside Foot Rest Repair and Minor Patch work
296	AP16TH8430	TW	Srikakulam	Nil	Clutch Sleeve Assly Changing, GB Front and Rear Leakage and GB Top Leakage, GB O/H	Complete suspension OH	4 wheel brakes OH and hub Greasing	2 New tyres with Tubes	1 New Battery Required	AC complete check up includes compressor, Pipelines, Servicing, Gasfilling Filters	Nil	Front Door Locks Repairs and Replacements
297	AP16TH8547	TW	Srikakulam	Nil	Clutch O/H Clutch Cylinder and Sleeve Changing Gear Lever Hard	Nil	Nil	Nil	1 Battery	AC Gas Filling, Total Pipes Check up and wiring, Servicing, Compressor Check, Filters	Nil	Front wind shield frame rusted, Front Left and Right Door Locks Repairs, Pilot seat covers replacement, Emergency Siron and Light Wiring Repairs
298	AP16TH8654	TW	Srikakulam	Engine Oil Filter Cap Leak and Volve cover Gas Kit Leak, Engine Oil Drain Plug Leak	Clutch Sleeve Assly Changing, GB Front and Rear Leakage and GB Top Leakage	Complete suspension OH	4 wheel brakes OH and hub Greasing	4 New Tyres with Tubes	1 New Battery Required	Gas filling/pipes check/servicing/filters	Self Motor Check, Odometer Changing, Electrical Check up	Front wind shied frame rusted, Front Left and Right Door Locks Repairs
299	AP16TH9653	F	Srikakulam	Valve Cover Gasket Leak, Crank Front Seal Leak, Timing case Leak	Clutch Sleeve Cylinder change, Center Joint with Boot Changing	Overhauling of Suspension	Four Wheel Brakes Overhauling and upgreasing	4 New Tyres with Tubes	New Battery	AC Gas Filling, Total Pipes Check up and Servicing	Self Motor Checkup and wiring Check and Bulbs changing	Rear Doors Locks not working, Emergency Siron and Lights not working other Minor Tinkering

S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
300	AP16TH9884	F	Srikakulam	Engine Oil Filter Cap Leak and Valve cover Gas Kit Leak, Engine Oil Drain Plug Leak, FIP and Nozzle OH	Gear box O/H	Complete suspension OH	4 wheel brakes OH and hub Greasing	Nil	Nil	AC complete check up includes compressor, Pipelines, Servicing, Gasfilling Filters	Nil	Rear Doors Locks not working
301	AP16TH9935	F	Srikakulam	Valve Cover Gasket Leak, Crank Front Seal Leak, Timing case Leak	Nil	Complete suspension OH	4 wheel brakes OH and hub Greasing	Nil	Nil	Complete Check up gas filling and wiring check up, filters, pipes, compressor checkup	Complete Wiring check up	Emergency Siron bar and lights not working
302	AP16TJ0464	F	Srikakulam	Engine Top O/H, FIP and Nozzles O/H	Gbox O/H, Cylinders changing	Complete suspension OH	4 Wheel Brakes OH and hub greasing	Nil	1 battery required	AC complete check up includes compressor, Pipelines, Servicing, Gasfilling Filters	Complete electrical checkup	All door locks repair and minor tinkering
303	AP16TJ0470	F	Srikakulam	Engine Oil Leaks, Oil Pipe Chamber Leaks	Gear Box Clutch Sleeve Cylinder Changine, Cluch O/H	Complete suspension OH	4 wheel brakes OH and hub Greasing	Nil	Nil	AC complete check up includes compressor, Pipelines, Servicing, Gasfilling Filters	Nil	Emergency Siron not Rolling and Check
304	AP16TJ1642	F	Srikakulam	Valve Cover Gasket Leak, Crank Front Seal Leak, Timing case Leak	Nil	Overhauling required	4 wheel brakes OH and hub Greasing	4 New Tyres with Tubes	2 New Batteries required	Complete Check up gas filling and wiring check up, filters, pipes, compressor checkup	Front and Rear Parking Lights, Head lights changing, Odo meter Cable Changing	Front Door Locks Repairs, Emergency siron with Lights not working and other minor tinkering
305	AP16TJ6862	TW	Srikakulam	Nil	Nil	Complete suspension OH	Nil	2 New tyres with Tubes	Nil	Nil	Front Hlights Assly change, Wiring Check up	Front wind shield frame rusted, Front wind glass broken.Minor welding and Tinkering
306	AP16TJ6864	TW	Srikakulam	Nil	Nil	Complete suspension OH	4 wheel brakes OH and hub Greasing	4 New Tyres with Tubes	Nil	AC complete check up includes compressor, Pipelines, Servicing, Gasfilling Filters	Nil	No other repairs
307	AP16TJ6901	TW	Srikakulam	Nil	Nil	Complete suspension OH	Nil	Nil	Nil	Nil	Complete Wiring check up and bulbs changing	Emergency Siron not working
308	AP16TH7813	TW	Visakapatnam	Nil	Clutch Overhauling	Suspension Overhauling	4 Wheel brakes OH to replace brake liners and wheel cylinders	4 Tyres with Tubes	Nil	AC not working, Gas filling, wiring changing, Pipes, Servicing and Filters	Parking lights, Horn repair and danger light bulb	Body bedbolts, support beds, Backside Door Locks, Emergency Siren, Minor Patch work
309	AP16TH7780	TW	Visakapatnam	Engine oil filter cap leak, engine breather leak, crank front seal leakages, turbo charger leakages	Nil	Suspension Overhauling	Nil	2 Tyres	1 Battery	AC complete OH compressor, Pipelines, Servicing, Gasfilling Filters	Self Motor bendex problem, front both doors lights swithches problem, pilot cabin light problem	Front Bumber Damage, Front two doors not working, backside Door Locks and Foot rest welding, Minor patch work and emergency Siren
310	AP16TH7985	TW	Visakapatnam	Nil	Nil	Suspension Overhauling	Nil	4 Tyres with Tubes	Nil	AC complete OH compressor, Pipelines, Servicing, Gasfilling Filters	Self motor and wiring chekup	Bar light broken, Rear door lock not working, handle broken
311	AP16TH8662	TW	Visakapatnam	Nil	Nil	Suspension Overhauling	Nil	4 Tyres with Tubes	Nil	Compressor air leakage check pipeleak check, servicing, gas filling	Front and Rear parking lights assemblies, fog lamp not working, front and rear side indicators not working	Front locks not working, rear door rusted, Minor patch works
312	AP16TH7804	TW	Visakapatnam	Engine oil filter cap leak, valve cover gasket leak, engine oil chamber leak	Nil	Suspension Overhauling	2 Batteries	30%	2 Batteries	Total AC Check, Pipelines, Gas leakage, Filters, Compressor, Blower check	Fuel Gauge not working, pilot cabin light problem, front and rear parking lights	Backside Door Locks and handle broken, Minor Patch work

S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
313	AP16TH9886	F	Visakapatnam	engine oil filter cap leak, crank front seal leak	Nil	Suspension Overhauling	Nil	4 Tyres with Tubes	Nil	AC complete OH compressor, Pipelines, Servicing, Gasfilling Filters	Pilot cabin light, front both door light switches	Front door locks repairs and other minor patch works
314	AP16TH7762	TW	Visakapatnam	Engine oil leak, engine filter cap leak, valve cover gasket leak, engine oil chamber leak	Gear box top leak, gear box front and rear leak	Suspension Overhauling	Nil	1 Tyre	Nil	AC Servicing, Gas filling, Pipes, Filters Changing Repairs	Front and Rear Parking Lights, other minor electrical repairs	Backside Door Locks handle and Foot rest welding, Minor patch work
315	AP16TH7773	TW	Visakapatnam	Engine oil leak, engine filter cap leak, valve cover gasket leak, engine oil chamber leak, engine oil drain plug leak, timing case leaks	Gear box top leak, gear box front and rear leak	Suspension Overhauling	Brakes Overhauling	4 Tyres with Tubes	1 Battery	AC complete OH compressor, Pipelines, Servicing, Gasfilling Filters	Alternator not working, Reverse gear indication lights problem	Backside Door Locks , Minor patch work and Emergency Siren
316	AP16TJ6863	TW	Visakapatnam	Nil	Nil	Suspension Overhauling	4 wheel brakes overhauling and hub greasing	1 Tyre	Nil	AC bearing complaint, servicing, Gas filling, Filters Change	Head reflectors changing	No other repairs
317	AP16TH8045	TW	Visakapatnam	Oil leakage from volve cover, filter cap, drain plug, chamber leakage and packing replacement charges	Gear box overhauling to replace packing kit	Suspension overhauling to replace of the bush kit and shock absorber	4 wheel brakes overhauling replacement of front brake pads and rear brake liners and also wheel cylinder and calibers kits changed	4 Tyres with Tubes	Nil	Needs complete AC Check, Compressor Check, Pipeline check, Gas filling, Servicing etc.	Front both doors lights and pilot cabin light to be replaced	Front door lock rusted setting, foot board minor patch work, side wall beedings replacement, pilot seats covers, emergency siron not working
318	AP16TH7644	TW	Visakapatnam	Engine Valve cover Gasket leakage, engine oil filter base leakage, engine chamber leakage	Nil	Suspension Overhauling	NILL	4 Tyres with Tubes	Nil	AC Servicing, Gas filling, Pipes, Filters Changing Repairs	Front Both doors lights switches not working	Backside Door Locks handle and Minor Patch work and Emergency Siren
319	AP16TJ1952	F	Visakapatnam	Engine oil filter cap leakage, engine oil breather leak, engine oil drain plug leakage	Nil	Suspension Overhauling	Air brake liners and wheel cylinders	4 Tyres with Tubes	2 Batteries	Gas Leakage, Gas Filling, Pipes Check, Servicing, Filters Changing	Nil	Emergency Siron lights not blinking and other minor patch works
320	AP16TH8552	TW	Visakapatnam	engine oil filter cap leak, volve cover gas kit leak, crank front seal leak, engine oil drain plug leak, engine oil filter base leak	Gear box top leak and gear box front and rear leak	Suspension Overhauling	Nil	4 Tyres with Tubes	2 Batteries	AC Servicing, Gas filling, Pipes, Filters Changing Repairs	Speedometer changing, front and rear parking lights complaint	Front right side locks and working, Emergency siron not working rear door handle locks and minor patch work
321	AP16TH8545	TW	Visakapatnam	Engine breather leak, timing case leak, engine chamber leak, engine oil filter base leak	Gear box top leak, gear box front and rear leakage, 2nd gear hard	Suspension Overhauling	Rear brakes shoes and drums complaint	4 Tyres with Tubes	Nil	AC compressor drive belt, gas filling, servicing, filters	Nil	Tail door glass broken, backside door handles and locks, minor patch work
322	AP16TJ6882	TW	Visakapatnam	Nil	Nil	Suspension Overhauling	Front wheel brakes overhauling	4 Tyres with Tubes	Nil	Gas Leakage, Gas Filling, Pipes Check, Servicing, Filters Changing	Nil	No other repairs
323	AP16TH8044	TW	Visakapatnam	Nil	Complete Gear Box Overhauling	Suspension Overhauling	Nil	Nil	Nil	AC gas filling and pipes checkup, servicing, Filters changing	Complete wiring checkup	Front right side door not working and locks needs replacement and minor patch work



S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
324	AP16TH9831	F	Visakapatnam	Nil	Gear box top leak and 4th gear slipping	Suspension Overhauling	Brakes Overhauling	1 tyre	2 Batteries	Compressor leakchek, Gas Filling, Pipes check, servicing and filters	Speedometer Changing, Bendex changing, head lights reflectors and vipre blades	Front door locks repair, Siron not working, back side door not working and minor tinkering
325	AP16TJ6884	TW	Visakapatnam	Nil	Nil	Suspension Overhauling	Nil	Nil	1 Battery	Gas Leakage, Gas Filling, Pipes Check, Servicing, Filters Changing	Nil	No other repairs
326	AP16TH7794	TW	Visakapatnam	Engine oil leakage from timing cover oil seal, bottom crank case and drain plug packing to be changed	Gear lever bush kit changing and clutch adjustment	Suspension bush kit required and rear leaf springs recampering and bush kit changed	4 wheel brakes overhauling to replace brake liners and wheel cylinder assemblies	4 Tyres with Tubes	1 Battery	Compressor sound problem, Gas filling, servicing, filters, pipes check up	Nil	Front Door L and R Locks, Emergency siren and other minor welding and tinkering works
327	AP16TJ0453	F	Visakapatnam	Valve cover gasket leak, timing case laeakage, crank front seal leakage, engine oil chamber leak, engine oil filter base leakage and Turbo charger leakage	Nil	Suspension Overhauling	Four Wheel Brakes Overhauling and hub greasing	2 Tyres with tubes	Nil	AC gas filling and pipes checkup, servicing, Filters, AC belt Changing	Front and rear parking lamps assemblies changing and horn reparis	Front windshield broken, Pilot seat foam and covers
328	AP16TJ0458	F	Visakapatnam	Nil	Gear box overhauling, clutch overhauling to replace 4th gear wheel and synchronising assembly to be changed	Suspension major overhauling to replace 4th gear wheel and synchronizing assembly to be changed	4 wheel brakes overhauling, replacement of brake liners and wheel cylinders to be changed	1 tyre	Nil	Gas filling/pipes check/servicing/filters	Front both doors lights and front and rear parking lights and head lights to be changed	Seat covers, backside doors lock, Backside door not working other minor patch work
329	AP16TH9832	F	Visakapatnam	Volve Cover Gasket Leakage, engine breatgher leakage, engine mounting required	Nil	Suspension overhauling	Nil	Nil	2 Batteries	Gas filling, servicing, filters change	Speedo meter changing, fuel meter changing and front head light reflector changing	Pilot seat replacement, Emergency siren bulbs and minor tinkering
330	AP16TH8551	TW	Visakapatnam	Engine oil leakage from volve cover and breather pipe gasket to be changed	Gear box overhauling, clutch overhauling to replace of the packing kit	Suspension Overhauling	4 wheel brakes overhauling	Nil	1 Battery	Compressor check, gas filling, servicing, pipes check, filters change and repair charges	Self starter overhauling, replacement of solenoid switch	All door lock settings and seat covers and foam required, Emergency Siron light checking and other Minor Tinkering works
331	AP16TH0466	F	Visakapatnam	Nil	Clutch overhauling, gear box front and rear leakage and UJ cross changing	Suspension overhauling	Brakes Overhauling	2 Tyres with tubes	1 Battery	AC Gas Filling, Servicing, Filters, Pipes checking charges	Speedometer changing, fuel gauge not working and wiper blades changing	Nil
332	AP16TJ0658	F	Visakapatnam	engine oil filter cap leakage, volve cover gasket leakage, timing case leakage, timing case leakages, crank front seal leakage	Clutch overhauling, UJ rubber changing	Suspension Overhauling	NILL	4 Tyres	2 Batteries	Compressor Testing, Gas Leakage, Gas filling, Pipes check, Servicing, Filters Changing	Speedometer changing, front and rear parking lights complaint	Emergency siron, blinkers not working, minor tinkering
333	AP16TH9893	F	Visakapatnam	Nil	Gear shifting levers and cable status leakages, U.J bearing changing	Suspension Overhauling	Complete Brakes overhauling	Nil	2 Batteries	AC Functional Testing and control switch, AC Gasfilling, Servicing Filters	Speedometer cable changing and horns repair	Front door locks not working, backside door locks not working and Rear doors locks and handle repairs.Minor patch work
334	AP16TH8043	TW	Visakapatnam	Nil	Nil	Suspension Overhauling	Nil	Nil	Nil	AC complete OH compressor, Pipelines, Servicing, Gasfilling Filters	Headlight reflectors changing and complete electrical checkup	Front door locks not working, minor patch work and emergency siren

S.no	Vehicle No	Model	District	Engine & Cooling System	Transmission	Suspension	Brakes	Tyres	Battery	Air conditioning system	Electrical system	Any other repairs
		Tata Winger/Force		Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required	Nature of repair required
335	AP16TJ0454	F	Visakapatnam	Nil	Engine leakage, mounting beds replacement, turbo charger repair kit	Suspension major overhauling to replacement of bush kit, rear leaf spring recampering and bush changing	4 wheel brakes overhauling to replace brake liners and wheel cylinders	Nil	2 Batteries	AC gas leakages, Pipes changing, Gas Filling, Servicing, Filters	Pilot cabin light, instrument panel indication lights, head light and danger lights bulbs changing	Seat covers, body bed bolts provided, Front Bannet repairs and other minor tinkering

## Annexure-II - District Wise Consolidated report on the details of repair components

S.No	District	Total No of vehicles		Engine & Cooling System		Transmission		Suspension		Brakes		Tyres		Battery		Air conditioning system		Electrical system		Any other repairs	
		TW	F	TW	F	TW	F	TW	F	TW	F	TW	F	TW	F	TW	F	TW	F	TW	F
1	Anantapur	25	6	19	4	21	3	25	5	11	2	18	3	20	3	24	6	25	6	23	6
2	Chittoor	29	8	28	7	27	6	29	7	20	5	28	5	19	3	25	7	23	6	28	7
3	East Godavari	21	8	15	8	15	6	21	8	17	8	20	7	8	3	17	6	20	8	21	8
4	Guntur	19	7	19	7	11	1	14	5	11	5	17	5	8	3	18	6	18	6	17	6
5	Kadapa	14	6	13	6	13	5	14	6	11	3	14	6	14	6	13	6	14	6	13	6
6	Krishna	20	9	20	8	17	5	20	7	11	6	19	4	10	4	18	4	20	8	21	7
7	Kurnool	22	5	17	2	12	2	18	3	20	4	8	4	3	1	20	4	13	0	15	3
8	Nellore	20	6	12	3	11	1	15	6	14	5	17	3	5	2	17	4	19	6	19	6
9	Prakasam	20	4	20	4	17	3	18	4	20	4	20	4	19	4	17	3	20	4	20	4
10	Srikakulam	12	6	5	6	7	4	11	6	7	6	7	2	5	3	9	6	7	4	12	6
11	Visakapatnam	18	10	10	5	9	6	18	12	9	7	14	7	7	7	18	10	14	9	15	9
12	Vizayanagaram	12	5	9	4	9	3	12	5	9	5	10	1	5	2	11	4	10	5	10	5
13	West Godavari	16	7	6	2	5	1	13	6	5	2	16	7	13	6	16	7	9	6	9	7
<b>Grand Total</b>		<b>248</b>	<b>87</b>	<b>193</b>	<b>66</b>	<b>174</b>	<b>46</b>	<b>228</b>	<b>80</b>	<b>165</b>	<b>62</b>	<b>208</b>	<b>58</b>	<b>136</b>	<b>47</b>	<b>223</b>	<b>73</b>	<b>212</b>	<b>74</b>	<b>223</b>	<b>80</b>

1 Vehicle AP16TJ0457 not audited